




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Sea Horse Ranch West Gravel Pit	MINE/PROSPECTING ID#: M-2001-113	MINERAL: Sand and aggregate	COUNTY: Gunnison
INSPECTION TYPE: Monitoring	WEATHER: Clear	INSP. DATE: April 29, 2025	INSP. TIME: 08:30
OPERATOR: Oldcastle SW Group, Inc. dba United Companies of Mesa County	OPERATOR REPRESENTATIVE: Jesse Farmer	TYPE OF OPERATION: 112c - Construction Regular Operation	
REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: Complete Bond	BOND AMOUNT: \$167,363.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
INSPECTOR(S): Dustin Czapla	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: May 13, 2025	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>Y</u>	(RD) ROADS----- <u>Y</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>NA</u>
(PW) PROCESSING WASTE/TAILING---- <u>NA</u>	(SF) PROCESSING FACILITIES----- <u>Y</u>	(TS) TOPSOIL----- <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>Y</u>	(RV) REVEGETATION---- <u>Y</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>NA</u>	(RS) RECL PLAN/COMP-- <u>Y</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>NA</u>	(SC) EROSION/SEDIMENTATION--- <u>Y</u>	(ST) STIPULATIONS----- <u>NA</u>
(AT) ACID OR TOXIC MATERIALS----- <u>Y</u>	(OD) OFF-SITE DAMAGE----- <u>NA</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted as part of the Division of Reclamation, Mining and Safety's (Division) normal monitoring program. Jesse Farmer, representing the Operator, was present during this inspection. Photographs are included with this report in order to illustrate some of the conditions observed.

The Sea Horse Ranch West Gravel Pit is located approximately 3.5 miles southeast of Gunnison and is accessed from Industrial Park Road. The site is a 112c operation that includes a total of 40 permitted acres. The Division currently holds a financial warranty amount of \$167,363.00 for this site. The Division has reviewed the reclamation costs, in order to ensure the financial warranty reflects the actual current cost of fulfilling the requirements of the Reclamation Plan, and determined that the current financial warranty amount is sufficient.

Adequate mine identification signage was noted at the entrance to the site.

The affected area was marked by fencing that was clearly visible and adequate to delineate the affected area boundary.

The pit was not dewatered during this inspection. Crushing equipment was operating on site, working from existing materials stockpiles located on the northeast side of the pit. The pit currently covers approximately 26 acres. The remainder of the permit area is used for processing and stockpiling. The pit highwalls had been mined to approximately 1.5H:1V. The slopes will require backfilling to 3H:1V during reclamation. Topsoil was stockpiled along the south end of the pit.

No issues related to stormwater or erosion control were noted.

Fuels stored on site were in adequate secondary containment.

No problems regarding disturbance to the hydrologic balance were noted.

Explosives are not used for this operation.

No noxious weed infestations were noted.

No problems or violations were noted during this inspection.

Responses to this inspection report should be directed to Dustin Czapla at the Division of Reclamation, Mining and Safety, Room 215, 1001 E 62nd Avenue, Denver, CO 80216, phone number (970) 433-8393, dustin.czapla@state.co.us.



Pit lake viewed from east end



Pit lake viewed from east end



Pit lake viewed from north side



Pit lake viewed from north side



Crushing/stockpile area north of pit



Crushing/stockpile area north of pit

Inspection Contact Address

Jason Burkey
Oldcastle SW Group, Inc. dba United Companies of Mesa County
2273 River Road
Grand Junction, CO 81505