




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: The Quarry L,L,C,	MINE/PROSPECTING ID#: M-2025-021	MINERAL: Decomposed Granite	COUNTY: Gunnison
INSPECTION TYPE: Preoperation Inspection	WEATHER: Clear	INSP. DATE: April 29, 2025	INSP. TIME: 12:00
OPERATOR: The Quarry LLC	OPERATOR REPRESENTATIVE: John Councilman	TYPE OF OPERATION: 110c - Construction Limited Impact	
REASON FOR INSPECTION: Preoperation Inspection	BOND CALCULATION TYPE: Complete Bond	BOND AMOUNT: \$0.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
INSPECTOR(S): Dustin Czapla	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: May 20, 2025	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>N</u>	(RD) ROADS----- <u>N</u>
(HB) HYDROLOGIC BALANCE----- <u>N</u>	(BG) BACKFILL & GRADING----- <u>N</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>N</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>N</u>
(SM) SIGNS AND MARKERS----- <u>N</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>N</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>N</u>	(ST) STIPULATIONS----- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This was a pre-operation inspection for a pending 110c application. John Councilman, representing the Operator, was present during the inspection. Photographs are included with this report to illustrate some of the conditions observed.

The Quarry, L.L.C. site is located approximately 16.5 road miles east of Gunnison and accessed from CR76. The permit application proposes an affected area of 7.5 acres. This will be a surface mine. Decomposed granite will be excavated with typical gravel mining equipment.

The site has been disturbed by previous mining operations and was permitted under revoked permit M-1995-057 (Rudibaugh Pit). The applicant has recently purchased the property and has done significant cleanup to the site and now wishes to reopen the gravel pit. Most of the junk vehicles and equipment have been removed from the west end of the permit area. The pile of old tires has been removed.

The pit slopes have all been reduced to at least 1H:1V. The slopes on the south side of the pit are flatter, less than 4H:1V.

The affected area will include approximately 7.5 acres of previously mined land. The area has long been stripped and there is little to no topsoil available for salvage. The area will be reclaimed as rangeland.

Notice of the application was posted at the site entrance pursuant to Rule 1.6.2(1)(b).

Overall, the application seems to accurately portray the site conditions.

No problems or violations were noted during this inspection.

Responses to this inspection report should be directed to Dustin Czapla at the Division of Reclamation, Mining and Safety, Room 215, 1001 E 62nd Avenue, Denver, CO 80216, phone number (970) 433-8393, dustin.czapla@state.co.us.





Inspection Contact Address

John Councilman
The Quarry LLC
5400 Cty Rd. 76
Parlin, CO 81239