

May 28, 2025

Mr. Patrick Lennberg
Division of Reclamation, Mining and Safety
1313 Sherman Street, Room 215
Denver, CO 80203

RE: M-2009-082 Additional Information Required

Dear Mr. Lennberg:

Follow-up to your April 18, 2025 letter is below:

1. Please provide a monitoring well location map that shows the locations of all the monitoring wells relative to the permit boundary.

Map is attached.

2. Please provide a line graph that shows the water levels for all monitoring wells since November 2022.

Graphs are attached.

3. Please provide an explanation for the rising water levels in MW-9 and decreasing water levels in MW-12 since November 2022.

MW-9 is on the west edge of Phase 5B. Mining in that phase is completed and the dewatering pump has been shut off so it can fill back to the normal water table and will be used for a silt pond and clean water.

MW-12 is between the west edge of Phase 4C and the east edge of Windsor East M-2022-042 Phase A. Both cells are actively being dewatered and Windsor East is no longer flood irrigated for farming.

4. The groundwater level data was submitted at the same time as the Annual Report, Map, and Fee. A review of the map submitted is incorrectly titled Windsor East. Please update and resubmit the map with the correct title.

Revised annual report map is attached.

Mr. Patrick Lennberg

May 28, 2025

Page 2

If any additional information is needed, please contact me by email at julie.mikulas@martinmarietta.com or cell phone at 970-227-4041.

Sincerely,


A handwritten signature in cursive script that reads "Julie Mikulas".

Julie Mikulas
Regional Land Manager

PARSONS MONITORING WELLS



M-2009-082 Parsons Monitoring Wells



M-2009-082 Parsons Monitoring Wells

