



June 9, 2025

Ms. Hunter Ridley
Environmental Protection Specialist
Colorado Division of Reclamation, Mining & Safety
Department of Natural Resources
1313 Sherman Street, Room 215
Denver, CO 80203

**RE: Colowyo Coal Company L.P.
Permit No. C-1981-019
2025 Annual Rill and Gully Report**


Dear Ms. Ridley,

Tri-State Generation and Transmission Association Inc. (Tri-State), is the parent company to Axial Basin Coal Company, which is the general partner to Colowyo Coal Company L.P. (Colowyo). Therefore, Tri-State is submitting the 2025 Annual Rill and Gully Report on behalf of Colowyo.

Permit requirements in Section 4.14.6 of Colowyo's permit to mine, require Colowyo to submit an Annual Rill and Gully Report no later than June 15 of each year. All the information required in Section 4.14.6 has been included under this cover.

If you should have any additional questions, please feel free to contact Tony Tennyson at (970) 824-1232.

Sincerely,

DocuSigned by:

D250C711D0BF450...

Chris Gilbreath
Senior Manager,
Remediation and Reclamation

CG:TT

Enclosure

cc: Tony Tennyson (via email)
File: Colowyo CF 17.22
G471-11.3(21)h-1

2025 Rill and Gully Report

Colowyo Coal Company L.P.
Permit No. C-1981-019

TABLE OF CONTENTS

SECTION 1 - INTRODUCTION 2

SECTION 2 – IDENTIFIED RILLS AND GULLIES 2

SECTION 3 – RILL AND GULLY LOCATIONS 2

SECTION 4 – TIMELINES FOR REPAIR..... 3

SECTION 1 - INTRODUCTION

Rills and gullies forming in reclamation areas are mitigated if they either (1) disrupt the approved postmining land use or the reestablishment of the vegetative covers or (2) cause or contribute to a violation of water quality standards for receiving streams. These features will be identified during the spring of each year. As part of the spring inspection reclamation areas are visually inspected and rills and gullies identified.

This report provides a summary of any identified rills and gullies, activities undertaken to remediate these areas, and anticipated time frames for repair. As required by Permit No. C-1981-019, Volume 1, Section 4.14.6, this report will be submitted annually and no later than June 15 of each year.

SECTION 2 – IDENTIFIED RILLS AND GULLIES

In 2025, several areas have been identified for the repair of rilling and/or gullies. Due to the small nature of the rills identified they have not been mapped out for reference. Nonetheless, please refer to the Exhibit 2 in the 2024 Annual Reclamation Report Map for the reclamation unit locations listed below which corresponds to the areas the rills and gullies have been identified.

SECTION 3 – RILL AND GULLY LOCATIONS

Rill 1 located in reclamation block WP034 on the east side of the Taylor Ditch. This starts in WP034 and continues through WP035 down to an uncompleted portion of the Taylor Ditch.

Rill 2 located in reclamation block WP035 on the east side of the Taylor Ditch. This rill starts in WP035 and continues through WP037 down to a completed portion of the Taylor Ditch.

Rill 3 located in center section of reclamation block WP035 on the west side of the Taylor Ditch.

Rill 4 located in northern section of reclamation block WP035, west side of the Taylor Ditch near the border with WP031.

Rill 5 located in reclamation block WP035 and WP037 on the west side of the Taylor ditch near where WP035 and WP037 reclamation blocks come together.

Rill 6 located in southern section of reclamation block WP035 on the west side of the Taylor ditch.

SECTION 4 – TIMELINES FOR REPAIR

As noted in Volume 1, Section 4.14.6 in Permit No. C-1981-019, all areas will be repaired within three months of being identified. The areas noted above will be repaired by August 31, 2024.