




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Red Rock Pit	MINE/PROSPECTING ID#: M-1978-315	MINERAL: Sand and gravel	COUNTY: Routt
INSPECTION TYPE: Monitoring	WEATHER: Clear	INSP. DATE: May 14, 2025	INSP. TIME: 09:30
OPERATOR: Peabody Williams Fork Mining, LLC	OPERATOR REPRESENTATIVE: Mike Howard	TYPE OF OPERATION: 112c - Construction Regular Operation	
REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: Complete Bond	BOND AMOUNT: \$37,143.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
INSPECTOR(S): Brock Bowles	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: June 20, 2025	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>N</u>	(RD) ROADS----- <u>N</u>
(HB) HYDROLOGIC BALANCE----- <u>N</u>	(BG) BACKFILL & GRADING----- <u>N</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>Y</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>N</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>N</u>	(ST) STIPULATIONS----- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted by Brock Bowles of the Division of Reclamation, Mining and Safety (Division). Mike Howard of Peabody Williams Fork Mining, LLC (operator) was present for the inspection. The weather during the inspection was clear and warm. The ground was dry.

The Red Rock Pit is a 112c permitted site that includes a total of 41.8 acres. A maximum of 9 acres disturbance is approved. The site is located 8.5 miles southwest of Hayden.

Availability Of Records:

The Division reviewed and updated the reclamation cost estimate. The updated estimate to ensure fulfilling the requirements of the approved reclamation plan is \$37,245. The Division currently holds a bond in the amount of \$37,143. The difference between the cost estimate and the amount held is \$102 or 0.2%, the Division will not issue a surety increase at this time.

Gen. Compliance With Mine Plan:

No mining activity was taking place and no mining equipment was on-site during this inspection.

The mining operation is along the west side of CR 53 and approximately 6 acres are currently disturbed. Overburden material and large rocks are placed on the west side of the mined area, against the hillside. A stockpile is located on the northern end of the mined area and is approximately 20 feet high, 60 feet wide and 80 feet long (photo 1).

The hillside slopes on the west side of the excavated area are sloped between 1h:1v and 2h:1v as approved in the permit application (photo 2). They appear to be stable at this time.

Revegetation:

Several houndstongue and bull thistle plants were seen on and around the stockpile and need to be treated (photo 3).

Signs and Markers:

The mine entrance signs were in place along CR 53. T-post markers delineate the disturbed area.

PHOTOGRAPHS



Photo 1 – Stockpile on north end of pit area. Photo facing north with CR 53 is on right side below the berm



Photo 2 – Mined area looking south. CR 53 on left.



Photo 3- Houndstongue and thistle plants on stockpile.

Inspection Contact Address

Mike Howard
Peabody Williams Fork Mining, LLC
29515 Routt County Road #27
Oak Creek, CO 80467

Enclosure

CC: