

STATE OF
COLORADO

Reilley - DNR, Robin <robin.reilley@state.co.us>

Compliance Reviews WF mine Q1

1 message

Reilley - DNR, Robin <robin.reilley@state.co.us>

Wed, Jun 25, 2025 at 12:53 PM

To: "Kawcak, Miranda" <MKawcak@peabodyenergy.com>, Robin Reilley - DNR <robin.reilley@state.co.us>

Good Afternoon Miranda,

Please find the 2025 quarter 1 compliance report reviews for the Williams Fork Mine. The reviews comprise:

- Sediment Ponds
- DMRs
- Fill and the ARR for 2024

Thank you

Robin Reilley, M.S. GISP
Environmental Protection Specialist II

image.png

P [303.866.3567](tel:303.866.3567) |F [303.832.8106](tel:303.832.8106)

Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203

Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216

robin.reilley@state.co.us | <http://mining.state.co.us>

4 attachments

**Review_DMR_2025_Q1 _WF.pdf**

181K

**Review_Ponds_2025_Q1_WF.pdf**

231K

**WastePile_Review_2025_Q1.pdf**

185K

**ARR_Review_WF_2024.pdf**

184K



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

25 June 2025

Ms. Miranda Kawcak
Moffat County Mining, LLC.
29515 Routt County Road #27
Oak Creek, CO 80467

**RE: Refuse Pile Report Review: 2025 Quarter 1
Williams Fork Mines, Permit No. C1981044**

Dear Ms. Kawcak;

The Colorado Division of Reclamation, Mining and Safety has completed its review of the above referenced report. Please see the Division's findings below regarding the report's compliance with the following Rules.

1. 4.10.2(1)
 - a. The mine waste bank was inspected, on behalf of the person conducting surface coal mining operations, by a qualified registered engineer, or other qualified professional specialist.
 - b. The waste bank was capped in December 2020 and topsoil was placed on the surface of the waste pile.
 - c. The #9 excavation waste disposal area was reclaimed in 2009.
2. 4.10.2(2)
 - a. The submitted inspection report complies with the inspection requirement of rule 4.09.1(11).
 - o This was a quarterly inspection.
 - o The report indicated the stability of the fill was inspected and no appearances of instability, structural weakness or other hazardous conditions were noted. The inspection was conducted on 25 March 2025 and the report received by DRMS on 10 April 2025.
 - b. The stability of the fills was inspected. Tests were not necessary to evaluate any potential hazard to human life and property.
 - o Stability of the waste disposal areas was inspected, and problems were not identified. No maintenance items were noted.
 - c. Copies of the inspection findings shall be maintained at the mine site.
3. 4.10.2(3)

No potential hazards were noted in the above referenced refuse pile inspection report. Vegetation is establishing.

If you have any questions, please contact me, I am available.



Sincerely,

A handwritten signature in blue ink that reads "Robin Reilley". The signature is fluid and cursive, with the first name "Robin" and last name "Reilley" clearly distinguishable.

Robin Reilley M.S. GISP
Environmental Protection Specialist II
Robin.reilley@state.co.us