

July 18, 2025

Robin Reilley
Colorado Division of Reclamation, Mining and Safety
1313 Sherman Street, Room 215
Denver, CO 80203

RE: Seneca Yoast Mine, Permit C-1994-082, Second Quarter 2025 IIR

CDRMS-

In accordance with Rule 4.05.9(17), please find enclosed the Seneca Yoast Mine (SYM) Impoundment Inspection Report (IIR) and Impoundment Inspection Log (IIL). Please contact me with any comments and/or questions.

Best regards,

Miranda Kawcak

Miranda Kawcak
Environmental Manager
Peabody, Colorado Operations

Enclosure: SYM 2Q25 IIR

Mining Area Date Inspected Impoundment NPDES ID No Owner's Rep	Yoast Mine(Seneca Coal Co)	Facility Configuration Date Last Inspected Pond Location Site Location Inspector	Cross-Valley Pond	Quarterly Impoundment Inspection Form
	6/16/2025		3/25/2025	
	Pond #010		NW¼ NE¼, Sec. 8, T5N, R87W	
	CO-0000221 D.P. 010		8.5 mi SE of Hayden, CO	
	Miranda Kawcak		Jason Herden	
Mark or Write in Appropriate Response:				
FEATURE	PROBLEM		COMMENTS	
	YES (Above)	NO (Below)		
GENERAL				
Water Level (ft above or below principal spillway)	X		0.1 FT	
Existing Embankment Freeboard (10.1 ft)	X		10 FT	
Outflow (gpm)	X		1.6 GPM	
EROSION				
Rills & Gullies on Embankment		X		
Wave Erosion		X		
Spillway Erosion		X		
Burrows		X		
Other		X		
STRUCTURAL				
Differential Settling		X		
Cracks or Slides		X		
Seepage		X		
Other		X		
STRUCTURES				
Principal Spillway				
Clogged Orifice		X		
Clogged or Damaged Culvert		X		
Damaged Headgate		NA		
Emergency Spillway				
Erosion		X		
Riprap		X		
Clogged or Damaged Culvert		X		
Other		X		
MAINTENACE				
Maintenance Required		X		
Maintenance Performed		X		
Additional Comments		X		

Mining Area Date Inspected Impoundment NPDES ID No Owner's Rep	Yoast Mine(Seneca Coal Co)	Facility Configuration Date Last Inspected Pond Location Site Location Inspector	Cross-Vally Pond	Quarterly Impoundment Inspection Form
	6/17/2025		3/25/2025	
	Pond #011		NW¼ SW¼, Sec. 16, T5N, R87W	
	CO-0000221 D.P.011		8.5 mi SE of Hayden, CO	
	Miranda Kawcak		Jason Herden	
Mark or Write in Appropriate Response:				
FEATURE		PROBLEM		COMMENTS
		YES (Above)	NO (Below)	
GENERAL				
Water Level (ft above or below principal spillway)			X	1.5 FT
Existing Embankment Freeboard (5.1 ft)		X		6.6 FT
Outflow (gpm)			X	0 GPM
EROSION				
Rills & Gullies on Embankment			X	
Wave Erosion			X	
Spillway Erosion			X	
Burrows			X	
Other			X	
STRUCTURAL				
Differential Settling			X	
Cracks or Slides			X	
Seepage			X	
Other			X	
STRUCTURES				
Principal Spillway				
Clogged Orifice			X	
Clogged or Damaged Culvert			X	
Damaged Headgate			NA	
Emergency Spillway				
Erosion			X	
Riprap			X	
Clogged or Damaged Culvert			X	
Other			X	
MAINTENANCE				
Maintenance Required			X	
Maintenance Performed			X	
Additional Comments			X	

Mining Area Date Inspected Impoundment NPDES ID No Owner's Rep	Yoast Mine(Seneca Coal Co)	Facility Configuration Date Last Inspected Pond Location Site Location Inspector	Cross-Vally Pond	Quarterly Impoundment Inspection Form
	6/19/2025		3/25/2025	
	Pond #011A		SW¼ NW¼, Sec. 16, T5N, R87W	
	N/A		8.5 mi SE of Hayden, CO	
	Miranda Kawcak		Jason Herden	
Mark or Write in Appropriate Response:				
FEATURE	PROBLEM		COMMENTS	
	YES (Above)	NO (Below)		
GENERAL				
Water Level (ft above or below principal spillway)		X	1.7 FT	
Existing Embankment Freeboard (4.6 ft)	X		6.3 FT	
Outflow (gpm)		X	0 GPM	
EROSION				
Rills & Gullies on Embankment		X		
Wave Erosion		X		
Spillway Erosion		X		
Burrows		X		
Other		X		
STRUCTURAL				
Differential Settling		X		
Cracks or Slides		X		
Seepage		X		
Other		X		
STRUCTURES				
Principal Spillway				
Clogged Orifice		X		
Clogged or Damaged Culvert		X		
Damaged Headgate		NA		
Emergency Spillway				
Erosion		X		
Riprap		X		
Clogged or Damaged Culvert		X		
Other		X		
MAINTENACE				
Maintenance Required		X		
Maintenance Performed		X		
Additional Comments		X		

Top of Sediment Storage = 2.1 feet below top of pipe

Mining Area Date Inspected Impoundment NPDES ID No Owner's Rep	Yoast Mine(Seneca Coal Co)	Facility Configuration Date Last Inspected Pond Location Site Location Inspector	Cross-Vally Pond	Quarterly Impoundment Inspection Form
	6/16/2025		3/25/2025	
	Pond #012		NE¼ NW¼, Sec. 19, T5N, R87W	
	CO-0000221 D.P. 012		8.5 mi SE of Hayden, CO	
	Miranda Kawcak		Jason Herden	
Mark or Write in Appropriate Response:				
FEATURE		PROBLEM		COMMENTS
		YES (Above)	NO (Below)	
GENERAL				
Water Level (ft above or below principal spillway)		X		0.1 FT
Existing Embankment Freeboard (9.0 ft)		X		8.9 FT
Outflow (gpm)		X		57.6 GPM
EROSION				
Rills & Gullies on Embankment			X	
Wave Erosion			X	
Spillway Erosion			X	
Burrows			X	
Other			X	
STRUCTURAL				
Differential Settling			X	
Cracks or Slides			X	
Seepage			X	
Other			X	
STRUCTURES				
Principal Spillway				
Clogged Orifice			X	
Clogged or Damaged Culvert			X	
Damaged Headgate			NA	
Emergency Spillway				
Erosion			X	
Riprap			X	
Clogged or Damaged Culvert			X	
Other			X	
MAINTENACE				
Maintenance Required			X	
Maintenance Performed			X	
Additional Comments			X	

Mining Area Date Inspected Impoundment NPDES ID No Owner's Rep	Yoast Mine(Seneca Coal Co)	Facility Configuratio Date Last Inspected Pond Location Site Location Inspector	Cross-Vally Pond	Quarterly Impoundment Inspection Form
	6/18/2025		3/25/2025	
	Pond #012A		NE¼ NW¼, Sec. 19, T5N, R87W	
	N/A		8.5 mi SE of Hayden, CO	
	Miranda Kawcak		Jason Herden	
Mark or Write in Appropriate Response:				
FEATURE		PROBLEM		COMMENTS
		YES (Above)	NO (Below)	
GENERAL				
Water Level (ft above or below principal spillway)			X	1.4 FT
Existing Embankment Freeboard (4.6 ft)		X		6.0 FT
Outflow (gpm)			X	0 GPM
EROSION				
Rills & Gullies on Embankment			X	
Wave Erosion			X	
Spillway Erosion			X	
Burrows			X	
Other			X	
STRUCTURAL				
Differential Settling			X	
Cracks or Slides			X	
Seepage			X	
Other			X	
STRUCTURES				
Principal Spillway				
Clogged Orifice			X	
Clogged or Damaged Culvert			X	
Damaged Headgate			NA	
Emergency Spillway				
Erosion			X	
Riprap			X	
Clogged or Damaged Culvert			X	
Other			X	
MAINTENACE				
Maintenance Required			X	
Maintenance Performed			X	
Additional Comments			X	

Mining Area Date Inspected Impoundment NPDES ID No Owner's Rep	Yoast Mine(Seneca Coal Co)	Facility Configuration Date Last Inspected Pond Location Site Location Inspector	Cross-Vally Pond	Quarterly Impoundment Inspection Form
	6/16/2025		3/25/2025	
	Pond #013		SE¼ NW¼, Sec. 19, T5N, R87W	
	CO-0000221 D.P. 013		8.5 mi SE of Hayden, CO	
	Miranda Kawcak		Jason Herden	
Mark or Write in Appropriate Response:				
FEATURE	PROBLEM		COMMENTS	
	YES (Above)	NO (Below)		
GENERAL				
Water Level (ft above or below principal spillway)		X	1.0 FT	
Existing Embankment Freeboard (4.0 ft)	X		5.0 FT	
Outflow (gpm)		X	0 GPM	
EROSION				
Rills & Gullies on Embankment		X		
Wave Erosion		X		
Spillway Erosion		X		
Burrows		X		
Other		X		
STRUCTURAL				
Differential Settling		X		
Cracks or Slides		X		
Seepage		X		
Other		X		
STRUCTURES				
Principal Spillway				
Clogged Orifice		X		
Clogged or Damaged Culvert		X		
Damaged Headgate		NA		
Emergency Spillway				
Erosion		X		
Riprap		X		
Clogged or Damaged Culvert		X		
Other		X		
MAINTENACE				
Maintenance Required		X		
Maintenance Performed		X		
Additional Comments		X		

Mining Area Date Inspected Impoundment NPDES ID No Owner's Rep	Yoast Mine(Seneca Coal Co)	Facility Configuration	Cross-Vally Pond	Quarterly Impoundment Inspection Form
	6/16/2025	Date Last Inspected	3/25/2025	
	Pond #014	Pond Location	NE¼ SW¼, Sec. 19, T5N, R87W	
	CO-0000221 D.P. 014	Site Location	8.5 mi SE of Hayden, CO	
	Miranda Kawcak	Inspector	Jason Herden	
Mark or Write in Appropriate Response:				
FEATURE	PROBLEM		COMMENTS	
	YES (Above)	NO (Below)		
GENERAL				
Water Level (ft above or below principal spillway)		X	1.5 FT	
Existing Embankment Freeboard (6.8 ft)	X		8.3 FT	
Outflow (gpm)		X	0 GPM	
EROSION				
Rills & Gullies on Embankment		X		
Wave Erosion		X		
Spillway Erosion		X		
Burrows		X		
Other		X		
STRUCTURAL				
Differential Settling		X		
Cracks or Slides		X		
Seepage		X		
Other		X		
STRUCTURES				
Principal Spillway				
Clogged Orifice		X		
Clogged or Damaged Culvert		X		
Damaged Headgate		NA		
Emergency Spillway				
Erosion		X		
Riprap		X		
Clogged or Damaged Culvert		X		
Other		X		
MAINTENACE				
Maintenance Required		X		
Maintenance Performed		X		
Additional Comments		X		


IMPOUNDMENT INSPECTION LOG

JOB DATA

JOB NAME: PEC Hydrologic Services	CLIENT: Peabody	JOB(s): 2023-086 (PSCM), 2023-087 (SCC)
-----------------------------------	-----------------	---

FLOW DATA

SITE ID	COMPANY	MINE	DATE	WATER LEVEL (FT)	OUTFLOW (GPM)	OBSERVATIONS	MAINTENANCE (Y/N)
002	Sage Creek	Sage Creek	6-16-25	0.3	67.8		N
003	Sage Creek	Sage Creek	6-16-25	0.1	1.9	some animal burrows	N
Lower Sump	Sage Creek	Sage Creek	6-17-25	0.1	22.1		N
Pecoco	Sage Creek	Sage Creek	6-17-25	0.1	87.6		N
Portal Sump 1	Sage Creek	Sage Creek	6-17-25	—	—	no flow	N
Portal Sump 2	Sage Creek	Sage Creek	6-17-25	0.1	—	not pumping	N
Spill Control 2	Sage Creek	Sage Creek	6-17-25	—	—	no flow	N
Truck Wash	Sage Creek	Sage Creek	6-17-25	—	—	Dry	N
Upper Sump	Sage Creek	Sage Creek	6-17-25	0.1	22.7		N
006	Seneca	Seneca II West	6-16-25	0.1	61.3	Sluff on S. side, no issues	N
015	Seneca	Seneca II West	6-16-25	0.1	1.8		N
016	Seneca	Seneca II West	6-14-25	0.1	69.9		N
017	Seneca	Seneca II West	6-16-25	0.1	4.7		N
T-2	Seneca	Seneca II West	6-19-25	~	—	Dry	N
T-3	Seneca	Seneca II West	6-19-25	-3.4	—	no flow	N
010	Seneca	Yoast	6-16-25	0.1	1.6		N
011	Seneca	Yoast	6-17-25	-1.5	—	no flow	N
011A	Seneca	Yoast	6-19-25	-1.7	—	no flow	N
012	Seneca	Yoast	6-16-25	0.1	57.6		N
012A	Seneca	Yoast	6-18-25	-1.4	—	no flow	N
013	Seneca	Yoast	6-16-25	-1.0	—	no flow	N
014	Seneca	Yoast	6-16-25	-1.5	—	no flow	N

FIELD PERSONNEL: JH	FIELD PERSONNEL SIGNATURE: 
---------------------	---

NOTES

--