



August 28, 2024

Ms. Hunter Ridley
Environmental Protection Specialist
Colorado Division of Reclamation Mining and Safety
Department of Natural Resources
1313 Sherman Street, Room 215
Denver, CO 80203

**RE: Colowyo Coal Mine L.P.
Permit No. C-1981-019
Quarterly Impoundment Inspections
3rd Quarter 2025**

Dear Ms. Ridley,

Tri-State Generation and Transmission Association Inc. (Tri-State), is the parent company to Axial Basin Coal Company, which is the general partner to Colowyo Coal Company L.P. Therefore, Tri-State on behalf of Colowyo, and in accordance with Rule 4.05.9(17), is submitting the enclosed quarterly impoundment inspection report.

If you should have any additional questions or concerns, please feel free to contact Tony Tennyson at (970) 824-1232 or tony.tennyson@tristategt.org.

Sincerely,

DocuSigned by:
A handwritten signature in black ink that reads "Chris Gilbreath".
D250C711D0BF450...

Chris Gilbreath
Senior Manager
Remediation and Reclamation

CG:TT

Enclosure

cc: Tony Tennyson (via email)
Tom Fry (via email)
CF 21.1.2.2025
G471-11.3(21)h-4

Colowyo Coal Company L.P.
Permit No. C-1981-019

Quarterly Impoundment Inspections
3rd Quarter 2025

	Streeter Pond	Gossard Pond	Stoker Siding Pond	Rail Loop Pond	Prospect Pond	Section 28 Pond	Section 16 Pond	West Pit Pond	East Taylor Pond	West Taylor Pond	Work Area Pond		
Inspection Date:	8/13/2025	7/1/2025	8/13/2025	7/1/2025	8/13/2025	8/13/2025	8/14/2025	7/10/2025	7/10/2025	7/10/2025	8/18/2025		
Inspector:	TF	TF	TF	TF	TF	TF	TF	TF	TF	TF	TF		
Rule 4.05.9 (17) Does the pond exhibit any structural weakness or other hazardous conditions	No	No	No	No	No	No	No	No	No	No	No		
Flume in place and functioning.	Parshall Flume In Place and Functioning	Not Applicable	Parshall Flume In Place and Functioning	Not Applicable	Parshall Flume In Place and Functioning	Parshall Flume In Place and Functioning	Parshall Flume In Place and Functioning	Parshall Flume In Place and Functioning	Parshall Flume In Place and Functioning	Parshall Flume In Place and Functioning	Not Applicable		
Any Erosional Issues Present on the Embankment	No	No	No	No	No	No	No	No	No	No	No		
Spillway and Discharge Pipes Functioning and Clear of Debris	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes		
Any Additional Issues Affecting the Pond Stability and Function	No	No	No	No	No	No	No	No	No	No	No		
	Temporary Facilities Pond	Wilson Storage Pond	Section 36 Pond	Middle Pond	Section 25 Pond	Coal Stockpile	Sidehill Pond	Section 26 Pond	Evaporation Pond #1	Evaporation Pond #2	Aeration Pond	Section 3	
Inspection Date:	8/18/2025	8/18/2025	8/5/2025	8/5/2025	7/1/2025	8/18/2025	8/5/2025	7/1/2025	7/1/2025	8/14/2025	8/14/2025	8/14/2025	
Inspector:	TF	TF	TF	TF	TF	TF	TF	TF	TF	TF	TF	TF	
Rule 4.05.9 (17) Does the pond exhibit any structural weakness or other hazardous conditions	No	No	No	No	No	No	No	No	No	No	No	No	
Flume in place and functioning.	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Parshall Flume In Place and Functioning	Not Applicable	Not Applicable	Parshall Flume In Place and Functioning	Not Applicable	Not Applicable	Not Applicable	Not Applicable	
Any Erosional Issues Present on the Embankment	No	No	No	No	No	No	No	No	No	No	No	No	
Spillway and Discharge Pipes Functioning and Clear of Debris	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	
Any Additional Issues Affecting the Pond Stability and Function	No	No	No	No	No	No	No	East Side Slump: Continued Monitoring	No	No	No	No	
	PD1	PD2	NTEP1	EP1	EP2	EP3	Section 15 Pond	TD1	TD2	ETD1	Washbay Pond	Taylor Pump Holding	Warehouse Pond
Inspection Date:	8/14/2025	8/14/2025	8/5/2025	8/5/2025	8/5/2025	8/5/2025	8/5/2025	8/18/2025	8/18/2025	8/18/2025	8/14/2025	7/10/2025	8/14/2025
Inspector:	TF	TF	TF	TF	TF	TF	TF	TF	TF	TF	TF	TF	TF
Rule 4.05.9 (17) Does the pond exhibit any structural weakness or other hazardous conditions.	No	No	No	No	No	No	No	No	No	No	No	No	No
Flume in place and functioning.	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable
Any Erosional Issues Present on the Embankment	No	No	No	No	No	No	No	No	No	No	No	No	No
Spillway Clear of Debris and Functioning	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes
Does the Pond Require Pumping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes
Any Additional Issues Affecting the Pond Stability and Function	Pond is nearly full of sediment	No	No	No	No	No	No	No	Pond is full of sediment, no capacity	No	No	No	No