



MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Greer Pit	MINE/PROSPECTING ID#: M-1985-115	MINERAL: Sand and gravel	COUNTY: La Plata
INSPECTION TYPE: Monitoring	WEATHER: Clear	INSP. DATE: September 3, 2025	INSP. TIME: 11:00
OPERATOR: J Pat and Lila N Greer	OPERATOR REPRESENTATIVE: Jim Greer	TYPE OF OPERATION: 110c - Construction Limited Impact	
REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: None	BOND AMOUNT: \$12,721.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
INSPECTOR(S): Dustin Czapla	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: September 17, 2025	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>Y</u>	(RD) ROADS----- <u>Y</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>NA</u>
(PW) PROCESSING WASTE/TAILING---- <u>NA</u>	(SF) PROCESSING FACILITIES----- <u>NA</u>	(TS) TOPSOIL----- <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>Y</u>	(RV) REVEGETATION---- <u>Y</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>NA</u>	(RS) RECL PLAN/COMP-- <u>Y</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>NA</u>	(SC) EROSION/SEDIMENTATION-- <u>Y</u>	(ST) STIPULATIONS----- <u>NA</u>
(AT) ACID OR TOXIC MATERIALS----- <u>NA</u>	(OD) OFF-SITE DAMAGE----- <u>NA</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted as part of the Division of Reclamation, Mining and Safety's (Division) normal monitoring program. Jim Greer, representing the Operator, was present during this inspection. Photographs are included with this report to illustrate some of the conditions observed.

The Greer Pit is located approximately 2.7 miles west of Marvel and accessed from CR 100. The site is a 110c operation that includes a total of 8.3 permitted acres. The Division currently holds a financial warranty amount of \$12,721.00 for this site. The Division will review the reclamation costs to ensure the financial warranty reflects the actual current cost of fulfilling the requirements of the Reclamation Plan. The Operator will be notified under separate cover if the Division determines that the current financial warranty amount is insufficient.

Adequate mine identification signage was noted at the entrance to the site.

The affected area was marked by fencing and berms that were clearly visible and adequate to delineate the affected area boundary.

Nearly the entire permit area has been disturbed by the mining operation. Mining will now continue downward to extract the remaining gravel. The highwall on the east side has been backfilled and graded to 3H:1V. Vegetation is well established on this slope. Backfilling of the south highwall is underway. The slope was at an approximate 1H:1V grade at the time of this inspection. The highwall on the west end of the pit has been reduced to 3H:1V. The west end of the pit will eventually daylight to the west. There is no highwall on the north side of the pit. Overburden and topsoil are stockpiled in berms above the highwalls. Crushed gravel stockpiles are located on the pit floor.

No stability or erosional concerns were noted.

Mining at the site has not exposed groundwater. No problems related to stormwater or erosion control were noted.

Overall, the operation appears to be in general compliance with the approved Mine Plan.

There was no processing waste observed on site.

The operation has not exposed acid or toxic forming materials. Fuels were not stored on site.

Explosives are not used for the operation.

Noxious weed infestations were not observed.

No problems or violations were noted during this inspection.

Responses to this inspection report should be directed to Dustin Czapla at the Division of Reclamation, Mining and Safety, Room 215, 1001 E 62nd Avenue, Denver, CO 80216, phone number (970) 433-8393, dustin.czapla@state.co.us.



Sign at entrance



East highwall



East highwall



South highwall



West highwall



West highwall



West highwall



West highwall

Inspection Contact Address

Jim Greer
J Pat and Lila N Greer
8097 CR 100
Hesperus, CO 81326