



TRAPPER MINING INC.

September 22, 2025

Ms. Nikie Gagnon
Environmental Protection Specialist
Colorado Division of Reclamation, Mining, and Safety
1313 Sherman Street, Room 215
Denver, CO 80203

Dear Ms. Nikie Gagnon:

**RE: Trapper Mining Inc., Permit C-81-010
Third Quarter 2025 Sediment Pond Inspections**


All impoundment inspections were conducted by a qualified inspector. The inspections took place on September 15th, 16th, 17th and 18th.

There were no maintenance items.

Data related to pond capacity is attached. The last column on the table provides an estimate of the remaining capacity in each pond where remaining capacity is defined as the volume remaining after considering the estimated amount of sediment noted during the inspections.

Please contact me if you have any questions.

Sincerely,


Tonia Marie Perkins
CO PE 43864

C: EQ file 118.7



Trapper Mining Inc.
Third Quarter 2025
Impoundment Inspection - Pond Capacity Data

Pond ID	Princ. Spillway Stage (ft)	Total Capacity to PS stage (acre-feet)	60% Sediment Capacity (acre-feet)	60% Sediment Capacity Stage (ft)	Remaining Design Capacity (acre-feet)	Inspection Observation (% sediment)	Qtr. 3 Estimated Sediment (acre-feet)	Qtr. 3 Approximate Rem. Capacity (acre-feet)
Far East Buzzard	2.0	0.03	0.02	1.4	0.01	10.00	0.00	0.03
Coyote	30.5	75.1	45.06	26.7	30.04	0.00	0.00	75.10
No Name #2	8.5	8.47	5.08	6.0	3.39	35.00	2.96	5.51
No Name #4	14.5	8.23	4.94	11.7	3.29	15.00	1.23	7.00
No Name #5	6.0	1.03	0.62	4.7	0.41	25.00	0.26	0.77
Johnson #6	9.0	1.80	1.08	7.1	0.72	25.00	0.45	1.35
Johnson #7R	7.0	2.99	1.79	5.2	1.20	35.00	1.05	1.94
Johnson #8	7.0	3.58	2.15	4.6	1.43	35.00	1.25	2.33
Johnson #9	8.5	2.74	1.64	6.6	1.10	20.00	0.55	2.19
Johnson #10	9.0	6.09	3.65	7.0	2.44	10.00	0.61	5.48
West Pyeatt #1	9.0	2.76	1.66	7.0	1.10	50.00	1.38	1.38
West Pyeatt #2	10.0	1.89	1.13	7.3	0.76	45.00	0.85	1.04
Middle Pyeatt #1	10.0	1.40	0.84	8.1	0.56	35.00	0.49	0.91
Middle Pyeatt #2	10.0	1.26	0.76	8.4	0.50	25.00	0.32	0.95
Middle Pyeatt #3	10.0	5.70	3.42	7.9	2.28	40.00	2.28	3.42
East Pyeatt #1	8.0	0.99	0.59	6.5	0.40	20.00	0.20	0.79
East Pyeatt #2	8.0	4.15	2.49	6.1	1.66	40.00	1.66	2.49
East Pyeatt #3	8.0	1.51	0.91	6.8	0.60	35.00	0.53	0.98
Grouse #1	7.5	3.35	2.01	5.7	1.34	55.00	1.84	1.51
Grouse #2	4.5	0.79	0.47	3.6	0.32	15.00	0.12	0.67
Sage #1	8.0	2.67	1.60	6.4	1.07	10.00	0.27	2.40
Sage #2	7.0	2.07	1.24	5.8	0.83	10.00	0.21	1.86
Oak #1	13.0	1.43	0.86	10.6	0.57	45.00	0.64	0.79
Oak #2	9.5	0.93	0.56	7.7	0.37	10.00	0.09	0.84

Trapper Mining Inc.
Third Quarter 2025
Impoundment Inspection - Pond Capacity Data

Pond ID	Princ. Spillway Stage (ft)	Total Capacity to PS stage (acre-feet)	60% Sediment Capacity (acre-feet)	60% Sediment Capacity Stage (ft)	Remaining Design Capacity (acre-feet)	Inspection Observation (% sediment)	Qtr. 3 Estimated Sediment (acre-feet)	Qtr. 3 Approximate Rem. Capacity (acre-feet)
West Flume	10.0	2.35	1.41	7.8	0.94	10.00	0.24	2.12
Middle Flume #1	11.7	0.80	0.48	9.0	0.32	40.00	0.32	0.48
Middle Flume #3	14.0	3.36	2.02	10.5	1.34	0.00	0.00	3.36
East Middle Flume	13.0	2.56	1.54	9.2	1.02	5.00	0.13	2.43
East Flume	11.3	1.18	0.71	8.5	0.47	15.00	0.18	1.00
Ute	7.0	1.72	1.03	5.2	0.69	45.00	0.77	0.95
Horse	13.3	6.20	3.72	10.3	2.48	55.00	3.41	2.79
West Horse	13.0	2.00	1.20	9.7	0.80	20.00	0.40	1.60
Deal #1	16.8	2.00	1.20	15.1	0.80	5.00	0.10	1.90
Deal #2	6.0	1.66	0.60	3.1	1.06	0.00	0.00	1.66
Deacon #1	14.5	9.00	3.48	7.5	5.52	0.00	0.00	9.00
Deacon #2	12.0	7.03	3.60	7.7	3.43	0.00	0.00	7.03
Leftway #1	9.0	2.86	1.20	5.3	1.66	5.00	0.14	2.72
East Buzzard #3	7.0	2.21	0.80	3.3	1.41	5.00	0.11	2.10
West Buzzard #3	8.0	0.93	0.33	5.0	0.60	5.00	0.05	0.88
West Buzzard #4	9.0	1.53	0.55	5.0	0.98	5.00	0.08	1.45
Impoundment H	9.5	4.82	2.89	4.9	1.93	5.00	0.24	4.58

TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia PerkinsSIGNATURE: *Tonia Perkins*DRAINAGE: **FAR EAST BUZZARD**DATE OF INSPECTION: 9/18/2025

POND IDENTIFICATION	Far East Buzzard #1				
Approximate water level:	<u>DRY</u>				
Sediment level (% total storage):	<u>10%</u>				
Outflow (cfs):	<u>0</u>				
Sediment marker (install or replace)	<u>In place</u>				
Identification sign (install or replace)	<u>In place</u>				
EROSIONAL:					
Rills and/or gullies on downstream face.	<u>no</u>				
Rills and/or gullies on upstream face.	<u>no</u>				
Inadequate vegetation.	<u>no</u>				
Outlet channel erosion.	<u>no</u>				
Burrows.	<u>minimal</u>				
Erosion of toe.	<u>no</u>				
Water impounded against downstream toe.					
Other.					
STRUCTURAL:					
Differential settling.	<u>no</u>				
Cracks, slides, or scaps.	<u>no</u>				
Seepage (specify location, color, value).	<u>no</u>				
Defective spillways.	<u>no</u>				
Other.					
APPURTENANT STRUCTURES:					
Defective spillways.	<u>no</u>				
Dewatering device clogged.	<u>no</u>				
Cracking or crushing of pipes.	<u>no</u>				
Other.	<u>-</u>				
COMMENTS:					



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tim CumminsDRAINAGE: **COYOTE**SIGNATURE: *Tim Cummins*DATE OF INSPECTION: 9/16/2025

POND IDENTIFICATION	Coyote #1				
Approximate water level:	9%				
Sediment level (% total storage):	Minimal				
Outflow (cfs):	0				
Sediment marker (install or replace)	N/A				
Identification sign (install or replace)	IN PLACE				
EROSIONAL:					
Rills and/or gullies on downstream face:	NO				
Rills and/or gullies on upstream face:	NO				
Inadequate vegetation:	NO				
Outlet channel erosion:	NO				
Burrows:	NO				
Erosion of toe:	NO				
Water impounded against downstream toe:	NO				
Other:	—				
STRUCTURAL:					
Differential settling:	NO				
Cracks, slides, or scarps:	NO				
Seepage (specify location, color, value):	NO				
Defective spillways:	NO				
Other:	—				
APPURTENANT STRUCTURES:					
Defective spillways:	NO				
Dewatering device clogged:	NO				
Cracking or crushing of pipes:	NO				
Other:	—				
COMMENTS:					
Sediment level is measured by a fixed surveyed elevation of 6298.11 ft. (9/29/10).					




TRAPPER MINING INC.**QUARTERLY SEDIMENT POND INSPECTION REPORT**INSPECTOR: Tonia PerkinsDRAINAGE: **NO NAME**SIGNATURE: *Tonia Perkins*DATE OF INSPECTION: 9/10/2025

POND IDENTIFICATION	No Name #2	No Name #4	No Name #5		
Approximate water level:	100%.	90%.	100%.		
Sediment level (% total storage):	35%.	15%.	25%.		
Outflow (cfs):	41 cfs	0	41 cfs		
Sediment marker (install or replace)	Underwater	In Place	Underwater		
Identification sign (install or replace)	In Place	In Place	In Place		
EROSIONAL:					
Rills and/or gullies on downstream face.	no	no	no		
Rills and/or gullies on upstream face.	no	no	no		
Inadequate vegetation.	no	no	no		
Outlet channel erosion.	no	no	no		
Burrows.	no	no	no		
Erosion of toe.	no	no	no		
Water impounded against downstream toe.	no	no	no		
Other.	—	—	—		
STRUCTURAL:					
Differential settling.	no	no	no		
Cracks, slides, or scarps.	no	no	no		
Seepage (specify location, color, value).	no	no	no		
Defective spillways.	no	no	no		
Other.	—	—	—		
APPURTENANT STRUCTURES:					
Defective spillways.	no	no	no		
Dewatering device clogged.	no	no	no		
Cracking or crushing of pipes.	no	no	no		
Other.	—	—	—		
COMMENTS:					

#4: use riser/siphon tube as sediment marker; siphon top = 75%, bottom = 60%.
 #5: 60% level = top of post - 4.5'.



TRAPPER MINING INC.**QUARTERLY SEDIMENT POND INSPECTION REPORT**INSPECTOR: Tonia PerkinsDRAINAGE: **JOHNSON GULCH**SIGNATURE: DATE OF INSPECTION: 9/16/2025

POND IDENTIFICATION	Johnson #6	Johnson #7R	Johnson #8R	Johnson #9R	Johnson #10R
Approximate water level:	90%.	95%.	100%.	100%.	100%.
Sediment level (% total storage):	25%.	35%.	35%.	20%.	10%.
Outflow (cfs):	0	0	41 cfs	41 cfs	41 cfs
Sediment marker (install or replace)	In Place	Underwater	Underwater	In Place*	Underwater
Identification sign (install or replace)	In Place	In Place	In Place	In Place	In Place
EROSIONAL:					
Rills and/or gullies on downstream face:	NO	NO	NO	NO	NO
Rills and/or gullies on upstream face:	NO	NO	NO	NO	NO
Inadequate vegetation:	NO	NO	NO	NO	NO
Outlet channel erosion:	NO	NO	NO	NO	NO
Burrows:	NO	NO	NO	NO	NO
Erosion of toe:	NO	NO	NO	NO	NO
Water impounded against downstream toe:	NO	NO	NO	NO	NO
Other:	—	—	—	—	—
STRUCTURAL:					
Differential settling:	NO	NO	NO	NO	NO
Cracks, slides, or scarps:	NO	NO	NO	NO	NO
Seepage (specify location, color, value):	NO	NO	NO	NO	NO
Defective spillways:	NO	NO	NO	NO	NO
Other:	—	—	—	—	—
APPURTENANT STRUCTURES:					
Defective spillways:	NO	NO	NO	NO	NO
Dewatering device clogged:	NO	NO	NO	NO	NO
Cracking or crushing of pipes:	NO	NO	NO	NO	NO
Other:	—	—	—	—	—
COMMENTS:					

#6: use riser/siphon tube as sediment marker; siphon top = 90%, top - 1.5' = 60%.

* #9 - See sediment marker stake, actual marker under water.



TRAPPER MINING INC.

INSPECTOR: Tonia PerkinsDRAINAGE: **WEST PYEATT**

TRAPPER MINING INC. QUARTERLY SEDIMENT POND INSPECTION REPORT

SIGNATURE: *Tonia Perkins*DATE OF INSPECTION: 9/16/2025

POND IDENTIFICATION	West Pyeatt #1	West Pyeatt #2		
Approximate water level:	76%	DEY		
Sediment level (% total storage):	50%	45%		
Outflow (cfs):	0	0		
Sediment marker (install or replace)	Underwater	In place		
Identification sign (install or replace)	In place	In place		
EROSIONAL:				
Rills and/or gullies on downstream face:	no	no		
Rills and/or gullies on upstream face:	no	no		
Inadequate vegetation:	no	no		
Outlet channel erosion:	no	no		
Burrows:	no	no		
Erosion of toe:	no	no		
Water impounded against downstream toe:	no	no		
Other:	-	-		
STRUCTURAL:				
Differential settling:	no	no		
Cracks, slides, or scarps:	no	no		
Seepage (specify location, color, value):	no	no		
Defective spillways:	no	no		
Other:	-	-		
APPURTENANT STRUCTURES:				
Defective spillways:	no	no		
Dewatering device clogged:	no	no		
Cracking or crushing of pipes:	no	no		
Other:	-	-		
COMMENTS:				



TRAPPER MINING INC.

TRAPPER MINING INC.**QUARTERLY SEDIMENT POND INSPECTION REPORT**INSPECTOR: Tonia PerkinsDRAINAGE: **MIDDLE PYEATT**SIGNATURE: *Tonia Perkins*DATE OF INSPECTION: 9/18/2025

POND IDENTIFICATION	Middle Pyeatt #1	Middle Pyeatt #2	Middle Pyeatt #3		
Approximate water level:	50% 35%	DRY 25%	DRY 40%		
Sediment level (% total storage):					
Outflow (cfs):	0 Place In Place	0 Place In Place	0 Place In Place		
Sediment marker (install or replace)					
Identification sign (install or replace)					
EROSIONAL:					
Rills and/or gullies on downstream face:	no	no	no		
Rills and/or gullies on upstream face:	no	no	no		
Inadequate vegetation:	no	no	no		
Outlet channel erosion:	no	no	no		
Burrows:	no	no	no		
Erosion of toe:	no	no	no		
Water impounded against downstream toe:	no	no	no		
Other:					
STRUCTURAL:					
Differential settling:	no	no	no		
Cracks, slides, or scarps:	no	no	no		
Seepage (specify location, color, value):	no	no	no		
Defective spillways:	no	no	no		
Other:					
APPURTENANT STRUCTURES:					
Defective spillways:	no	no	no		
Dewatering device clogged:	no	no	no		
Cracking or crushing of pipes:	no	no	no		
Other:					
COMMENTS:					



TRAPPER MINING INC.

TRAPPER MINING INC.**QUARTERLY SEDIMENT POND INSPECTION REPORT**INSPECTOR: Tonia PerkinsDRAINAGE: **EAST PYEATT**SIGNATURE: *Tonia Perkins*DATE OF INSPECTION: 9/18/2025

POND IDENTIFICATION	East Pyeatt #1	East Pyeatt #2	East Pyeatt #3
Approximate water level:	75%	65%	65%
Sediment level (% total storage):	20%	40%	35%
Outflow (cfs):	0	0	0
Sediment marker (install or replace)	Underwater	Underwater	Underwater
Identification sign (install or replace)	In Place	In Place	In Place
EROSIONAL:			
Rills and/or gullies on downstream face.	no	no	no
Rills and/or gullies on upstream face.	no	no	no
Inadequate vegetation.	no	no	no
Outlet channel erosion.	no	no	no
Burrows.	no	no	no
Erosion of toe.	no	no	no
Water impounded against downstream toe.	no	no	no
Other.	-	-	-
STRUCTURAL:			
Differential settling.	no	no	no
Cracks, slides, or scarps.	no	no	no
Seepage (specify location, color, value).	no	no	no
Defective spillways.	no	no	no
Other.	-	-	-
APPURTENANT STRUCTURES:			
Defective spillways.	no	no	no
Dewatering device clogged.	no	no	no
Cracking or crushing of pipes.	no	no	no
Other.	-	-	-
COMMENTS:			



INSPECTOR: Tim CumminsDRAINAGE: **GROUSE GULCH**

TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

SIGNATURE: Tim CumminsDATE OF INSPECTION: 9-18-25

POND IDENTIFICATION	Grouse #1	Grouse #2		
Approximate water level:	65% 55% 0	Dry 15% 0		
Sediment level (% total storage):				
Outflow (cfs):				
Sediment marker (install or replace)	IN PLACE	IN PLACE		
Identification sign (install or replace)	IN PLACE	IN PLACE		
EROSIONAL:				
Rills and/or gullies on downstream face:	NO	NO		
Rills and/or gullies on upstream face:	NO	NO		
Inadequate vegetation:	NO	NO		
Outlet channel erosion:	NO	NO		
Burrows:	NO	*		
Erosion of toe:	NO	NO		
Water impounded against downstream toe:	NO	NO		
Other:				
STRUCTURAL:				
Differential settling:	NO	NO		
Cracks, slides, or scarps:	NO	NO		
Seepage (specify location, color, value):	NO	NO		
Defective spillways:	NO	NO		
Other:				
APPURTENANT STRUCTURES:				
Defective spillways:	NO	NO		
Dewatering device clogged:	NO	NO		
Cracking or crushing of pipes:	NO	NO		
Other:				
COMMENTS:				

* Filled in one badger hole on grouse #2 dam



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tim CumminsDRAINAGE: **SAGE GULCH**SIGNATURE: Tim CumminsDATE OF INSPECTION: 9-18-25

POND IDENTIFICATION	Sage #1	Sage #2		
Approximate water level:	Dry	Dry		
Sediment level (% total storage):	10%	10%		
Outflow (cfs):	0	0		
Sediment marker (install or replace)	IN PLACE	IN PLACE		
Identification sign (install or replace)	IN PLACE	IN PLACE		
EROSIONAL:				
Rills and/or gullies on downstream face.	No	No		
Rills and/or gullies on upstream face.	No	No		
Inadequate vegetation.	No	No		
Outlet channel erosion.	No	No		
Burrows.	*	*		
Erosion of toe.	No	No		
Water impounded against downstream toe.	No	No		
Other.	—	—		
STRUCTURAL:				
Differential settling.	No	No		
Cracks, slides, or scarps.	No	No		
Seepage (specify location, color, value).	No	No		
Defective spillways.	No	No		
Other.	—	—		
APPURTENANT STRUCTURES:				
Defective spillways.	No	No		
Dewatering device clogged.	No	No		
Cracking or crushing of pipes.	No	No		
Other.	—	—		

COMMENTS:

* Filled in one badger hole at toe of upstream side of dam.
 * Filled in one badger hole on upstream side of Principal spillway



TRAPPER MINING INC.**QUARTERLY SEDIMENT POND INSPECTION REPORT**INSPECTOR: Tonia PerkinsDRAINAGE: **OAK GULCH**SIGNATURE: *Tonia Perkins*DATE OF INSPECTION: 9/18/2025

POND IDENTIFICATION	Oak #1	Oak #2		
Approximate water level:	40%	084		
Sediment level (% total storage):	45%	10%		
Outflow (cfs):	0	0		
Sediment marker (install or replace)	In Place	In Place		
Identification sign (install or replace)	In Place	In Place		
EROSIONAL:				
Rills and/or gullies on downstream face.	no	no		
Rills and/or gullies on upstream face.	no	no		
Inadequate vegetation.	no	no		
Outlet channel erosion.	no	no		
Burrows.	no	no		
Erosion of toe.	no	no		
Water impounded against downstream toe.	no	no		
Other.	-	-		
STRUCTURAL:				
Differential settling.	no	no		
Cracks, slides, or scarps.	no	no		
Seepage (specify location, color, value).	no	no		
Defective spillways.	no	no		
Other.	-	-		
APPURTENANT STRUCTURES:				
Defective spillways.	no	no		
Dewatering device clogged.	no	no		
Cracking or crushing of pipes.	no	no		
Other.	-	-		
COMMENTS:				




TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia Perkins

DRAINAGE: WEST FLUME

SIGNATURE



DATE OF INSPECTION:

9/18/2025

POND IDENTIFICATION	West Flume #1				
Approximate water level:	DKY				
Sediment level (% total storage):	101.				
Outflow (cfs):	0				
Sediment marker (install or replace)	In Place				
Identification sign (install or replace)	In Place				
EROSIONAL:					
Rills and/or gullies on downstream face.	NO				
Rills and/or gullies on upstream face.	NO				
Inadequate vegetation.	NO				
Outlet channel erosion.	NO				
Burrows.	NO				
Erosion of toe.	NO				
Water impounded against downstream toe.	NO				
Other.	-				
STRUCTURAL:					
Differential settling.	NO				
Cracks, slides, or scarps.	NO				
Seepage (specify location, color, value).	NO				
Defective spillways.	NO				
Other.	-				
APPURTENANT STRUCTURES:					
Defective spillways.	NO				
Dewatering device clogged.	NO				
Cracking or crushing of pipes.	NO				
Other.	-				
COMMENTS:					



TRAPPER MINING INC.

TRAPPER MINING INC.**QUARTERLY SEDIMENT POND INSPECTION REPORT**INSPECTOR: Tim CumminsSIGNATURE: Tim CumminsDRAINAGE: **MIDDLE FLUME**DATE OF INSPECTION: 9-16-25

POND IDENTIFICATION	Middle Flume #1	Middle Flume #3			
Approximate water level:	30%	10%			
Sediment level (% total storage):	40%	0%			
Outflow (cfs):	0	0			
Sediment marker (install or replace)	IN PLACE	IN PLACE			
Identification sign (install or replace)	IN PLACE	IN PLACE			
EROSIONAL:					
Rills and/or gullies on downstream face.	No	No			
Rills and/or gullies on upstream face.	No	No			
Inadequate vegetation.	No	No			
Outlet channel erosion.	No	No			
Burrows.	No	No			
Erosion of toe.	No	No			
Water impounded against downstream toe.	No	No			
Other.	—	—			
STRUCTURAL:					
Differential settling.	No	No			
Cracks, slides, or scarps.	No	No			
Seepage (specify location, color, value).	No	No			
Defective spillways.	No	No			
Other.	—	—			
APPURTENANT STRUCTURES:					
Defective spillways.	No	No			
Dewatering device clogged.	No	No			
Cracking or crushing of pipes.	No	No			
Other.	—	—			
COMMENTS:					

Middle Flume 3 was recently cleaned of sediment

TRAPPER MINING INC.**QUARTERLY SEDIMENT POND INSPECTION REPORT**INSPECTOR: Tim CumminsSIGNATURE: Tim CumminsDRAINAGE: **EAST MIDDLE FLUME**DATE OF INSPECTION: 9-16-25

POND IDENTIFICATION	East Middle Flume #1				
Approximate water level:	1/5 %				
Sediment level (% total storage):	5 %				
Outflow (cfs):	0				
Sediment marker (install or replace)	IN PLACE				
Identification sign (install or replace)	IN PLACE				
EROSIONAL:					
Rills and/or gullies on downstream face.	NO				
Rills and/or gullies on upstream face.	NO				
Inadequate vegetation.	NO				
Outlet channel erosion.	NO				
Burrows.	NO				
Erosion of toe.	NO				
Water impounded against downstream toe.	NO				
Other.	—				
STRUCTURAL:					
Differential settling.	NO				
Cracks, slides, or scarps.	NO				
Seepage (specify location, color, value).	NO				
Defective spillways.	NO				
Other.	—				
APPURTENANT STRUCTURES:					
Defective spillways.	NO				
Dewatering device clogged.	NO				
Cracking or crushing of pipes.	NO				
Other.	—				
COMMENTS:					

This impoundment recently had sediment removal



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tim CumminsDRAINAGE: **EAST FLUME**SIGNATURE: Tim CumminsDATE OF INSPECTION: 9-16-25

POND IDENTIFICATION	East Flume #1				
Approximate water level:	<i>Dry</i>				
Sediment level (% total storage):	<i>15%</i>				
Outflow (cfs):	<i>0</i>				
Sediment marker (install or replace)	<i>IN PLACE</i>				
Identification sign (install or replace)	<i>IN PLACE</i>				
EROSIONAL:					
Rills and/or gullies on downstream face.	<i>No</i>				
Rills and/or gullies on upstream face.	<i>No</i>				
Inadequate vegetation.	<i>No</i>				
Outlet channel erosion.	<i>No</i>				
Burrows.	<i>No</i>				
Erosion of toe.	<i>No</i>				
Water impounded against downstream toe.	<i>No</i>				
Other.	<i>—</i>				
STRUCTURAL:					
Differential settling.	<i>No</i>				
Cracks, slides, or scarps.	<i>No</i>				
Seepage (specify location, color, value).	<i>No</i>				
Defective spillways.	<i>No</i>				
Other.	<i>—</i>				
APPURTENANT STRUCTURES:					
Defective spillways.	<i>No</i>				
Dewatering device clogged.	<i>No</i>				
Cracking or crushing of pipes.	<i>No</i>				
Other.	<i>—</i>				
COMMENTS:					



INSPECTOR: Tonia PerkinsDRAINAGE: **UTE GULCH****TRAPPER MINING INC.****QUARTERLY SEDIMENT POND INSPECTION REPORT**SIGNATURE: *Tonia Perkins*DATE OF INSPECTION: 9/18/2025

POND IDENTIFICATION	Ute #1				
Approximate water level:	<i>DRY</i>				
Sediment level (% total storage):	<i>45.1</i>				
Outflow (cfs):	<i>0</i>				
Sediment marker (install or replace)	<i>IN PLACE</i>				
Identification sign (install or replace)	<i>IN PLACE</i>				
EROSIONAL:					
Rills and/or gullies on downstream face:	<i>NO</i>				
Rills and/or gullies on upstream face:	<i>NO</i>				
Inadequate vegetation:	<i>NO</i>				
Outlet channel erosion:	<i>NO</i>				
Burrows:	<i>NO</i>				
Erosion of toe:	<i>NO</i>				
Water impounded against downstream toe:	<i>NO</i>				
Other:	<i>-</i>				
STRUCTURAL:					
Differential settling:	<i>NO</i>				
Cracks, slides, or scarps:	<i>NO</i>				
Seepage (specify location, color, value):	<i>NO</i>				
Defective spillways:	<i>NO</i>				
Other:	<i>-</i>				
APPURTENANT STRUCTURES:					
Defective spillways:	<i>NO</i>				
Dewatering device clogged:	<i>NO</i>				
Cracking or crushing of pipes:	<i>NO</i>				
Other:	<i>-</i>				
COMMENTS:					



TRAPPER MINING INC.**QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR:

Tim Cummins
Tonia Perkins**DRAINAGE: HORSE GULCH**

SIGNATURE:

Tim Cummins

DATE OF INSPECTION: 9-17-25

POND IDENTIFICATION	Horse #1				
Approximate water level:	DRY				
Sediment level (% total storage):	55%				
Outflow (cfs):	0				
Sediment marker (install or replace)	IN PLACE				
Identification sign (install or replace)	IN PLACE				
EROSIONAL:					
Rills and/or gullies on downstream face.	No				
Rills and/or gullies on upstream face.	No				
Inadequate vegetation.	No				
Outlet channel erosion.	No				
Burrows.	No				
Erosion of toe.	No				
Water impounded against downstream toe.	No				
Other.	—				
STRUCTURAL:					
Differential settling.	No				
Cracks, slides, or scarps.	No				
Seepage (specify location, color, value).	No				
Defective spillways.	No				
Other.	—				
APPURTENANT STRUCTURES:					
Defective spillways.	No				
Dewatering device clogged.	No				
Cracking or crushing of pipes.	No				
Other.	—				
COMMENTS:					



TRAPPER MINING INC.**QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR:

Tim Cummins
~~Tonia Perkins~~**DRAINAGE: WEST HORSE GULCH**

SIGNATURE:

Tim Cummins

DATE OF INSPECTION:

9-17-25

POND IDENTIFICATION	West Horse #1				
Approximate water level:	PRY				
Sediment level (% total storage):	20%				
Outflow (cfs):	0				
Sediment marker (install or replace)	IN PLACE				
Identification sign (install or replace)	IN PLACE				
EROSIONAL:					
Rills and/or gullies on downstream face.	No				
Rills and/or gullies on upstream face.	No				
Inadequate vegetation.	No				
Outlet channel erosion.	No				
Burrows.	No				
Erosion of toe.	No				
Water impounded against downstream toe.	No				
Other.					
STRUCTURAL:					
Differential settling.	No				
Cracks, slides, or scarps.	No				
Seepage (specify location, color, value).	No				
Defective spillways.	No				
Other.					
APPURTENANT STRUCTURES:					
Defective spillways.	No				
Dewatering device clogged.	No				
Cracking or crushing of pipes.	No				
Other.					
COMMENTS:					



TRAPPER MINING INC.

TRAPPER MINING INC. QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR:

Tim Cummins
Tim Cummins

DRAINAGE: DEAL GULCH

SIGNATURE:

Tim Cummins


DATE OF INSPECTION:

9-17-25

POND IDENTIFICATION	Deal #1	Deal #2			
Approximate water level:	50%	minimal			
Sediment level (% total storage):	5%	minimal			
Outflow (cfs):	0	0			
Sediment marker (install or replace)	under water	in-place			
Identification sign (install or replace)	in-place	in-place			
EROSIONAL:					
Rills and/or gullies on downstream face.	No	No			
Rills and/or gullies on upstream face.	No	No			
Inadequate vegetation.	No	No			
Outlet channel erosion.	No	No			
Burrows.	No	No			
Erosion of toe.	No	No			
Water impounded against downstream toe.	No	No			
Other.	-	-			
STRUCTURAL:					
Differential settling.	No	No			
Cracks, slides, or scarps.	No	No			
Seepage (specify location, color, value).	No	No			
Defective spillways.	No	No			
Other.	-	-			
APPURTENANT STRUCTURES:					
Defective spillways.	No	No			
Dewatering device clogged.	No	No			
Cracking or crushing of pipes.	No	No			
Other.	-	-			
COMMENTS:					



TRAPPER MINING INC. **QUARTERLY SEDIMENT POND INSPECTION REPORT**

INSPECTOR: Tonia PerkinsSIGNATURE: DRAINAGE: **DEACON**DATE OF INSPECTION: 9/18/2025

POND IDENTIFICATION	Deacon #1	Deacon #2		
Approximate water level:	<i>DRY</i>	<i>DRY</i>		
Sediment level (% total storage):	<i>0</i>	<i>0</i>		
Outflow (cfs):	<i>0</i>	<i>0</i>		
Sediment marker (install or replace)	<i>In Place</i>	<i>In Place</i>		
Identification sign (install or replace)	<i>In Place</i>	<i>In Place</i>		
EROSIONAL:				
Rills and/or gullies on downstream face.	<i>NO</i>	<i>NO</i>		
Rills and/or gullies on upstream face.	<i>NO</i>	<i>NO</i>		
Inadequate vegetation.	<i>NO</i>	<i>NO</i>		
Outlet channel erosion.	<i>NO</i>	<i>NO</i>		
Burrows.	<i>NO</i>	<i>NO</i>		
Erosion of toe.	<i>NO</i>	<i>NO</i>		
Water impounded against downstream toe.	<i>NO</i>	<i>NO</i>		
Other.	<i>—</i>	<i>—</i>		
STRUCTURAL:				
Differential settling.	<i>NO</i>	<i>NO</i>		
Cracks, slides, or scarps.	<i>NO</i>	<i>NO</i>		
Seepage (specify location, color, value).	<i>NO</i>	<i>NO</i>		
Defective spillways.	<i>NO</i>	<i>NO</i>		
Other.	<i>—</i>	<i>—</i>		
APPURTENANT STRUCTURES:				
Defective spillways.	<i>NO</i>	<i>NO</i>		
Dewatering device clogged.	<i>NO</i>	<i>NO</i>		
Cracking or crushing of pipes.	<i>NO</i>	<i>NO</i>		
Other.	<i>—</i>	<i>—</i>		
COMMENTS:				



TRAPPER MINING INC.**QUARTERLY SEDIMENT POND INSPECTION REPORT**INSPECTOR: Tonia PerkinsDRAINAGE: **JEFFWAY**SIGNATURE: *Tonia Perkins*DATE OF INSPECTION: 9/18/2025

POND IDENTIFICATION	Jeffway #1				
Approximate water level:	DRY				
Sediment level (% total storage):	51.				
Outflow (cfs):	0				
Sediment marker (install or replace)	In Place				
Identification sign (install or replace)	In Place				
EROSIONAL:					
Rills and/or gullies on downstream face.	NO				
Rills and/or gullies on upstream face.	NO				
Inadequate vegetation.	NO				
Outlet channel erosion.	NO				
Burrows.	NO				
Erosion of toe.	NO				
Water impounded against downstream toe.	NO				
Other.					
STRUCTURAL:					
Differential settling.	NO				
Cracks, slides, or scarps.	NO				
Seepage (specify location, color, value).	NO				
Defective spillways.	NO				
Other.					
APPURTENANT STRUCTURES:					
Defective spillways.	NO				
Dewatering device clogged.	NO				
Cracking or crushing of pipes.	NO				
Other.					
COMMENTS:					



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia PerkinsDRAINAGE: **EAST BUZZARD**SIGNATURE: *Tonia Perkins*DATE OF INSPECTION: 9/18/2025

POND IDENTIFICATION	East Buzzard #3				
Approximate water level:	50%.				
Sediment level (% total storage):	5%.				
Outflow (cfs):	0				
Sediment marker (install or replace)	In place				
Identification sign (install or replace)	In place				
EROSIONAL:					
Rills and/or gullies on downstream face.	no				
Rills and/or gullies on upstream face.	no				
Inadequate vegetation.	no				
Outlet channel erosion.	no				
Burrows.	no				
Erosion of toe.	no				
Water impounded against downstream toe.	no				
Other.	-				
STRUCTURAL:					
Differential settling.					
Cracks, slides, or scarps.	no				
Seepage (specify location, color, value).	no				
Defective spillways.	no				
Other.	-				
APPURTENANT STRUCTURES:					
Defective spillways.	no				
Dewatering device clogged.	no				
Cracking or crushing of pipes.	no				
Other.	-				
COMMENTS:					



TRAPPER MINING INC.
QUARTERLY SEDIMENT POND INSPECTION REPORT

INSPECTOR: Tonia PerkinsDRAINAGE: **WEST BUZZARD**SIGNATURE: Tonia PerkinsDATE OF INSPECTION: 9/16/2025

POND IDENTIFICATION	West Buzzard #3	West Buzzard #4		
Approximate water level:	10'1.	10'1.		
Sediment level (% total storage):	5'1.	5'1.		
Outflow (cfs):	0	0		
Sediment marker (install or replace)	In Place	In Place		
Identification sign (install or replace)	In Place	In Place		
EROSIONAL:				
Rills and/or gullies on downstream face.	NO	NO		
Rills and/or gullies on upstream face.	NO	NO		
Inadequate vegetation.	NO	NO		
Outlet channel erosion.	NO	NO		
Burrows.	NO	NO		
Erosion of toe.	NO	NO		
Water impounded against downstream toe.	NO	NO		
Other.	—	—		
STRUCTURAL:				
Differential settling.	NO	NO		
Cracks, slides, or scarps.	NO	NO		
Seepage (specify location, color, value).	NO	NO		
Defective spillways.	NO	NO		
Other.	—	—		
APPURTENANT STRUCTURES:				
Defective spillways.	NO	NO		
Dewatering device clogged.	NO	NO		
Cracking or crushing of pipes.	NO	NO		
Other.	—	—		
COMMENTS:				



TRAPPER MINING INC.

TRAPPER MINING INC.**QUARTERLY SEDIMENT POND INSPECTION REPORT**INSPECTOR: Tonia PerkinsDRAINAGE: **IMPOUNDMENT H**SIGNATURE: *Tonia Perkins*DATE OF INSPECTION: 9/18/2025

POND IDENTIFICATION	Impoundment H					
Approximate water level:	100%					
Sediment level (% total storage):	5%					
Outflow (cfs):	21 cfs					
Sediment marker (install or replace)	FN Place					
Identification sign (install or replace)	FN Place					
EROSIONAL:						
Rills and/or gullies on downstream face.	NO					
Rills and/or gullies on upstream face.	NO					
Inadequate vegetation.	NO					
Outlet channel erosion.	NO					
Burrows.	NO					
Erosion of toe.	NO					
Water impounded against downstream toe.	NO					
Other.	-					
STRUCTURAL:						
Differential settling.	NO					
Cracks, slides, or scarps.	NO					
Seepage (specify location, color, value).	NO					
Defective spillways.	NO					
Other.	-					
APPURTENANT STRUCTURES:						
Defective spillways.	NO					
Dewatering device clogged.	NO					
Cracking or crushing of pipes.	NO					
Other.	-					
COMMENTS:						



TRAPPER MINING INC.

TRAPPER MINING INC.**QUARTERLY SEDIMENT POND INSPECTION REPORT**INSPECTOR: Tim CumminsSIGNATURE: Tim Cummins**DRAINAGE: INDUSTRIAL WASTE POND**DATE OF INSPECTION: 9/15/25

POND IDENTIFICATION	Industrial Waste Pond #1				
Approximate water level:	61%				
Sediment level (% total storage):	7%				
Outflow (cfs):	0				
Sediment marker (install or replace)	N/A				
Identification sign (install or replace)	IN PLACE				
EROSIONAL:					
Rills and/or gullies on downstream face.	No				
Rills and/or gullies on upstream face.	No				
Inadequate vegetation.	No				
Outlet channel erosion.	No				
Burrows.	No				
Erosion of toe.	No				
Water impounded against downstream toe.	No				
Other.	-				
STRUCTURAL:					
Differential settling.	No				
Cracks, slides, or scarps.	No				
Seepage (specify location, color, value).	No				
Defective spillways.	No				
Other.	-				
APPURTENANT STRUCTURES:					
Defective spillways.	N/A				
Dewatering device clogged.	N/A				
Cracking or crushing of pipes.	N/A				
Other.	-				
COMMENTS:					

