## **QUARTERLY POND INSPECTION REPORT** Bowie Resources LLC Quarter: 3rd 2025 Operator: Mine: 29-Sep-25 Bowie No. 2 Mine - C-1996-083 Inspection Date: D - Gob Pile K UTL West Pond Identification В С F - New Gob J UTL East Type of Pond Sediment Sediment Sediment Sediment Sediment Sediment Status During Inspection: Approximate Water Level 5942' 5990 5970' 5944' 5846' 5819 Sediment (% remaining) 90% 90% 80% 100% 100% 80% Outflow (cfs) 0 0 0 0 0 0 Features Problem Problem Problem Problem Problem Problem Yes/No Yes/No Yes/No Yes/No Yes/No Yes/No Erosional Rills & Gulleys No No No No No No Inadequate Vegetation No No No No No No **Outlet Channel Erosion** No No No No No No Burrows No No No No No No Other No No No No No No Structural Differential Settling No No No No No No Cracks or Slides No Seepage No Other No No No No No No Appurtenant Structures **Defective Spillways** No No No No No No **Dewatering Devices Clogged** No No No No No No

## Additional Comments

Faulty Gates, Etc.

Other

Design depth measured from pond bottom to invert of emergency spillway:

Pond B=10', C=10', D=10', J=10', K=3', F=10' TD

No

No

Pond Bottom Elevations B=5942, C=5990, D=5970, F=5944, J=5846, K=5819

No

No

No

No

Pond B is dry Pond C is dry Pond D is dry

No

No

Pond F was cleaned out in June and dry

Pond J sediment removed late Q4 2024, water less than six inches deep

Pond K is dry

SWMP components were inspected and found to be in good condition. No corrections necessary at this time.

Name of Inspector: Art Etter

Arthur Etter

No

No

No

No

Colorado P. E. 42377 Date