



MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Red Wash Gravel Pit	MINE/PROSPECTING ID#: M-1999-040	MINERAL: Gravel	COUNTY: Rio Blanco
INSPECTION TYPE: Monitoring	WEATHER: Clear	INSP. DATE: October 8, 2025	INSP. TIME: 12:00
OPERATOR: Rio Blanco County	OPERATOR REPRESENTATIVE: Clint Chappell	TYPE OF OPERATION: 110c - Construction Limited Impact	
REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: Complete Bond	BOND AMOUNT: \$0.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: DRMS	JOINT INSP. AGENCY: None	
INSPECTOR(S): Amy Yeldell	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: October 22, 2025	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>NA</u>	(RD) ROADS----- <u>N</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>NA</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>NA</u>	(TS) TOPSOIL----- <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>Y</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>NA</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION-- <u>Y</u>	(ST) STIPULATIONS----- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>NA</u>	(OD) OFF-SITE DAMAGE----- <u>NA</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted as part of the Colorado Division of Reclamation, Mining and Safety (Division) normal monitoring program. The Red Wash Gravel Pit is a 110c permitted site that includes a total of 9.9 permitted acres. The site is located 16 miles south of Rangely, Colorado and is accessed from Rio Blanco County Road 111. The pit is on property owned by the Bureau of Land Management, no representative was present for the inspection. Clint Chappell represented the operator and accompanied Amy Yeldell of the Division on the inspection. No financial warranty is held for this site as is it operated by Rio Blanco County, per Rule 4.1.2(2).

A mine sign was posted at the entrance to the mine site as required by Rule 3.1.12(1). The information depicted was correct/ up to date and the sign was of sufficient size . The permit boundary of the affected land was clearly delineated pursuant to Rule 3.1.12(2). There is a gate located on the south side of the pit which grants access to the top of the cut located along the west side. Access to the east side of the pit cannot be restricted as it is adjacent to the county road.

The site was active over the summer. Rather than mining benches on the hillside the operation is now taking the top off layer by layer and then pushing down to process material. This is a safer and more efficient way to remove the material. Grizzly bars were located on the east side of the pit adjacent to the county road. No other processing equipment, structures, fuel, etc. are stored on site. A stockpile of screened material is located on the east side of the pit. A large pile of crushed material is located in the middle of the pit adjacent to the processing area. There are two active highwalls both of which appear stable.

Overall the site is kept in good working order. Little to no weeds were observed. Native vegetation has volunteered in some areas. No problems or violations were noted during this inspection.

Responses to this inspection report should be directed to: Amy Yeldell at the Division of Reclamation, Mining and Safety, Room 215, 1001 E 62nd Ave, Denver, CO 80216. Direct contact can be made by phone at 970-210-1272 or via email at amy.yeldell@state.co.us

Inspection Contact Address

Clint Chappell
Rio Blanco County
570 Second St.
Meeker, CO 81641

CC:
Travis Marshall, Senior EPS, Grand Junction DRMS
White River Field Office BLM

PHOTOGRAPHS







