



MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Johnson Draw	MINE/PROSPECTING ID#: M-1995-046	MINERAL: Gravel	COUNTY: Rio Blanco
INSPECTION TYPE: Monitoring	WEATHER: Clear	INSP. DATE: October 8, 2025	INSP. TIME: 12:45
OPERATOR: Rio Blanco County	OPERATOR REPRESENTATIVE: Clint Chappell	TYPE OF OPERATION: 112c - Construction Regular Operation	
REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: None	BOND AMOUNT: \$0.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: DRMS	JOINT INSP. AGENCY: None	
INSPECTOR(S): Amy Yeldell	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: October 22, 2025	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>NA</u>	(RD) ROADS----- <u>N</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>NA</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>NA</u>	(TS) TOPSOIL----- <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>Y</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>N</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>NA</u>	(SC) EROSION/SEDIMENTATION-- <u>Y</u>	(ST) STIPULATIONS----- <u>Y</u>
(AT) ACID OR TOXIC MATERIALS----- <u>NA</u>	(OD) OFF-SITE DAMAGE----- <u>NA</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted as part of the Colorado Division of Reclamation, Mining and Safety (Division) normal monitoring program. The Johnson Draw is a 112c permitted site that includes a total of 40 permitted acres. The site is located two miles west of Rangely, Colorado and is accessed from County Road 2. The pit is on property owned by the State Land Board. Clint Chappell represented the operator and accompanied Amy Yeldell of the Division on the inspection. No financial warranty is held for this site as it is operated by Rio Blanco County, per Rule 4.1.2(2).

A mine sign was posted at the entrance to the mine site as required by Rule 3.1.12(1). The information depicted was correct/ up to date and the sign was of sufficient size. The permit boundary of the affected land was clearly delineated pursuant to Rule 3.1.12(2).

This pit is approaching the conclusion of mining. Most of the perimeter has been graded. Some additional materials may be removed if not necessary for contouring. Additionally, the powerline along the south side of the site still has bank material. This material will likely be left as it is rather than coordinating the utility pole relocation. There is a stockpile of pit run on site. The county is debating if they wish to haul it off site to West Johnson Draw or bring in the crusher to process the remaining amount. Once this stockpile is removed final reclamation can commence. Some areas have begun to self-reclaim.

A dozer was located on site to complete grading tasks. No fuel was present. Overall, the site is kept in good working order. Stormwater controls are properly employed with no signs of erosion. Little to no weeds were observed. Native vegetation has volunteered in some areas. No problems or violations were noted during this inspection.

Responses to this inspection report should be directed to: Amy Yeldell at the Division of Reclamation, Mining and Safety, Room 215, 1001 E 62nd Ave, Denver, CO 80216. Direct contact can be made by phone at 970-210-1272 or via email at amy.yeldell@state.co.us

Inspection Contact Address

Clint Chappell
Rio Blanco County
570 Second Street
Meeker, CO 81641

CC:
Travis Marshall, Senior EPS, Grand Junction DRMS
State Land Board (SLB)

PHOTOGRAPHS







