



MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: C-JD-5	MINE/PROSPECTING ID#: M-1977-248	MINERAL: Uranium and vanadium	COUNTY: Montrose
INSPECTION TYPE: Monitoring	WEATHER: Clear	INSP. DATE: October 27, 2025	INSP. TIME: 14:00
OPERATOR: Gold Eagle Mining, Inc.	OPERATOR REPRESENTATIVE:	TYPE OF OPERATION: 112d-1 - Designated Mining Operation	
REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: None	BOND AMOUNT: \$100.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
INSPECTOR(S): Dustin Czapla	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: November 3, 2025	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>N</u>	(FN) FINANCIAL WARRANTY----- <u>N</u>	(RD) ROADS----- <u>N</u>
(HB) HYDROLOGIC BALANCE----- <u>N</u>	(BG) BACKFILL & GRADING----- <u>N</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>N</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>N</u>
(SM) SIGNS AND MARKERS----- <u>N</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>N</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>N</u>	(ST) STIPULATIONS----- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted as part of the Division of Reclamation, Mining and Safety's (Division) normal monitoring program. A representative for the operator was not present. Photographs are included with this report to illustrate conditions observed.

The C-JD-5 mine is located approximately ten miles west of Naturita and accessed from Dd19 Road. The site is a 112d-1 operation that includes a total of ten permitted acres. The site is located within a Department of Energy (DOE) lease tract. The Division holds a financial warranty amount of \$100.00. DOE holds the remainder of the financial warranty.

The site is in final reclamation. On October 9, 2024, the Mined Land Reclamation Board issued an order to the operator to complete all reclamation by October 30, 2025. On May 21, 2025 the Division issued a "Conditional Approval" for a technical revision (TR3), that proposed modifications to the Reclamation Plan which included (1) revisions to the ventilation shaft closure method, (2) a request to revise the structure removal plan to allow the head frame and hoist/compressor house to remain intact after reclamation, and (3) a request to allow the access roads to remain after reclamation. The Divisions "Conditions for Approval" stated that the Operator must also receive authorization from the associated land management agencies (DOE and BLM) for the Reclamation Plan changes proposed by TR3, and that once authorized by these land management agencies, the terms of TR3 would be incorporated into the permit. To date, the Division has not received documentation from the operator that the Reclamation Plan changes proposed through TR3 have been approved by DOE and BLM.

The head frame and hoist/compressor house structures remain on site. TR3 proposed securing these structures within fencing. Fencing materials were located on site, however the fencing was not yet installed at the time of this inspection.

In the Ore Bin area and the Joe Dandy Decline area, the wood debris has been removed, and the areas have been regraded and covered with cover soil. The areas have not been reseeded yet.

The vent shaft remains in place. The shaft is secured with steel grating welded to the shaft collar.

The vent fan and wood cribbing have been removed. The vent fan shaft had not yet been secured with grating welded to the collar.



Head frame and hoist/compressor house structures remain on site



Ore bin area – debris removed, area regraded



Joe Dandy Decline area – debris removed, area regraded



Vent shaft secured with steel grating welded to collar



Ventilation fan shaft – fan removed, shaft not yet secured

Inspection Contact Address

Don Coram
Gold Eagle Mining, Inc.
P.O. Box 3007
Montrose, CO 81402