



MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Weaselskin	MINE/PROSPECTING ID#: M-1986-148	MINERAL: Sand and gravel	COUNTY: La Plata
INSPECTION TYPE: Monitoring	WEATHER: Clear	INSP. DATE: October 28, 2025	INSP. TIME: 16:10
OPERATOR: Weaselskin Corp.	OPERATOR REPRESENTATIVE: None	TYPE OF OPERATION: 110c - Construction Limited Impact	
REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: None	BOND AMOUNT: \$8,215.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
INSPECTOR(S): Dustin Czapla	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: November 5, 2025	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>Y</u>	(RD) ROADS----- <u>NA</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>NA</u>
(PW) PROCESSING WASTE/TAILING---- <u>NA</u>	(SF) PROCESSING FACILITIES----- <u>NA</u>	(TS) TOPSOIL----- <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>Y</u>	(RV) REVEGETATION---- <u>Y</u>
(SM) SIGNS AND MARKERS----- <u>N</u>	(SP) STORM WATER MGT PLAN---- <u>NA</u>	(RS) RECL PLAN/COMP-- <u>Y</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>NA</u>	(SC) EROSION/SEDIMENTATION-- <u>Y</u>	(ST) STIPULATIONS----- <u>NA</u>
(AT) ACID OR TOXIC MATERIALS----- <u>NA</u>	(OD) OFF-SITE DAMAGE----- <u>NA</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted as part of the Division of Reclamation, Mining and Safety's (Division) normal monitoring program. A representative for the operator was not present. Photographs are included with this report to illustrate conditions observed.

The Weaselskin site is located approximately 6.4 miles southeast of Durango and accessed from a private drive from Hwy 550. The site is a 110c operation that includes a total of 5.0 permitted acres. The Division currently holds a financial warranty amount of \$8,215.00 for this site. The Division has reviewed the reclamation costs, to ensure the financial warranty reflects the actual current cost of fulfilling the requirements of the Reclamation Plan and determined that the current financial warranty amount is sufficient.

A mine sign or boundary markers were not noted at the site.

The site is in final reclamation. The slopes have been graded to 2H:1V. The slopes appear stable. Vegetation on the slopes is becoming well established. Noxious weed infestations were not noted.

One stockpile of gravel remains near the site entrance.

No stability or erosional concerns were noted.

Mining at the site has not exposed groundwater. No problems related to stormwater or erosion control were noted.

Overall, the operation appears to be in general compliance with the approved Mine Plan.

There was no processing waste observed on site.

The operation has not exposed acid or toxic forming materials. Fuels were not stored on site.

Explosives were not used by the operation.

No problems or violations were noted during this inspection.

Responses to this inspection report should be directed to Dustin Czapla at the Division of Reclamation, Mining and Safety, Room 215, 1001 E 62nd Avenue, Denver, CO 80216, phone number (970) 433-8393, dustin.czapla@state.co.us.



Inspection Contact Address

Doug Thurston
Weaselskin Corp.
12995 U.S. Hwy. 550
Durango, CO 81303