



**MINERALS PROGRAM INSPECTION REPORT**  
**PHONE: (303) 866-3567**

**The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.**

<b>MINE NAME:</b> Rock Dog #1	<b>MINE/PROSPECTING ID#:</b> M-2005-045	<b>MINERAL:</b> Sand and gravel	<b>COUNTY:</b> La Plata
<b>INSPECTION TYPE:</b> Monitoring	<b>WEATHER:</b> Clear	<b>INSP. DATE:</b> October 29, 2025	<b>INSP. TIME:</b> 12:00
<b>OPERATOR:</b> Oldcastle SW Group, Inc. dba Four Corners Materials	<b>OPERATOR REPRESENTATIVE:</b> None	<b>TYPE OF OPERATION:</b> 112c - Construction Regular Operation	
<b>REASON FOR INSPECTION:</b> Normal I&E Program	<b>BOND CALCULATION TYPE:</b> None	<b>BOND AMOUNT:</b> \$194,409.00	
<b>DATE OF COMPLAINT:</b> NA	<b>POST INSP. CONTACTS:</b> None	<b>JOINT INSP. AGENCY:</b> None	
<b>INSPECTOR(S):</b> Dustin Czapla	<b>INSPECTOR'S SIGNATURE:</b> 	<b>SIGNATURE DATE:</b> November 7, 2025	

**GENERAL INSPECTION TOPICS**

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

<b>(AR) RECORDS-----</b>	<b>Y</b>	<b>(FN) FINANCIAL WARRANTY-----</b>	<b>Y</b>	<b>(RD) ROADS-----</b>	<b>Y</b>
<b>(HB) HYDROLOGIC BALANCE-----</b>	<b>Y</b>	<b>(BG) BACKFILL &amp; GRADING-----</b>	<b>Y</b>	<b>(EX) EXPLOSIVES-----</b>	<b>NA</b>
<b>(PW) PROCESSING WASTE/TAILING----</b>	<b>NA</b>	<b>(SF) PROCESSING FACILITIES----</b>	<b>NA</b>	<b>(TS) TOPSOIL-----</b>	<b>Y</b>
<b>(MP) GENL MINE PLAN COMPLIANCE-</b>	<b>Y</b>	<b>(FW) FISH &amp; WILDLIFE-----</b>	<b>Y</b>	<b>(RV) REVEGETATION---</b>	<b>N</b>
<b>(SM) SIGNS AND MARKERS-----</b>	<b>Y</b>	<b>(SP) STORM WATER MGT PLAN---</b>	<b>NA</b>	<b>(RS) RECL PLAN/COMP--</b>	<b>N</b>
<b>(ES) OVERBURDEN/DEV. WASTE-----</b>	<b>NA</b>	<b>(SC) EROSION/SEDIMENTATION--</b>	<b>Y</b>	<b>(ST) STIPULATIONS-----</b>	<b>NA</b>
<b>(AT) ACID OR TOXIC MATERIALS-----</b>	<b>NA</b>	<b>(OD) OFF-SITE DAMAGE-----</b>	<b>NA</b>		

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

## OBSERVATIONS

This inspection was conducted as part of the Division of Reclamation, Mining and Safety's (Division) normal monitoring program. A representative for the operator was not present. Photographs are included with this report to illustrate conditions observed.

The Rock Dog #1 site is located approximately 10 miles southeast of Durango and accessed from CR 309. The site is a 112c operation that includes a total of 224.2 permitted acres. The Division currently holds a financial warranty amount of \$194,409.00 for this site. The Division will review the reclamation costs to ensure the financial warranty reflects the actual current cost of fulfilling the requirements of the Reclamation Plan. The Operator will be notified under separate cover if the Division determines that the current financial warranty amount is insufficient.

Adequate mine identification signage was noted at the entrance to the site.

The affected area was marked by posts and fencing that was clearly visible and adequate to delineate the affected area boundary.

Approximately 40 acres are currently affected. Mining has progressed southward through the Phase C and B areas, into the Phase A area. A crusher or any other processing equipment were not on site. Crushed gravel stockpiles are located in the Phase C and B areas. The highwall slope on the east side of the Phase C and B areas is graded to approximately 2H:1V and vegetation is becoming well established on the slope. The highwall on the south end of the pit is roughly 4 feet high by 300 linear feet and 1H:1V.

No stability or erosional concerns were noted.

Mining at the site has not exposed groundwater. No problems related to stormwater or erosion control were noted.

Overall, the operation appears to be in general compliance with the approved Mine Plan.

There was no processing waste observed on site.

The operation has not exposed acid or toxic forming materials. Fuels were not stored on site.

Explosives are not used by the operation.

Noxious weed infestations were not observed.

No problems or violations were noted during this inspection.

Responses to this inspection report should be directed to Dustin Czapla at the Division of Reclamation, Mining and Safety, Room 215, 1001 E 62<sup>nd</sup> Avenue, Denver, CO 80216, phone number (970) 433-8393, [dustin.czapla@state.co.us](mailto:dustin.czapla@state.co.us).





**Inspection Contact Address**

Tyra Bartuska  
Oldcastle SW Group, Inc., dba Four Corners Materials  
9755 CR 213  
Durango, CO 81303