



STATE OF
COLORADO

Simmons - DNR, Leigh <leigh.simmons@state.co.us>

C1980007, West Elk Mine, November Inspection Report

Simmons - DNR, Leigh <leigh.simmons@state.co.us>
To: "Wilczek, Jessica A." <JessicaWilczek@coreresources.com>

Wed, Nov 19, 2025 at 12:59 PM

Attached

Leigh Simmons
Environmental Protection Specialist



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

P 720.220.1180

Physical address: 1313 Sherman Street, Room 215, Denver, CO 80203

Mailing address: Colorado Division of Reclamation, Mining and Safety, Room 215, 1001 E 62nd Avenue, Denver, CO 80216
leigh.simmons@state.co.us | <https://drms.colorado.gov>

INSP-REPORTC_C1980007_LDS_11192025123445.pdf
4078K



PERMIT INFORMATION

Permit Number: C-1980-007 Mine Name: West Elk Mine Operator: Mountain Coal Company, LLC Operator Address: Jessica Wilczek 5174 Highway 133 Somerset, CO 81434	County: Delta, Gunnison Operation Type: Underground Permit Status: Active Ownership: Private
	Operator Representative Present: N/A
Operator Representative Signature: (Field Issuance Only)	

INSPECTION INFORMATION

Inspection Start Date: November 18, 2025 Inspection Start Time: 11:00 Inspection End Date: Inspection End Time:	Inspection Type: Aerial Inspection Inspection Reason: Normal I&E Program Weather: Clear
Joint Inspection Agency: None	Joint Inspection Contacts:
Post Inspection Agency: None	Post Inspection Contacts:
Inspector(s): Leigh Simmons Brock Bowles	Inspector's Signature:  Signature Date: November 19, 2025

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

N - Air Resource Protection	N - Roads
N - Availability of Records	N - Reclamation Success
N - Backfill & Grading	N - Revegetation
N - Excess Spoil and Dev. Waste	N - Subsidence
N - Explosives	N - Slides and Other Damage
N - Fish & Wildlife	R - Support Facilities On-site
N - Hydrologic Balance	N - Signs and Markers
R - Gen. Compliance With Mine Plan	N - Support Facilities Not On-site
N - Other	N - Special Categories Of Mining
R - Processing Waste	N - Topsoil

COMMENTS

This was an aerial inspection conducted by the Division of Reclamation Mining and Safety (Division). Brock Bowles and Hunter Kragenbrink took the photographs, and the images were reviewed by Leigh Simmons. The weather was clear and dry. The mine was active.

GENERAL MINE PLAN COMPLIANCE:

MCC should submit a Minor Revision to update section 2.03 of the Permit Application Packet to reflect recent personnel changes.

PROCESSING WASTE/COAL MINE WASTE PILES – Rule 4.10 and 4.11**Drainage Control; Surface Stabilization; Placement:**

The images show haul trucks traveling to and from the RPEE, suggesting that processing waste was being transported.

SUPPORT FACILITIES - Rule 4.04:

The volume of material on the run-of-mine coal stockpile had been drawn down, including the fines at stack tube 3.

Material on top of the LRP appeared to have been graded. This should be reported in the quarterly waste pile report.

Equipment had been mobilized to begin construction of recently permitted B-seam MVB pads.

DOCUMENTS RECEIVED

N/A

OTHER (SPECIFY)

N/A

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

Number of Partial Inspection this Fiscal Year: 4

Number of Complete Inspections this Fiscal Year: 1

PHOTOGRAPHS



Figure 1: Overview of main facilities (west)

Number of Partial Inspection this Fiscal Year: 4

Number of Complete Inspections this Fiscal Year: 1



Figure 2: Overview of main facilities (east)

Number of Partial Inspection this Fiscal Year: 4

Number of Complete Inspections this Fiscal Year: 1



Figure 3: Run-of-mine coal stockpile

Number of Partial Inspection this Fiscal Year: 4

Number of Complete Inspections this Fiscal Year: 1



Figure 4: Silos, clean coal stockpile and train loadout

Number of Partial Inspection this Fiscal Year: 4

Number of Complete Inspections this Fiscal Year: 1



Figure 5: Prep plant and LRP

Number of Partial Inspection this Fiscal Year: 4

Number of Complete Inspections this Fiscal Year: 1



Figure 6 Office and shop buildings, FW ponds, MSB, C1 conveyor and portal

Number of Partial Inspection this Fiscal Year: 4

Number of Complete Inspections this Fiscal Year: 1



Figure 7: RPE and RPEE haul road

Number of Partial Inspection this Fiscal Year: 4

Number of Complete Inspections this Fiscal Year: 1



Figure 8: RPEE

Number of Partial Inspection this Fiscal Year: 4

Number of Complete Inspections this Fiscal Year: 1



Figure 9: Sylvester Gulch Mine Water Pumping Facility

Number of Partial Inspection this Fiscal Year: 4

Number of Complete Inspections this Fiscal Year: 1



Figure 10: MVB pads and roads

Number of Partial Inspection this Fiscal Year: 4

Number of Complete Inspections this Fiscal Year: 1




Figure 11: Dozer and excavator staged on USFS road

Number of Partial Inspection this Fiscal Year: 4

Number of Complete Inspections this Fiscal Year: 1