Hernandez, Alysha

From: Burgmaier, Susan

Sent: Wednesday, March 14, 2012 9:23 PM

To: 'Karo, Roy'

Cc: DRMS-Coal-Admin; Brown, Sandy; 'James, Jay'

Subject: Seneca IIW Mine C1982057 March 13 2012 Complete Inspection

Attachments: Seneca IIW March 13 2012 Complete.pdf

Hi Roy – my inspection report is attached. I spoke with Jay about Stock Tank T1 at IIW. He seemed to recall that the impoundment was intentionally removed from the map because it was no longer needed on the ground. I told him that it was definitely in place on the ground and appeared to be serving a purpose, but suggested that he discuss it with you. You can either leave it on the ground and put it back on the map (Exhibit 13-2) with an MR, or remove it on the ground (breach the "embankment" so it drains). Let me know what you guys decide, please.

Susan L. Burgmaier

Environmental Protection Specialist Colorado Division of Reclamation, Mining and Safety 1313 Sherman Street, Room 215 Denver CO 80203 303-866-3567 x 8111



COLORADO DIVISION OF RECLAMATION, MINING AND SAFETY COAL PROGRAM INSPECTION REPORT



PERMIT INFORMATION

Permit Number: C-1982-057	County: Routt				
Mine Name: Seneca II-W Mine	Operation Type: Surface				
Operator: Seneca Coal Company, LLC	Permit Status: Active				
Operator Address:	Ownership: Federal				
Mr Roy Karo	_				
37796 Routt County Road 53	Operator Representative Present:				
P.O. Box 670					
Hayden, CO 81639	Roy Karo				
•					
Operator Representative Signature: (Field Issuance Only)					

INSPECTION INFORMATION

Inspection Start Date: March 13, Inspection Start Time: 14:30 Inspection End Date: March 14, 2 Inspection End Time: 11:30			Inspection Type: Coal Comp Inspection Reason: Normal Weather: Clear	-	
Joint Inspection Agency: Joi		Joint	oint Inspection Contacts:		
None					
Post Inspection Agency:		Post 1	Post Inspection Contacts:		
None					
Inspector(s):	Inspector's Signature:		Signature Date:		
Susan L. Burgmaier	Sus	an	Brugmanin	03/14/12	

Inspection Topic Summary

March 13, 2012

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

NA - Air Resource Protection R - Roads

R - Availability of Records **Y** - Reclamation Success

 ${f Y}$ - Backfill & Grading ${f Y}$ - Revegetation

NA - Excess Spoil and Dev. Waste NA - Subsidence

NA - Explosives

R - Slides and Other Damage

R - Fish & Wildlife

Y - Support Facilities On-site

P - Signs and Markets

R - Hydrologic Balance
R - Signs and Markers

Y - Gen. Compliance With Mine Plan
 NA - Support Facilities Not On-site
 Y - Special Categories Of Mining

NA - Processing Waste Y - Topsoil

COMMENTS

This was a complete inspection of the Seneca IIW Mine conducted by Susan Burgmaier of CDRMS. Roy Karo of Seneca Coal Company was present during the inspection. Ground conditions at lower elevations were wet and muddy; the upper reaches of the mine areas were still covered by about 8" of snow. Only the lower areas were accessible by vehicle, as the upper roads had not been plowed.

AVAILABILITY OF RECORDS - Rule 5.02.4(1):

Records were inspected at the Sage Creek mine office and at the Seneca IIW mine office. All required records were available, as documented below.

FISH and WILDLIFE – Rule 4.18:

The area has been utilized extensively by elk and deer, as evidenced by the numerous game trails throughout the permit area.

HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

Ponds 005 and 006 were both discharging. Stock tanks T-1, T-2, T-3, and T-5 all held water. Stock Tank T-3 will need to be cleaned out this year; there was a fair amount of sediment in a delta at the outlet of Culvert A-1. Ponds 009, 015, 016, and 017 and Stock Tanks 18, 20, 25, 26, and 27 were inaccessible. The reconstructed section of Gulch 006 appeared to be stable.

ROADS – Rule 4.03 Construction 4.03.1(3)/4.03.2(3) Drainage 4.03.1(4)/4.03.2(4) Surfacing and Maintenance4.03.1(5) and (6)/4.03.2(5) and (6) Reclamation 4.03.1(7)/4.03.2(7):

Roads were muddy or snow covered. The only accessible roads were Road G to Pond 005, and Road A around to the Ridgeline Access road to LU-1A. Water was running down the Road G and Road A ditches. Ice

Number of <u>Partial</u> Inspection this Fiscal Year: 11 Number of Complete Inspections this Fiscal Year: 3 dams in the ditches on

Road G near Pond 005 and Road A at the facilities area had caused runoff to leave the channel in places, but the operator corrected the situation during the inspection.

SLIDES and DAMAGE - Rule 4.12:

No signs of movement were observed at any of the know areas of instability, nor were any new areas of instability observed. Much of the mine area was covered in snow, so detailed observations were not possible.

SUPPORT FACILITIES - Rule 4.04:

The facilities area was fairly saturated, but drainage ditches and culverts were functional.

SIGNS AND MARKERS - Rule 4.02:

Signs and markers were in place as required along the stream buffer zone, at the mine entrance, and along the permit boundary.

TOPSOIL – Rule 4.06 Removal 4.06.2; Substitute Materials 4.06.4(4); Storage and Protection 4.06.3; Redistribution 4.06.4:

The recently topsoiled areas along Road A were in good condition. Very few rills were observed; the straw wattles placed by the operator had been effective at preventing channelized flow.

DOCUMENTS RECEIVED

OTHER (SPECIFY)

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

PHOTOGRAPHS




A Pit/Upper 006 Drainage

B Pit and Substation



Number of <u>Partial</u> Inspection this Fiscal Year: 11 Number of <u>Complete</u> Inspections this Fiscal Year: 3

Page **5** of **8**







006 Drainage and Oil well site

Number of <u>Partial</u> Inspection this Fiscal Year: 11 Number of <u>Complete</u> Inspections this Fiscal Year: 3

Page **6** of **8**



Sediment Delta in Stock Tank T2

Reconstructed 006 Gulch



Number of <u>Partial</u> Inspection this Fiscal Year: 11 Number of <u>Complete</u> Inspections this Fiscal Year: 3

AVAILABILITY OF RECORDS

PERMIT RECORDS		HYDROLOGIC RECORDS	
DRMS Permit	X Exp 12/31/15	NPDES Permit	X Exp 10/31/2011
Permit Application w/Revisions	X @Sage Creek Office	NPDES Records	X 4 th Q 2011
Findings Document	X PR-6 2012	Stormwater Management Plan	Jan 25 2011
Insurance Certificate	X Exp 11/1/2012	SPCC Plan	X December 15, 2010
Bond Document	X SB \$6,743,430	MSHA Pond Inspections	NA
Phased Bond Release	X SL2		NA
Documents/Findings		State Engineer's Pond Inspection	
Air Emission Permits	NA	Quarterly Pond Inspections	X 4 th Q
County Special Use Permits	X 2014	Annual Hydrology Reports	X 2010
UG Mining Landowner Notification	NA	 Ground Water Monitoring 	Χ
Subsidence Monitoring Reports	NA	 Surface Water Monitoring 	Χ
Subsidence Monitoring Data	NA	 Spring & Seep Monitoring 	Χ
Rill & Gully Survey	X 2011	Mine Water Discharge Monitoring	NA
Vegetation Monitoring Data	X 2010	Mine Inflow Study	NA
Specific Variance Approvals	X PAP	Water Consumption Records	Dec 2011
Annual Reclamation Reports	X 2010	Well Permits	X Aug 1990
Midterm Review Documents	X 2008		
DRMS/OSM Inspection	Χ		
Reports/Enforcement Actions (3 Years)		BLASTING RECORDS	
Transfers/Succession of Operator	X 1994	Blasting Publication	NA
Temporary Cessation Notification	NA	Blasting Records (3 years)	NA (last blast Jan '06)
Reclamation Cost Estimate	X SL2	ATFE Explosives Permit	NA
CERTIFICATIONS		Blasting Variances	PAP
Pond Certifications	X PAP	Pre-Blast Surveys	PAP
Annual Certifications for Impoundments	X 2011 (Sept '11)		
Fill Certifications for Excess Spoil or Underground Development Waste	NA	ADDITIONAL RECORDS (specify)	
Quarterly Inspections	NA		
 Compaction Testing 	NA		
 Final Certification 	NA		
Coal Processing Waste Banks	NA		
Haul Road Certifications	X PAP		
Access Road Certifications	X PAP		
COMMENTS:			

Number of <u>Partial</u> Inspection this Fiscal Year: 11 Number of <u>Complete</u> Inspections this Fiscal Year: 3