



Denison Mines (USA) Corp.  
1050 17th Street, Suite 950  
Denver, CO 80265  
USA

Tel : 303 628-7798  
Fax : 303 389-4125

[www.denisonmines.com](http://www.denisonmines.com)

May 8, 2012

Bob Oswald  
Colorado Department of Natural Resources  
Division of Reclamation, Mining and Safety  
691 County Road 233, Unit A2  
Durango, Colorado 81301

James Blair  
Bureau of Land Management  
Tres Rios Public Lands Office  
29211 Hwy. 184  
Dolores, CO, 81323

Dear Mr. Oswald & Mr. Blair:

**Re: Concurrent Reclamation and Cleanup at the Sunday Mines (M/1977-285 & COC53227)**


Denison Mines (USA) Corp ("Denison") performed some cleanup and concurrent reclamation operations at the Sunday Mine Complex in the spring of 2012. Specifically, at the Sunday Mine, Denison removed a compressor building (compressor to be picked up by contractor in the near future), various large scrap metal items, scrap metal from the Sunday scale and former fuel storage area, and corrugated metal piping that was located at the north edge of the Sunday development rock area. Although no specific bond line item is associated with these items, Denison wanted to notify you that cleanup was performed at the site and unnecessary metal structures and scrap have been removed. Photographic documentation is attached for your use and reference. We are scheduled to meet at the site to discuss the Sunday Environmental Assessment in the near future; however, let me know if you would like to schedule a visit earlier than July 18<sup>th</sup> or if you have any questions or comments.

Yours very truly,

**DENISON MINES (USA) CORP.**

A handwritten signature in blue ink that reads "Christy Woodward".

Christy Woodward, P.E.  
Environmental Coordinator



Cc: Denison Mines (USA) Corp, File  
Terry Wetz, Philip Buck & Terry MacKinnon, Denison Mines (USA) Corp.

**Denison Mines (USA) Corp  
Sunday Mines Photographic Log  
Spring 2012**

**Sunday Mines Compressor  
Building (before).**



**Sunday Mines Compressor  
Building Removed (after)  
Compressor to be removed by  
contractor.**



**Denison Mines (USA) Corp**  
**Sunday Mines Photographic Log**  
**Spring 2012**

Scrap iron box near the Sunday Portal (before).



Area where scrap metal box was located (after).



**Denison Mines (USA) Corp  
Sunday Mines Photographic Log  
Spring 2012**

Scrap metal frames located near Sunday portal (before).



Area where scrap metal frames were located (after).





**Denison Mines (USA) Corp**  
**Sunday Mines Photographic Log**  
**Spring 2012**

Scrap Iron at the toe of the  
Sunday Mine development rock  
area (before).



Scrap Iron at the toe of the  
Sunday Mine development rock  
area (before).



**Denison Mines (USA) Corp**  
**Sunday Mines Photographic Log**  
**Spring 2012**

Scrap Iron at the toe of the  
Sunday Mine development rock  
area (after).



**Denison Mines (USA) Corp  
Sunday Mines Photographic Log  
Spring 2012**

Scrap Iron at the Sunday Mine  
scale (before).



Scrap Iron at the Sunday Mine  
scale (after).





**Denison Mines (USA) Corp  
Sunday Mines Photographic Log  
Spring 2012**

**Metal culverts north of the  
Sunday Mine (before).**



**Metal culverts north of the  
Sunday Mine (after).**





**Denison Mines (USA) Corp**  
**Sunday Mines Photographic Log**  
**Spring 2012**

Scale at the Sunday Mine  
(before).



Scale at the Sunday Mine  
(after).



**Denison Mines (USA) Corp  
Sunday Mines Photographic Log  
Spring 2012**

Scrap iron near the Sunday  
Mine east entrance (before).



Scrap iron removed near the  
Sunday Mine east entrance  
(after).

