




COLORADO DIVISION OF RECLAMATION, MINING AND SAFETY
MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Dotsero Quarry	MINE/PROSPECTING ID#: M-1987-074	MINERAL: Volcanic materials	COUNTY: Eagle
INSPECTION TYPE: Monitoring	INSPECTOR(S): Dustin M. Czapla	INSP. DATE: June 5, 2012	INSP. TIME: 14:00
OPERATOR: Mayne Block & Stone Company	OPERATOR REPRESENTATIVE: None	TYPE OF OPERATION: 112c - Construction Regular Operation	

REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: BC (Complete)	BOND AMOUNT: \$100.00
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None
WEATHER: Clear	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: June 21, 2012

The following inspection topics were identified as having Problems or Possible Violations. OPERATORS SHOULD READ THE FOLLOWING PAGES CAREFULLY IN ORDER TO ASSURE COMPLIANCE WITH THE TERMS OF THE PERMIT AND APPLICABLE RULES AND REGULATIONS. If a Possible Violation is indicated, you will be notified under separate cover as to when the Mined Land Reclamation Board will consider possible enforcement action.

INSPECTION TOPIC: Signs & Markers

PROBLEM/POSSIBLE VIOLATION: Problem: The mine identification sign and affected area boundary markers were not observed per the requirements of Rule 3.1.12.

CORRECTIVE ACTIONS: The operator must post a sign at the entrance to the mine site which shall be clearly visible from the access road and specify the following; the name of the operator, indicate that a reclamation permit for the operation has been issued by the Colorado Mined Land Reclamation Board, and the permit number. The boundaries of the affected area must be marked by monuments or other markers that are clearly visible and adequate to delineate such boundaries.

CORRECTIVE ACTION DUE DATE: 7/23/12

OBSERVATIONS

This inspection was conducted as part of the Division of Reclamation, Mining and Safety's (Division) normal monitoring program. An operator representative was not present during this inspection. Photographs are included with this report in order to illustrate some of the conditions observed during this inspection.

The Dotsero Quarry is located approximately 1.5 miles northeast of Dotsero and accessed from Trail Gulch Road. The site is a 112c operation that includes a total of 65.5 permitted acres.

The Division currently holds a financial warranty amount of \$100.00 for this site. Pursuant to Rule 4.2.1(6), the Bureau of Land Management holds the remainder of the Financial Warranty. The amount of \$35,400 required to be posted with the BLM has been reviewed and is considered adequate to reclaim the site based on the conditions observed during this inspection.

The mine identification sign and affected area boundary markers were not observed during this inspection.

Mining was not occurring during this inspection. Vegetation is becoming well established in the reclaimed southern portion of the permit area. Several pieces of equipment were located in the quarry area. Mined slopes around the quarry appeared to be approximately 1H:1V on average.

No other problems or violations were noted during this inspection.

Responses to this inspection report should be directed to Dustin Czapla at the Division of Reclamation, Mining and Safety, Grand Junction Field Office, 101 South 3rd Street, Room 301, Grand Junction, Colorado 81501, phone number (970) 243-6299.

PHOTOGRAPHS



Figure 1: View from quarry area, facing south towards reclaimed area.



Figure 2: View facing north towards highwall.



Figure 3: View facing north towards highwall.



Figure 4: View facing north towards mine area.

GENERAL INSPECTION TOPICS

The following list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>Y</u>	(RD) ROADS----- <u>N</u>
(HB) HYDROLOGIC BALANCE----- <u>N</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING--- <u>Y</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION--- <u>Y</u>
(SM) SIGNS AND MARKERS----- <u>PB</u>	(SP) STORM WATER MGT PLAN--- <u>N</u>	(SB) COMPLETE INSP--- <u>Y</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>Y</u>	(RS) RECL PLAN/COMP-- <u>Y</u>
(AT) ACID OR TOXIC MATERIALS----- <u>Y</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	(ST) STIPULATIONS----- <u>N</u>

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

Inspection Contact Address

Matthew Welte
Mayne Block & Stone Company
P.O. Box 533
Pueblo, CO
81002

Enclosure

CC: