

COLORADO DIVISION OF RECLAMATION, MINING AND SAFETY MINERALS PROGRAM INSPECTION REPORT

PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME:	MINE/PROSPECTING ID#:	MINERAL: COUNTY:	
Krehmeyer Pit	M-2005-070	Gravel and sand Phillips	
INSPECTION TYPE:	INSPECTOR(S):	INSP. DATE: INSP. TIME:	
Monitoring	Berhan Keffelew	June 19.2012 13:00	
OPERATOR:	OPERATOR REPRESENTATIVE:	TYPE OF OPERATION:	
Ritchey's Redi-Mix Concrete, Inc.	Jerry Ritchey	110c - Construction Limited Impact	

REASON FOR INSPECTION:	BOND CALCULATION TYPE:	BOND AMOUNT:
Normal I&E Program	None	\$7,400.00
DATE OF COMPLAINT:	POST INSP. CONTACTS:	JOINT INSP. AGENCY:
NA	None	None
WEATHER:	INSPECTOR'S SIGNATURE:	SIGNATURE DATE:
Clear		July 13, 2012

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS <u>Y</u>	(FN) FINANCIAL WARRANTY <u>Y</u>	(RD) ROADS <u>Y</u>
(HB) HYDROLOGIC BALANCE <u>Y</u>	(BG) BACKFILL & GRADING <u>Y</u>	(EX) EXPLOSIVES <u>NA</u>
(PW) PROCESSING WASTE/TAILING Y	(SF) PROCESSING FACILITIES N	(TS) TOPSOIL <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- Y	(FW) FISH & WILDLIFE <u>Y</u>	(RV) REVEGETATION <u>Y</u>
(SM) SIGNS AND MARKERS <u>Y</u>	(SP) STORM WATER MGT PLAN N	(SB) COMPLETE INSP N
(ES) OVERBURDEN/DEV. WASTE NA	(SC) EROSION/SEDIMENTATION NA	(RS) RECL PLAN/COMP Y
(AT) ACID OR TOXIC MATERIALS NA	(OD) OFF-SITE DAMAGE <u>NA</u>	(ST) STIPULATIONS <u>NA</u>

 $Y = Inspected \ and \ found \ in \ compliance \ / \ N = \ Not \ inspected \ / \ NA = \ Not \ applicable \ to \ this \ operation \ / \ PB = Problem \ cited \ / \ PV = \ Possible \ violation \ cited \ PV = Poss$

PERMIT #: M-2005-070 INSPECTOR'S INITIALS: BMK INSPECTION DATE: September 24, 2007

OBSERVATIONS

- 1) The site is a small sand and gravel operation in a dry stream bed that is in reclamation. The site is located approximately 7 miles south of Haxtun Colorado. Present during the inspection was Mr. Jerry Ritchey the operator.
- 2) The approved reclamation plan for the site is to allow the river bed to reclaim the bottom of the channel and the operator to reclaim the embankments. The reclaimed embankments appeared stable and vegetated. There was a small amount of top soil/overburden stockpiled along the east side of the permit area that the operator plans to spread along the embankment.
- 3) Permit sign and boundary markers properly posted. There is an adjacent 110 permit (M-2004-037) Evert Pit mining the same river bottom.
- 4) The current financial warranty for the site in the amount of \$7,400.00 is more than adequate to cover the rest of the reclamation. The operation is in compliance with the approved reclamation plan

PHOTOGRAPHS



Figure 1 permit sign




Figure 2 looking @ the active dry gulch which was mined



Figure 3 looking at the small overburden stockpile $% \left\{ 1,2,\ldots ,n\right\}$



Figure 4 looking at the naturally reclaimed dry stream bed



PERMIT #: M-2005-070 INSPECTOR'S INITIALS: BMK INSPECTION DATE: September 24, 2007

Inspection Contact Address
Jerry Ritchey
Ritchey's Redi-Mix Concrete, Inc.
509 S Idlewild St Yuma, CO 80759

Enclosure

CC: