

COLORADO DIVISION OF RECLAMATION, MINING AND SAFETY MINERALS PROGRAM INSPECTION REPORT

PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME:	MINE/PROSPECTING ID#:	MINERAL:	COUNTY:
North Clear Creek Const. Materials Mine	M-2006-039	Borrow	Garfield
INSPECTION TYPE:	INSPECTOR(S):	INSP. DATE:	INSP. TIME:
Monitoring	Travis H. Marshall	July 17, 2012	10:30
OPERATOR:	OPERATOR REPRESENTATIVE:	TYPE OF OPERATION:	
Chevron U.S.A. Inc.	Julie Justus	110c - Construction Limited Impact	

REASON FOR INSPECTION:	BOND CALCULATION TYPE:	BOND AMOUNT:
Normal I&E Program DATE OF COMPLAINT:	POST INSP. CONTACTS:	\$36,939.00 JOINT INSP. AGENCY:
NA	None	None
WEATHER:	INSPECTOR'S SIGNATURE:	SIGNATURE DATE:
Clear	" Colonill	July 26, 2012

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS <u>Y</u>	(FN) FINANCIAL WARRANTY <u>Y</u>	(RD) ROADS <u>Y</u>
(HB) HYDROLOGIC BALANCE <u>Y</u>	(BG) BACKFILL & GRADING <u>Y</u>	(EX) EXPLOSIVES <u>NA</u>
(PW) PROCESSING WASTE/TAILING NA	(SF) PROCESSING FACILITIES Y	(TS) TOPSOIL <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- Y	(FW) FISH & WILDLIFE <u>Y</u>	(RV) REVEGETATION <u>Y</u>
(SM) SIGNS AND MARKERS <u>Y</u>	(SP) STORM WATER MGT PLAN NA	(SB) COMPLETE INSP Y
(ES) OVERBURDEN/DEV. WASTE NA	(SC) EROSION/SEDIMENTATION Y	(RS) RECL PLAN/COMP Y
(AT) ACID OR TOXIC MATERIALS NA	(OD) OFF-SITE DAMAGE <u>Y</u>	(ST) STIPULATIONS NA

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

PERMIT #: M-2006-039 INSPECTOR'S INITIALS: THM INSPECTION DATE: July 17, 2012

OBSERVATIONS

This inspection was conducted as part of the normal program established by the Colorado Division of Reclamation, Mining and Safety. The North Clear Creek Construction Materials Mine is a 110c permitted site located approximately 15 miles north of Debeque, Colorado on Clear Creek Road. Julie Justus of Chevron North America Exploration and Production was present during the inspection.

The mine identification sign and permit boundary markers were in place and in compliance with rule 3.1.12. The sign is located at the main entrance to the gravel mine. Permit boundary markers were comprised of fence posts that were evenly spaced and easily identified along the perimeter permit boundary.

Various pieces of heavy equipment were located within the permit area. The mine was inactive during the inspection. It appeared that only 2-3 acres of reserve material remains.

No weeds were observed within the permit area during the inspection.

No problems or violations were observed during the inspection.

Responses to this inspection report should be directed to Travis Marshall at the Division of Reclamation, Mining and Safety, Grand Junction Field Office, 101 South 3rd Street, Room 301, Grand Junction, Colorado 81501, phone no. 970-241-2042.

PHOTOGRAPHS



Inspection Contact Address
Julie Justus Chevron U.S.A. Inc. 760 Horizon Dr Grand JUnction, CO 81506