

COLORADO DIVISION OF RECLAMATION, MINING AND SAFETY MINERALS PROGRAM INSPECTION REPORT

PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME:	MINE/PROSPECTING ID#:	COMMODITY:	COUNTY:
Mountain View Pit	M-1981-002	Sand and Gravel	Gunnison
INSPECTION TYPE:	INSPECTOR(S):	INSP. DATE:	INSP. TIME:
Monitoring	Dustin Czapla	August 17, 2012	09:00
OPERATOR:	OPERATOR REPRESENTATIVE:	TYPE OF OPERATION:	
Town of Crested Butte	Bob Gilley, Rodney Due	110(c)	
REASON FOR INSPECTION:	BOND CALCULATION TYPE:	BOND AMOUNT:	
Monitoring	None	\$ NA	
DATE OF COMPLAINT:	POST INSP. CONTACTS:	JOINT INSPECTION AGENCY:	
NA	None	None	
WEATHER:	INSPECTOR'S SIGNATURE:	SIGNATURE DATE:	
Clear		August 21, 2012	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. Note: any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

		- 12 CONT.
(AR) RECORDS <u>Y</u>	(FN) FINANCIAL WARRANTY NA	(RD) ROADS <u>NA</u>
(HB) HYDROLOGIC BALANCE <u>Y</u>	(BG) BACKFILL & GRADING <u>Y</u>	(EX) EXPLOSIVES <u>NA</u>
(PW) PROCESSING WASTE/TAILING <u>NA</u>	(SF) PROCESSING FACILITIES NA	(TS) TOPSOIL <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE-Y	(FW) FISH & WILDLIFE <u>N</u>	(RV) REVEGETATION N
(SM) SIGNS AND MARKERS <u>Y</u>	(SP) STORM WATER MGT PLAN N	(SB) COMPLETE INSP N
(ES) OVERBURDEN/DEV. WASTE <u>NA</u>	(SC) EROSION/SEDIMENTATION \underline{Y}	(RS) RECL PLAN/COMP Y
(AT) ACID OR TOXIC MATERIALS <u>NA</u>	(OD) OFF-SITE DAMAGE <u>NA</u>	(ST) STIPULATIONS <u>NA</u>

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

M-1981-002

8/17/2012

INSPECTION DATE:

OBSERVATIONS

This inspection was conducted as part of the Division of Reclamation, Mining and Safety's (Division) normal Bob Gilley and Rodney Due, representing the Operator, were present during this inspection. Photographs are included with this report in order to illustrate some of the conditions observed.

The Mountain View Pit is located on the south side of the town of Crested Butte and accessed from a dirt road which begins at the intersection of Red Lady and 9th streets. The site is a 110c operation that includes a total of 9.1 permitted acres. The Division does not hold a financial warranty for this site.

Adequate mine identification signage was noted at the entrance to the site.

The affected area was marked by survey lathe that was clearly visible and adequate to delineate the affected area boundary.

Highwall stabilization efforts had been completed along the south side of the permit area. The highwall had been graded and seeded. Little topsoil exists at the site, but vegetation is beginning to establish itself. The slope appeared stable with no erosion features noted. At the base of the highwall is a flat, gravelled bench area.

Noxious weeds were not observed.

No problems or violations were noted during this inspection.

Responses to this inspection report should be directed to Dustin Czapla at the Division of Reclamation, Mining and Safety, Grand Junction Field Office, 101 South 3rd Street, Room 301, Grand Junction, Colorado 81501, phone number (970) 243-6299.

Inspection and Enforcement Contact

Rodney Due Town of Crested Butte P.O. Box 39 Crested Butte, CO 81224

Cc: None

PHOTOGRAPHS



Figure 1: Mine ID sign located at site entrance.




Figure 2: View of site, facing northwest, from the east side of the permit area.



Figure 3: View of site, facing southeast, from the west side of the permit area. The yellow line is the approximate west permit boundary.