

## COLORADO DIVISION OF RECLAMATION, MINING AND SAFETY COAL PROGRAM INSPECTION REPORT



# **PERMIT INFORMATION**

Permit Number: C-1981-019 Mine Name: Colowyo Coal Mine Operator: Colowyo Coal Company L.P. Operator Address: Mr. Tony Tennyson 5731 State Highway 13 Meeker, CO 81641 County: Moffat, Rio Blanco Operation Type: Surface Permit Status: Active Ownership: Federal

**Operator Representative Present:** 

Kurt Blunt

**Operator Representative Signature:** (Field Issuance Only)

## **INSPECTION INFORMATION**

Inspection Start Date: December 19, 2012 Inspection Start Time: 12:00 Inspection End Date: December 20, 2012 Inspection End Time: 10:30		Inspection	<b>Inspection Type:</b> Coal Complete Inspection <b>Inspection Reason:</b> Normal I&E Program <b>Weather:</b> Clear	
Joint Inspection Agency:		Joint Inspection Contacts:		
None				
Post Inspection Agency:		Post Inspection Contacts:		
None				
Inspector(s):	Inspector'	's Signature:	Signature D	ate:
Robert D. Zuber	Ph	ut D.	2/26/20	12

### **Inspection Topic Summary**

NOTE: Y=Inspected	N=Not Inspected	R=Comments Noted	V = Violation Issued	NA=Not Applicable
Y - Air Resource P	rotection		<b>R</b> - Roads	
Y - Availability of	Records		Y - Reclamation	on Success
R - Backfill & Grad	ding		<b>R</b> - Revegetati	on
R - Excess Spoil ar	nd Dev. Waste		NA - Subsider	ice
Y - Explosives			Y - Slides and	Other Damage
Y - Fish & Wildlife		<b>R</b> - Support Facilities On-site		
<b>R</b> - Hydrologic Balance		Y - Signs and Markers		
R - Gen. Complian	ce With Mine P	lan	NA - Support	Facilities Not On-site
N - Other			NA - Special (	Categories Of Mining
NA - Processing W	aste		Y - Topsoil	

## **COMMENTS**

Rob Zuber of DRMS conducted the complete inspection. Kurt Blunt of Colowyo also participated in the inspection. The ground was covered with 30 inches or more of snow, and most of the site was not accessible. The areas that could be accessed: the Gossard Loadout area, the active pits (West Pit and South Taylor), much of the facilities area, and the ponds along Highway 13 (observed from the road).

The weather was cold and clear; no precipitation was experienced.

Several pieces of heavy equipment were clearing snow from roads. No trucks were operating. The 115 excavator was working in the South Taylor Pit, apparently clearing snow from the work area.

The county road along Wilson Creek (CR 51) was driven, and no unauthorized development was seen. Thus CCC is in compliance with the relevant stipulations.

BACKFILL and GRADING – Rule 4.14 Contemporaneous Reclamation 4.14.1; Approximate Original Contour 4.14.2; Highwall Elimination 4.14.1(2)(f); Steep Slopes 4.14.2, 4.27; Handling of Acid and Toxic Materials 4.14.3; Stabilization of Rills and Gullies 4.14.6:

The East Pit was not accessible.

In the West Pit, the 103 dragline was idle. A drill rig was onsite but was not in operation at the time of the inspection.

EXCESS SPOIL and DEVELOPMENT WASTE – Rule 4.09 Delacement; Drainage Control; Surface Stabilization:

No problems were identified at the Streeter Fill, the West Taylor Fill, or the East Taylor Fill. At the West Taylor Fill, a dozer was clearing snow at the dump area.

HYDROLOGIC BALANCE - Rule 4.05 Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

The following ponds were (partially) inspected: Prospect, Streeter, Rail Loop, Gossard, and Stoker Siding. The inspection entailed looking at the ponds from the nearest road. All were holding water. Streeter was observed to be discharging. It could not be determined if others were discharging. No problems were identified with embankments, spillways, or other aspects of the ponds.

The road to the Section 28 Pond was not passable due to snow.

### GENERAL MINE PLAN COMPLANCE:

The mine was found to be in general compliance with the permit.

ROADS – Rule 4.03  $\square$  Construction 4.03.1(3)/4.03.2(3)  $\square$  Drainage 4.03.1(4)/4.03.2(4)  $\square$  Surfacing and Maintenance 4.03.1(5) and (6)/4.03.2(5) and (6)  $\square$  Reclamation 4.03.1(7)/4.03.2(7):

Several pieces of heavy equipment were clearing haul roads; the majority of the haul roads were clear at the time of the inspection, but other roads were generally blocked.

### REVEGETATION – Rule 4.15 □ Vegetative Cover; Timing:

The ground was covered with 30 inches or more of snow, and revegetation could not be assessed.

#### SUPPORT FACILITIES - Rule 4.04:

The main facilities area, the Gossard Loadout, and the South Taylor Ready Line were inspected. They were only partially cleared of snow. No problems were observed.

## ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were taken as a result of this inspection, and none are pending.

## **PHOTOGRAPHS**



West Pit – idle 103 dragline and drill rig. The 101 dragline is in background, on horizon.



**South Taylor Pit – idle haul trucks** 



Haul Road to South Taylor (foreground) and West Pit reclamation (looking north)



**Stoker Siding Pond** 



**Gossard Pond – water level below pipe invert** 



Road to Section 28 Pond



Prospect Pond – flume covered with snow



Prospect Pond – embankment (photo from County Road 13)



Streeter Pond – sign of discharge



**Streeter Fill** 



**Gossard Loadout (looking south)** 

HYDROLOGIC RECORDS

## **AVAILABILITY OF RECORDS**

#### PERMIT RECORDS

	Erra 11/5/2012	NDDEC Demait	CO 0045161
DRMS Permit	Exp 11/5/2012	NPDES Permit	CO 0045161
Permit Application w/Revisions	yes	NPDES Records	Thru 3rd Q 2012
Findings Document	RN-05	Stormwater Management Plan	yes
Insurance Certificate	Exp 1/1/13	SPCC Plan	April 2012
Bond Document	Comment 1	MSHA Pond Inspections	NA
Phased Bond Release	<b>GI</b> 05		
Documents/Findings	SL-05	State Engineer's Pond Inspection	NA
Air Emission Permits	Comment 2	Quarterly Pond Inspections	Thru 3rd Q 2012
County Special Use Permits	Comment 3	Annual Hydrology Reports	2011
UG Mining Landowner Notification	NA	<ul> <li>Ground Water Monitoring</li> </ul>	yes
Subsidence Monitoring Reports	NA	<ul> <li>Surface Water Monitoring</li> </ul>	yes
Subsidence Monitoring Data	NA	<ul> <li>Spring &amp; Seep Monitoring</li> </ul>	yes
Rill & Gully Survey	May 2012	Mine Water Discharge	
		Monitoring	NA
Vegetation Monitoring Data	2011 ARR and	Mine Inflow Study	NA
	SL-05		
Specific Variance Approvals	Yes, in PAP	<ul> <li>Water Consumption Records</li> </ul>	yes
Annual Reclamation Reports	2011	Well Permits	yes
Midterm Review Documents	MT-05		
DRMS/OSM Inspection	Thru November		
Reports/Enforcement Actions (3	2012, May 2011		
Years)	for OSM	BLASTING RECORDS	
Transfers/Succession of Operator	MR-113	Blasting Publication	Comment 5
Temporary Cessation Notification	NA	Blasting Records (3 years)	Thru 12/18/2012
Reclamation Cost Estimate	SL-05	ATFE Explosives Permit	Comment 6
CERTIFICATIONS		Blasting Variances	NA
Pond Certifications	yes	Pre-Blast Surveys	Yes, 1997
Annual Certifications for	NA		
Impoundments			
Fill Certifications for Excess Spoil		ADDITIONAL RECORDS	
or Underground Development Waste	Comment 4	(specify)	
<ul> <li>Quarterly Inspections</li> </ul>	yes		
<ul> <li>Compaction Testing</li> </ul>	NA		
• Final Certification	NA		
Coal Processing Waste Banks	NA		
Haul Road Certifications	yes		
Access Road Certifications	NA		

### COMMENTS:

1.	Bond numbers 929528345 and 190022683 for total of \$69,517,829.
2.	Air permits 95MF1040 and 06RB1317.
3.	Rio Blanco County SUP08-10, Moffat County C-05-05
4.	Through 3rd quarter 2012. South Taylor Fill and West Pit Fill inspected September 14, 2012.
5.	Published on 12/10/12 and 12/13/12.
6.	Permit 5-CO-103-20-3E-12055.