



**COLORADO DIVISION OF RECLAMATION, MINING AND SAFETY
COAL PROGRAM INSPECTION REPORT**



PERMIT INFORMATION

Permit Number: C-1981-020 Mine Name: Munger Canyon Mine Operator: CAM Mining, LLC Operator Address: Mr. Gary Isaac P.O. Box 98 Loma, CO 81524	County: Garfield, Mesa Operation Type: Underground Permit Status: Permanent Cessation Ownership: Federal
	Operator Representative Present: None
Operator Representative Signature: (Field Issuance Only)	

INSPECTION INFORMATION

Inspection Start Date: February 27, 2013 Inspection Start Time: 12:15 Inspection End Date: February 27, 2013 Inspection End Time: 13:20	Inspection Type: Coal Partial Inspection Inspection Reason: Normal I&E Program Weather: Cloudy
Joint Inspection Agency: None	Joint Inspection Contacts:
Post Inspection Agency: None	Post Inspection Contacts:
Inspector(s): Michael P. Boulay	Inspector's Signature: <i>Michael P. Boulay</i> Signature Date: 3/5/13

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

N - Air Resource Protection

N - Availability of Records

N - Backfill & Grading

NA - Excess Spoil and Dev. Waste

NA - Explosives

N - Fish & Wildlife

Y - Hydrologic Balance

Y - Gen. Compliance With Mine Plan

NA - Other

N - Processing Waste

R - Roads

N - Reclamation Success

N - Revegetation

NA - Subsidence

N - Slides and Other Damage

N - Support Facilities On-site

R - Signs and Markers

R - Support Facilities Not On-site

NA - Special Categories Of Mining

N - Topsoil

COMMENTS

This was a partial inspection of the Munger Canyon Mine conducted by Mike Boulay of the DRMS Grand Junction Field Office on February 27, 2013. There was no operator/representative from Munger Canyon Mine present during the inspection. Weather conditions were partly cloudy and cold. The ground was snow covered from the storm that occurred prior to the inspection.

ROADS – Rule 4.03

Construction 4.03.1(3)/4.03.2(3)

Drainage 4.03.1(4)/4.03.2(4)

Surfacing and Maintenance 4.03.1(5) and (6)/4.03.2(5) and (6)

Reclamation 4.03.1(7)/4.03.2(7):

The mine site access road off of Highway 139 was deemed unsafe to travel on due to snow packed and icy conditions. The access road had not been plowed. There was no activity at the mine site and it did not appear that any one has attempted to travel onto the access road since the recent snowstorm.

SIGNS AND MARKERS – Rule 4.02:

The mine identification sign with operator information, DRMS Permit Number and MSHA ID is in good condition and clearly visible at the gated entrance to the site. See attached photograph at the end of this inspection report.

OFFSITE SUPPORT FACILITIES - Rule 4.04, 4.28:

The reclaimed Loma Loadout site was inspected. The site was entirely snow packed. There is no activity at the site and it remains in good condition. No problems were identified with this inspection.

Number of Partial Inspection this Fiscal Year: 6Number of Complete Inspections this Fiscal Year: 2

DOCUMENTS RECEIVED

None

OTHER (SPECIFY)

Number of Partial Inspection this Fiscal Year: 6

Number of Complete Inspections this Fiscal Year: 2

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were taken as a result of this inspection and none are pending.

Number of Partial Inspection this Fiscal Year: 6

Number of Complete Inspections this Fiscal Year: 2

PHOTOGRAPHS



Number of Partial Inspection this Fiscal Year: 6

Number of Complete Inspections this Fiscal Year: 2