




COLORADO DIVISION OF RECLAMATION, MINING AND SAFETY COAL PROGRAM INSPECTION REPORT



PERMIT INFORMATION

Permit Number: C-1980-006 Mine Name: Marr Mine Operator: Kerr Coal Company Operator Address: Mr. George Patterson C/O Energy Fuels Coal, Inc. P.O. Box 459 Florence, CO 81226	County: Jackson Operation Type: Surface Permit Status: Permanent Cessation Ownership: Federal
Operator Representative Present:	
Operator Representative Signature: (Field Issuance Only)	

INSPECTION INFORMATION

Inspection Start Date: April 18, 2013 Inspection Start Time: 11:30 Inspection End Date: Inspection End Time:	Inspection Type: Coal Partial Inspection Inspection Reason: Normal I&E Program Weather: Snowing
Joint Inspection Agency: None	Joint Inspection Contacts:
Post Inspection Agency: None	Post Inspection Contacts:
Inspector(s): Robert D. Zuber, P.E.	Inspector's Signature:  Signature Date: 4/19/2013

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

NA - Air Resource Protection

N - Availability of Records

N - Backfill & Grading

NA - Excess Spoil and Dev. Waste

NA - Explosives

N - Fish & Wildlife

R - Hydrologic Balance

R - Gen. Compliance With Mine Plan

N - Other

NA - Processing Waste

N - Roads

R - Reclamation Success

N - Revegetation

NA - Subsidence

N - Slides and Other Damage

N - Support Facilities On-site

N - Signs and Markers

NA - Support Facilities Not On-site

NA - Special Categories Of Mining

N - Topsoil

COMMENTS

A partial inspection was conducted by Rob Zuber of DRMS. The inspection covered the loadout. Snow was falling and the ground was covered with snow.

HYDROLOGIC BALANCE - Rule 4.05 □ □ Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

The Best Management Practices for sediment control from the reclaimed pond area at the loadout were covered with snow, and thus it could not be determined if they are functioning.

GENERAL MINE PLAN COMPLIANCE:

The site was found to be in general compliance with the permit.

RECLAMATION SUCCESS - Rule 4.15, Rule 3:

At the loadout, no erosion, large weed patches, or other problems were seen.

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were taken as a result of this inspection, and none are pending.

Number of Partial Inspection this Fiscal Year: 7

Number of Complete Inspections this Fiscal Year: 3

PHOTOGRAPHS



Reclamation at Loadout, looking south

Number of Partial Inspection this Fiscal Year: 7

Number of Complete Inspections this Fiscal Year: 3



Area at Loadout where reclaimed pond was accessed, looking west



BMPs below reclaimed pond area

Number of Partial Inspection this Fiscal Year: 7

Number of Complete Inspections this Fiscal Year: 3