

COLORADO DIVISION OF RECLAMATION, MINING AND SAFETY MINERALS PROGRAM INSPECTION REPORT

PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME:	MINE/PROSPECTING ID#:	MINERAL:	COUNTY:
Zadra Pit	M-1989-030	Gravel	San Miguel
INSPECTION TYPE:	INSPECTOR(S):	INSP. DATE:	INSP. TIME:
Monitoring	Kate A. Pickford	May 29, 2013	12:00
OPERATOR:	OPERATOR REPRESENTATIVE:	TYPE OF OPERATION:	
San Miguel County	Bill Wilson	112c - Construction Regular Operation	

REASON FOR INSPECTION:	BOND CALCULATION TYPE:	BOND AMOUNT:
Normal I&E Program	None	\$0.00
DATE OF COMPLAINT:	POST INSP. CONTACTS:	JOINT INSP. AGENCY:
NA	None	None
WEATHER:	INSPECTOR'S SIGNATURE:	SIGNATURE DATE:
Clear	Kate Mill	June 3, 2013

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS <u>Y</u>	(FN) FINANCIAL WARRANTY N	(RD) ROADS <u>Y</u>
(HB) HYDROLOGIC BALANCE <u>Y</u>	(BG) BACKFILL & GRADING \underline{Y}	(EX) EXPLOSIVES <u>N</u>
(PW) PROCESSING WASTE/TAILING N	(SF) PROCESSING FACILITIES N	(TS) TOPSOIL <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- Y	(FW) FISH & WILDLIFE \underline{Y}	(RV) REVEGETATION N
(SM) SIGNS AND MARKERS <u>Y</u>	(SP) STORM WATER MGT PLAN N	(SB) COMPLETE INSP N
(ES) OVERBURDEN/DEV. WASTE N	(SC) EROSION/SEDIMENTATION Y	(RS) RECL PLAN/COMP Y
(AT) ACID OR TOXIC MATERIALS N	_	(ST) STIPULATIONS <u>N</u>

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited


PERMIT #: M-1989-030 INSPECTOR'S INITIALS: KAP INSPECTION DATE: May 29, 2013

OBSERVATIONS

This inspection was conducted as part of the Division of Reclamation, Mining and Safety monitoring program. The condition of this site is very similar to that at the time of the inspection conducted in 2008. A sign is posted at the entrance to the site and the boundaries are easily identifiable in the field. The disturbance at this site consists of an excavation into a hillside adjacent to the county road. Topsoil has been stockpiled and preserved with vegetation. The excavation is oriented well away from the boundaries at the site.

The operation is being conducted within the parameters of the approved permit.

PHOTOGRAPHS














PERMIT #: M-1989-030 INSPECTOR'S INITIALS: KAP INSPECTION DATE: May 29, 2013

<u>Inspection Contact Address</u> Bill Wilson

Bill Wilson San Miguel County P.O. Box 426 Norwood, CO 81423