



**COLORADO DIVISION OF RECLAMATION, MINING AND SAFETY**  
**MINERALS PROGRAM INSPECTION REPORT**  
**PHONE: (303) 866-3567**

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

<b>MINE NAME:</b> Norwood Pit	<b>MINE/PROSPECTING ID#:</b> M-1981-154	<b>MINERAL:</b> Sand and gravel	<b>COUNTY:</b> San Miguel
<b>INSPECTION TYPE:</b> Monitoring	<b>INSPECTOR(S):</b> Kate A. Pickford	<b>INSP. DATE:</b> May 29, 2013	<b>INSP. TIME:</b> 11:30
<b>OPERATOR:</b> San Miguel County	<b>OPERATOR REPRESENTATIVE:</b> Bill Wilson	<b>TYPE OF OPERATION:</b> 112c - Construction Regular Operation	

  

<b>REASON FOR INSPECTION:</b> Normal I&E Program	<b>BOND CALCULATION TYPE:</b> IT.Bondcalculationtype.CD.Desc	<b>BOND AMOUNT:</b> \$0.00
<b>DATE OF COMPLAINT:</b> NA	<b>POST INSP. CONTACTS:</b> None	<b>JOINT INSP. AGENCY:</b> None
<b>WEATHER:</b> Clear	<b>INSPECTOR'S SIGNATURE:</b> <i>Kate A. Pickford</i>	<b>SIGNATURE DATE:</b> June 3, 2013

**GENERAL INSPECTION TOPICS**

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>N</u>	(RD) ROADS----- <u>Y</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>N</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(SB) COMPLETE INSP---- <u>N</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>N</u>	(RS) RECL PLAN/COMP-- <u>Y</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	(ST) STIPULATIONS----- <u>N</u>

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

### **OBSERVATIONS**

This inspection was conducted as part of the Division of Reclamation, Mining and Safety monitoring program. The condition of the site is similar to that present at the 2008 inspection. A sign is posted at the entrance to the site. The boundaries are easily identified by fences along the edges of the permitted area, with the exception of the center line between this and an adjacent, permitted site. The disturbance at this site consists of a pit covering much of the permitted site, although there is some ground to the west that has not yet been excavated. Large stockpiles of material are contained on the pit floor. Topsoil has been stockpiled and well preserved with vegetation.

The operation is being conducted within the parameters of the approved permit.



PHOTOGRAPHS



**Inspection Contact Address**

Bill Wilson  
San Miguel County  
P.O. Box 426  
Norwood, CO 81423