




**COLORADO DIVISION OF RECLAMATION, MINING AND SAFETY**  
**MINERALS PROGRAM INSPECTION REPORT**  
**PHONE: (303) 866-3567**

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

|   |  |   |                             |
|---|--|---|-----------------------------|
| <b>MINE NAME:</b><br>Pit Number One                       | <b>MINE/PROSPECTING ID#:</b><br>M-2000-099         | <b>MINERAL:</b><br>Sand and gravel                              | <b>COUNTY:</b><br>Chaffee   |
| <b>INSPECTION TYPE:</b><br>Monitoring                     | <b>INSPECTOR(S):</b><br>Dustin M. Czaplá           | <b>INSP. DATE:</b><br>May 22, 2013                              | <b>INSP. TIME:</b><br>12:30 |
| <b>OPERATOR:</b><br>Marilyn E. Diamond & Misty R. Vazquez | <b>OPERATOR REPRESENTATIVE:</b><br>Marylin Diamond | <b>TYPE OF OPERATION:</b><br>110c - Construction Limited Impact |                             |

|   |   |  |
|---|---|--|
| <b>REASON FOR INSPECTION:</b><br>Normal I&E Program | <b>BOND CALCULATION TYPE:</b><br>None   | <b>BOND AMOUNT:</b><br>\$18,835.00     |
| <b>DATE OF COMPLAINT:</b><br>NA                     | <b>POST INSP. CONTACTS:</b><br>None   | <b>JOINT INSP. AGENCY:</b><br>None     |
| <b>WEATHER:</b><br>Cloudy                           | <b>INSPECTOR'S SIGNATURE:</b><br> | <b>SIGNATURE DATE:</b><br>June 6, 2013 |

**GENERAL INSPECTION TOPICS**

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

|  |  |                                 |
|--|--|---------------------------------|
| (AR) RECORDS----- <u>Y</u>                 | (FN) FINANCIAL WARRANTY----- <u>N</u>    | (RD) ROADS----- <u>N</u>        |
| (HB) HYDROLOGIC BALANCE----- <u>Y</u>      | (BG) BACKFILL & GRADING----- <u>N</u>    | (EX) EXPLOSIVES----- <u>NA</u>  |
| (PW) PROCESSING WASTE/TAILING---- <u>N</u> | (SF) PROCESSING FACILITIES----- <u>Y</u> | (TS) TOPSOIL----- <u>Y</u>      |
| (MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>   | (FW) FISH & WILDLIFE----- <u>N</u>       | (RV) REVEGETATION---- <u>N</u>  |
| (SM) SIGNS AND MARKERS----- <u>Y</u>       | (SP) STORM WATER MGT PLAN---- <u>N</u>   | (SB) COMPLETE INSP---- <u>Y</u> |
| (ES) OVERBURDEN/DEV. WASTE----- <u>NA</u>  | (SC) EROSION/SEDIMENTATION--- <u>Y</u>   | (RS) RECL PLAN/COMP-- <u>Y</u>  |
| (AT) ACID OR TOXIC MATERIALS----- <u>Y</u> | (OD) OFF-SITE DAMAGE----- <u>N</u>       | (ST) STIPULATIONS----- <u>N</u> |

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

### **OBSERVATIONS**

This inspection was conducted as part of the Division of Reclamation, Mining and Safety's (Division) normal monitoring program. Marylin Diamond, representing the Operator, was present during this inspection. Photographs are included with this report in order to illustrate some of the conditions observed.

The Pit No. One mine is located approximately 3.3 miles southeast of Buena Vista and accessed from CR 301. The site is a 110c operation that includes a total of 9.61 permitted acres. The Division currently holds a financial warranty amount of \$18,835.00 for this site. The required financial warranty was updated following the Division's last inspection in 2012. Little to no additional disturbance has occurred at the site since that time, so the financial warranty is assumed to be adequate. The operator's most recent annual report appears to accurately portray the current site conditions.

Adequate mine identification signage was noted at the entrance to the site, and the affected area was adequately marked.

Mining activity was not occurring during this inspection.

No problems or violations were noted during this inspection.

Responses to this inspection report should be directed to Dustin Czapla at the Division of Reclamation, Mining and Safety, Grand Junction Field Office, 101 South 3<sup>rd</sup> Street, Room 301, Grand Junction, Colorado 81501, phone number (970) 243-6299.

### **Inspection Contact Address**

Marylin Diamond  
26520 CR 301  
Buena Vista, CO 81211



**PHOTOGRAPHS**

