

COLORADO DIVISION OF RECLAMATION, MINING AND SAFETY MINERALS PROGRAM INSPECTION REPORT

PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME:	MINE/PROSPECTING ID#:	MINERAL:	COUNTY:
Iris Project	P-2012-003	Au,Ag,Pb,Zn,Cu	Saguache
INSPECTION TYPE:	INSPECTOR(S):	INSP. DATE:	INSP. TIME:
Mineral Prospect Inspection	Bob Oswald	June 12, 2013	16:00
OPERATOR:	OPERATOR REPRESENTATIVE:	TYPE OF OPERATION:	
Garth Cooke	Garth Cooke	MP - Mineral Prospecting	

REASON FOR INSPECTION:	BOND CALCULATION TYPE:	BOND AMOUNT:
Normal I&E Program	None	\$4,071.00
DATE OF COMPLAINT:	POST INSP. CONTACTS:	JOINT INSP. AGENCY:
NA	None, A	None
WEATHER:	INSPECTOR'S SIGNATURE:	SIGNATURE DATE:
Clear	306 pmg	June 17, 2013

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS <u>Y</u>	(FN) FINANCIAL WARRANTY Y	(RD) ROADS <u>Y</u>
(HB) HYDROLOGIC BALANCE <u>Y</u>	(BG) BACKFILL & GRADING NA	(EX) EXPLOSIVES <u>NA</u>
(PW) PROCESSING WASTE/TAILING NA	(SF) PROCESSING FACILITIES \underline{Y}	(TS) TOPSOIL <u>NA</u>
(MP) GENL MINE PLAN COMPLIANCE- NA	(FW) FISH & WILDLIFE NA	(RV) REVEGETATION <u>NA</u>
(SM) SIGNS AND MARKERS NA	(SP) STORM WATER MGT PLAN NA	(SB) COMPLETE INSP NA
(ES) OVERBURDEN/DEV. WASTE NA	(SC) EROSION/SEDIMENTATION Y	(RS) RECL PLAN/COMP NA
(AT) ACID OR TOXIC MATERIALS Y	(OD) OFF-SITE DAMAGE <u>NA</u>	(ST) STIPULATIONS NA

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This was a minerals prospecting inspection performed by the Division to monitor the operator's drilling activity. The operator (named on page one) and three other personnel were at the site at the time of the inspection. The drilling equipment was deployed and active, and the drill hole at Site 2 was about 270 feet deep. The operator is extracting 1.5-inch diameter core. The bore hole was dry at that depth during the inspection.

The entire project activity is on privately-owned land, being within the platted townsite of Iris, all of which is owned by the operator. Water for the drill operation is supplied by water from the townsite, to which the operator has rights for use. The drill hole locations are accessible via existing roads, with no improvements needed. There is no leveling of the drill pad required, and no topsoil is stripped, although a small mud pit was excavated from the existing surface. It was lined by impermeable membrane, and was adequately containing all recirculating drill fluids.

The disturbance observed was minimal, and in conformance with the approved plan. There were no problems observed.

For questions related to this report, please contact this inspector at the Division's Durango Field Office: DRMS - Durango Field Office 691 CR 233, Room A-2 Durango, CO 81301 Telephone 970-247-5193

Inspection Contact Address
Garth Cooke
PO Box 95
Warne, NC 28909

PHOTOGRAPHS











