

## COLORADO DIVISION OF RECLAMATION, MINING AND SAFETY MINERALS PROGRAM INSPECTION REPORT

PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME:	MINE/PROSPECTING ID#:	MINERAL:	COUNTY:
J & J Pit	M-1985-001	Sand and gravel	La Plata
INSPECTION TYPE:	INSPECTOR(S):	INSP. DATE:	INSP. TIME:
Monitoring	Kate A. Pickford	May 16, 2013	12:00
OPERATOR:	OPERATOR REPRESENTATIVE:	TYPE OF OPERATION:	
Glacier Gravel Products		110c - Construction Limited Impact	

REASON FOR INSPECTION:	BOND CALCULATION TYPE:	BOND AMOUNT:
Normal I&E Program	Complete Bond	\$5,000.00
DATE OF COMPLAINT:	POST INSP. CONTACTS:	JOINT INSP. AGENCY:
NA	None	None
WEATHER:	INSPECTOR'S SIGNATURE:	SIGNATURE DATE:
Clear	the Mill	July 11, 2013

## **GENERAL INSPECTION TOPICS**

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS <u>Y</u>	(FN) FINANCIAL WARRANTY <u>Y</u>	(RD) ROADS <u>Y</u>
(HB) HYDROLOGIC BALANCE <u>Y</u>	(BG) BACKFILL & GRADING <u>Y</u>	(EX) EXPLOSIVES N
(PW) PROCESSING WASTE/TAILING N	(SF) PROCESSING FACILITIES $\underline{N}$	(TS) TOPSOIL <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- Y	(FW) FISH & WILDLIFE $\underline{N}$	(RV) REVEGETATION N
(SM) SIGNS AND MARKERS <u>N</u>	(SP) STORM WATER MGT PLAN N	(SB) COMPLETE INSP N
(ES) OVERBURDEN/DEV. WASTE <u>N</u>	(SC) EROSION/SEDIMENTATION N	(RS) RECL PLAN/COMP N
(AT) ACID OR TOXIC MATERIALS N	(OD) OFF-SITE DAMAGE <u>N</u>	(ST) STIPULATIONS N

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

PERMIT #: M-1985-001 INSPECTOR'S INITIALS: KAP INSPECTION DATE: May 16, 2013

## **OBSERVATIONS**

This inspection was conducted as part of the Division of Reclamation, Mining and Safety monitoring program. The inspection was conducted aerially.


Relative to past inspections, there is more disturbance at the site. The highwall is much higher, estimated at approximately 50 feet in height and approximately 900 feet in length. There is additional acreage disturbed at the site than there was at the previous inspection, as well.

A bond calculation was conducted, based on the current amount of disturbance at the site. There is an increase in the required bond. Notice of the increase is included in this mailing.

## **PHOTOGRAPHS**














PERMIT #: M-1985-001 INSPECTOR'S INITIALS: KAP INSPECTION DATE: May 16, 2013

<u>Inspection Contact Address</u> Jim Helmericks Glacier Gravel Products 995 Hwy 3 Durango, CO 81301

Enclosure