




COLORADO DIVISION OF RECLAMATION, MINING AND SAFETY
MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: New Hay Camp Pit	MINE/PROSPECTING ID#: M-2013-031	MINERAL: Gravel	COUNTY: Montezuma
INSPECTION TYPE: Preoperation Inspection	INSPECTOR(S): Kate A. Pickford	INSP. DATE: July 5, 2013	INSP. TIME: 12:00
OPERATOR: McStone Aggregates	OPERATOR REPRESENTATIVE: Casey McClellan	TYPE OF OPERATION: 112c - Construction Regular Operation	

REASON FOR INSPECTION: Preoperation Inspection	BOND CALCULATION TYPE: Complete Bond	BOND AMOUNT: Undetermined
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None
WEATHER: Clear	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: July 16, 2013

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>Y</u>	(RD) ROADS----- <u>Y</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>N</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>N</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>N</u>
(SM) SIGNS AND MARKERS----- <u>N</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(SB) COMPLETE INSP---- <u>N</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>N</u>	(RS) RECL PLAN/COMP-- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	(ST) STIPULATIONS----- <u>N</u>

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted as a pre-operational inspection for a new 112c permit.

The site is located adjacent to the existing Hay Camp permit. The area consists of a lower level that is vegetated with grasses, where the access road and potential plants and stockpile areas are to be located; and an upper area that is currently vegetated with pinion/juniper, where excavation will occur.

A high voltage power line crosses the property. Accommodations for this line have been included within the permit application.

No mining related disturbance was observed within the proposed permit area.
Review of the application is still in process.

PHOTOGRAPHS



PERMIT #: M-2013-031
INSPECTOR'S INITIALS: KAP
INSPECTION DATE: July 5, 2013

Inspection Contact Address

Casey McClellan
McStone Aggregates
200 4th Street
P.O. Box 1525
Dolores, CO 81323-1525