Property Line
BLM Road Easement
Mining Area
Permit Boundary
Containment Ditch
Fence
Mining Direction
Test Pit

Weed Management

May 2012 pit inspection: No noxious weeds noticed.
Cattle onsite May thru ? this report period. Majority of pit acreage undisturbed with sparce native vegetation.

Southern Bank of River in 1895

NOTE: This area of LOT 4 was previously South of the Gunnison River. It unknown if the river changed course by avulsion or reliction.

Section 28

SW¼ NE¼

United Companies of Mesa County

Bureau of Land Management
30' Road Easement
Book 2783, Pages 829-833
Release of Easement
Book 4089, Pages 23-28

Wide Berm

Front Gate

Truck Scales

Berm

Stockpiles

Working Face

Haul Road

Left Bank 1895 GLO Meander Line

Future Sediment Pond

Mining Area 6
4.28 Acres

3 Catch Basin Areas

Old Mining Face

Mining Area 4
28.28 Acres

Mining Area 3
38.34.51 Acres

United Companies of Mesa County

NE¼ SW¼

Old Mining Area

Mining Area 2
11.75 Acres

30' Road Easement
Book 1272, Page 441

Berm

Fence

McCurther Land Company LLC

McCurther Land Company LLC

Highway 141

Left Bank 1895 GLO Meander Line

BLM

John E Schwartz

BD Interests LLC

Permit Bounadry
153.04 Acres

Bureau of Land Management
Exclusive Road Easement
Book 1749, Pages 362-365

SW¼ SE¼

SE¼ SW¼

Mining Area 5
28.78 Acres

SW¼ SW¼

Old Mill Road

BLM

Road ROW Road Book 1 Page 75
Also Book 4336 Page 808
Book 2189 Page 125 grants
10' easement

Book 573, Page 124

0 150 300 450

Notes:

Revisions	BY	DATE

DES: RE
DRN: RE
CHK:

Date
12/21/2010

Greg Lewicki And Associates

Oldcastle SW Group dba. United Companies
Craig Ranch Pit
DRMS Annual Report Map