



STATE OF
COLORADO

Ridley - DNR, Hunter <hunter.ridley@state.co.us>

BMP / Liner Update, Foidel Creek Mine

Kawcak, Miranda <MKawcak@peabodyenergy.com>

Wed, Sep 27, 2023 at
7:48 AM

To: "Ridley - DNR, Hunter" <hunter.ridley@state.co.us>

Hi Hunter,

The Spray company was here yesterday and got the building sealed up. See attached pictures. All the plumbing has been tied in on the outside of the building as well but I forgot to get a picture of that. I will send that to you later today!

Thanks

Miranda Kawcak, PE

Manager, Environmental

Peabody

Twentymile Coal, LLC | 29515 Routt County Rd #27 | Oak Creek, CO 80467

Office Phone: (970) 870-2718 | Cell: (970) 439-8273

mkawcak@peabodyenergy.com

[Quoted text hidden]

3 attachments




Image.jpeg
3935K



Image.jpeg
3742K




Image.jpeg
2976K



STATE OF
COLORADO

Ridley - DNR, Hunter <hunter.ridley@state.co.us>

BMP / Liner Update, Foidel Creek Mine

Kawcak, Miranda <MKawcak@peabodyenergy.com>

Fri, Sep 29, 2023 at
1:54 PM

To: "Ridley - DNR, Hunter" <hunter.ridley@state.co.us>

Hi Hunter!

Sorry!, I totally spaced sending the rest of these pictures to you! Attached are the remaining pictures from around the stoker building. Pictures show the plumbing on the outside of the building, the silt fence that was fixed and for the south west corner we used a synthetic wattle to hold coal fines back from going over the wall. Please let me know if you need anything else!

[Quoted text hidden]

3 attachments



processed-2EC0CBBE-6319-49E4-A3E3-
4BD7717338DD-67623FC7-7FC3-4D9F-9A76-
7361B378F800.jpeg
5172K



**processed-AC83CA77-8D73-4348-8E8C-C25EFFF4DAB3-7BB4AC41-EABC-4980-BB1A-2314B6BF6772.
jpeg
6439K**



**processed-F6D75242-7408-4BCC-8ADB-F131FECB5577-39957EBC-DBC5-4F99-8065-8D0C3B579843.
jpeg
6201K**











