



STATE OF
COLORADO

Cazier - DNR, Tim <tim.cazier@state.co.us>

Gisenti Farms Gravel Pit

1 message

Andre Laroche <Andre_Laroche@transitmix.com>

Fri, Sep 20, 2013 at 7:21 AM

To: "Cazier, Tim (Tim.Cazier@state.co.us)" <Tim.Cazier@state.co.us>

Cc: Mike Morgan <Mike_Morgan@transitmix.com>, Chris Usry <Chris_Usry@transitmix.com>, John Crowley <John_Crowley@transitmix.com>

Hello Tim:

Yesterday I spoke to you regarding the Upset we recently had at the Grisenti Farms Gravel Pit (DRMS Permit #M-2001-005). Attached please find the notification I submitted to the State's Water Quality Control Division regarding the Upset.

Please do not hesitate to contact me if you have any questions.

Regards,

Andre Laroche | Permit Specialist

Transit Mix Concrete Co. | 719-491-0288 cell



Gisenti_Breach_WQCD_091713.pdf

355K

FILE COPY

TRANSIT MIX AGGREGATES

CASTLE AGGREGATES

TRANSIT MIX OF PUEBLO AGGREGATES

DANIELS SAND

September 17, 2013

RECEIVED

SEP 18 2013

BY *Willie Delgado*
CDPHE MAIL ROOM

Water Quality Protection Section – Industrial Compliance Program
Water Quality Control Division
Colorado Department of Public Health and Environment
WQCD-WQP-B2
4300 Cherry Creek Drive South
Denver, CO 80246-1530

RE: Permit Number COG-500401, September 12, 2013, Upset Notification

Dear Sir or Madam:

The purpose of this letter is to report an Upset at our Grisenti Farms Pit (Permit #COG-500401).

Sometime during the evening hours of September 11, 2013, and/or early morning hours of September 12 the Arkansas River breached its bank approximately 500 feet southwest of Outfall 002A. Breached water entered the pit from the southwest dewatering trench causing the pit to flood. We are in the process of pumping the water to the Arkansas River via Outfall 002A and this should be completed no later than Friday, September 20, 2013.


Also during the same time period Brush Hollow Creek backed into the pit's fresh water pond, which is connected to Outfall 001A. Outfall 001A is not currently in use. When Brush Hollow Creek recedes, so will the pond inlet to Outfall 001A. The fresh water pond is regulated by the Division of Water Resources and accounting for this pond is monitored by third party water engineers hired by Transit Mix Concrete Co. (aka Castle Concrete Co. and Transit Mix of Pueblo).

Andre Laroche, Transit Mix Permit Specialist, inspected the Grisenti site on September 12, 2013. Andre reported there was no petroleum sheen observed on water surface areas in the pit, fresh water pond or Outfall 001A. All petroleum based products are stored inside and the bulk diesel storage AST is housed in a covered concrete containment area. After business hours equipment is removed from the pit area. There was no damage to the Arkansas River bank where the breach occurred.

Andre left a phone message for Kenan Diker, CDPHE, on September 12, 2013, to report the Upset. They spoke the following day regarding this incident.

If you have questions or concerns, please feel free to contact Andre Laroche 719-491-0288 cell, andre_laroche@transitmix.com.

Sincerely,



Jerald Schnabel, President

CASTLE
DANIELS
TMP

P.O. Box 2379
P.O. Box 2379
P.O. Box 857

Colorado Springs, CO 80901
Colorado Springs, CO 80901
Pueblo, CO 81002

Phone: (719) 598-0215
Phone: (719) 392-8018
Phone: (719) 561-8350

FAX (719) 598-3053
FAX (719) 598-3053
FAX (719) 566-0231