

STATE OF COLORADO

DIVISION OF RECLAMATION, MINING AND SAFETY

Department of Natural Resources

1313 Sherman St., Room 215

Denver, Colorado 80203

Phone: (303) 866-3567

FAX: (303) 832-8106



September 25, 2013

Julie Mikulas
Martin Marietta Materials, Inc. - Rocky Mountain Division
1800 N Taft Hill Road
Fort Collins, CO 80521

John W. Hickenlooper
Governor

Mike King
Executive Director

Loretta Piñeda
Director

**Re: Cortner Pit, Permit No. M-1986-159,
Corrective Action Adequacy**

Dear Ms. Mikulas:

On September 25, 2013, the Division of Reclamation, Mining and Safety (DRMS) received your letter providing photographic documentation that the required permit sign has been posted. The DRMS considers the following Corrective Action to be resolved:

INSPECTION TOPIC: Signs & Markers

PROBLEM/POSSIBLE VIOLATION: Problem: The mine identification sign posted at the entrance of the mine site does not include the permit number. This is a problem for failure to post a mine identification sign as required by Section 3.1.12(1) of the rule.

CORRECTIVE ACTIONS: The operator shall, at the entrance of the mine site, post a sign which shall be clearly visible from the access road with the following: the name of the operator, a statement that a reclamation permit for the operation has been issued by the Colorado Mined Land Reclamation Board; and the permit number. The operator shall submit photo documentation that a proper sign has been posted by the corrective action date.

CORRECTIVE ACTION DUE DATE: 9/30/13

RESOLUTION DATE: 9/25/13

If you have any questions, please contact me at (303)866-3567, ext. 8169

Sincerely,

A handwritten signature in blue ink, appearing to read "Timothy A. Cazier".

Timothy A. Cazier, P.E.
Environmental Protection Specialist

cc: Tom Kaldenbach, DRMS
DRMS file