

Wildcat Mining Corporation

3926 North State Hwy 67
Sedalia, Colorado 80135
303.832.7664

DMC

October 31, 2013

Department of Natural Resources
Division of Reclamation, Mining and Safety
1313 Sherman Street
Denver, Colorado 80102

Re: Wildcat Mining Corporation-2013 Annual Report

To Whom it May Concern

Please find enclosed Wildcat Mining Corporation's 2012-13 annual report. The report includes the completed forms plus a CD containing water quality data and supporting maps.

If there are any questions or comments please call me at the above number or my cell phone which is 720.641.2534.

Sincerely,


George M.L. Robinson
President

georgerobinson@r2incorporated.com

Permit No. M-1981-185

RECEIVED

NOV 12 2013

DIVISION OF RECLAMATION
MINING AND SAFETY

REC
NOV 12 2013
DIVISION OF
MINING

STATE OF COLORADO

DIVISION OF RECLAMATION, MINING AND SAFETY
Department of Natural Resources

1313 Sherman St., Room 215
Denver, Colorado 80203
Phone: (303) 866-3567
FAX: (303) 832-8106



August 1, 2013

George M.L. Robinson
Wildcat Mining Corporation
3926 North State Highway 67
Sedalia, Colorado 80135

John W. Hickenlooper
Governor

Mike King
Executive Director

Loretta E. Pineda
Director

May Day Idaho Mine Complex, Permit M-1981-185, Annual Fee Invoice and Report Request

PLEASE READ CAREFULLY – ACTION REQUIRED

Please attach your COMPLETED written Annual Report and Annual Report Map to this form

Under the terms of your NOI or Reclamation Permit and Colorado Statutes, you must submit Annual Fees and Annual Reports (including a map). You must pay the Annual Fee and submit an Annual Report each year until reclamation responsibility release is granted. The Annual Fee is not a renewal fee. The Fee and Report are for LAST YEAR'S mining and reclamation season, and MUST be paid even if your operation was inactive.

The Annual Report and Fee requirement will be considered submitted when we have received the following components:

1. **APPROPRIATE ANNUAL FEE**
2. **COMPLETED ANNUAL REPORT**
3. **ASSOCIATED MAP as required by rule**

If you have requested reclamation responsibility release from the Division of Reclamation, Mining and Safety (the "Division") but your permit is not released by the anniversary date listed below, the Annual Fee MUST be paid. If the permit is released before the anniversary date, then by Statute, it is not necessary to pay an Annual Fee or submit an Annual Report for that year.

Division records indicate the \$1,150.00 fee is due for the following:

Permit:	M-1981-185
Operation Name:	May Day Idaho Mine Complex
Anniversary Date:	September 5, 2013
Total Fee Due:	\$1,150.00 (Due on or before your Anniversary Date)

Return the enclosed Annual Report FORM, a MAP, and a CHECK or MONEY ORDER made payable to: Division of Reclamation, Mining and Safety, 1313 Sherman St., Room 215, Denver, CO 80203. If your records indicate these documents and fees have already been submitted, please notify the Division.

If you have additional comments and/or information that should be provided to the Division, please provide it below or attach it to this form along with your written report and map. Annual Report instructions are enclosed. If you have any questions, please feel free to contact Jim Dupler (303)866-3567 x8119 or Christine Brookshire (303)866-3567 x8132. Thank you for your cooperation in this matter.

IF THE ANNUAL FEE SUBMITTALS ARE NOT RECEIVED ON OR BEFORE YOUR ANNIVERSARY DATE, THE ENFORCEMENT PROCESS WILL AUTOMATICALLY BE INITIATED. ENFORCEMENT ACTIONS MAY RESULT IN CIVIL PENALTIES AND/OR REVOCATION OF YOUR PERMIT.

112d-1 Annual Report

Permittee Name:	Wildcat Mining Corporation	Permit Number:	M-1981-185
Operation Name:	May Day Idaho Mine Complex	County:	La Plata
Annual Fee Due:	\$1,150.00	Anniversary Date:	September 5, 2013
Permit Acreage:	274.70	Current Bond Amt:	\$204,562.00

According to C.R.S. 34-32.5-116 or 34-32-116, each year, on the anniversary date of the permit, an operator shall submit the Annual Fee, an Annual Report and Map showing the extent of current disturbances to affected land, required monitoring information, reclamation accomplished to date and during the preceding year, any new disturbance that is anticipated to occur during the upcoming year, any reclamation that will be performed during the upcoming year, the dates for the beginning of active operations, and the date active operations ceased for the year.

Information contained in this report will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action.

1. Is the site identification sign posted in accordance with Rule 3.1.12(1). YES NO
2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). YES NO
3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? YES NO
If "YES," please note time limits related to completion of reclamation, Rule 3.1.3.
4. What was the date of last excavation, processing or hauling activity at the mine? Portal Repair-June-2013
5. Does the mine operate more than 180 days per year (In development mode) YES NO
If "NO", please review Rule 1.13 to assure that your mine is in compliance.
6. Has this mine been granted: YES NO
a) approval of TEMPORARY CESSATION Status? YES NO
b) approval for INTERMITTENT OPERATION?
7. Number of acres currently affected (mining + incomplete and or unreleased reclamation). < 20 acres
8. Number of acres that were newly affected during the current report year. < 1 acre
9. Number of acres that were reclaimed during the current report year. < 1 acre
10. Estimated new acreage to be affected in the next report year. < 5 acres
11. Estimated acres to be reclaimed in the next report year. 2-3 acres

12. **Total acres in various stages of reclamation, since permitted mining activities began:**

Total acres backfilled:	none	Total acres seeded w/ approved mix:	< 1 acre	Total acres w/topsoil replaced:	< 1 acre	Total acres mulched w/ approved mulch:	< 1 acre
Total acres graded:	None	Total acres fertilized w/ apvd fertilizer:	None	Topsoil replacement depth (in.):	1-4 inches	Mulch application rate (tons):	2 tons/acre
Seed application method:	Broadcast	Fertilizer application method:	Not Applicable	Mulch application method:	Manual-tacked in places		

13. Is weed control being conducted in accordance with an approved Weed Control Plan? **YES** NO N/A
If "YES", indicate the weed species, control area, control type, application rate and treatment date on the report map.
14. Is adequate topsoil reserved for reclamation, based on your approved permit? YES NO **N/A**
If "NO", please explain: (NO NEW DISTURBANCE)
15. Is the reserved topsoil vegetated/stabilized in accordance with Rule 3.1.9(1)? YES NO **N/A**
If "NO" please explain: (NO NEW DISTURBANCE)
16. If mining has exposed groundwater, is the site in compliance with the approved mining plan and Office of the State Engineer (Well Permit, S.W.S.P., and/or Permanent Augmentation Plan)? **YES** NO N/A
17. Are all hazardous materials stored within approved spill containment structures? YES NO **N/A**
18. Is your financial warranty value sufficient to cover the cost to complete reclamation? **YES** NO N/A
19. Is your basis for legal right to enter still valid? **YES** NO
20. Does your permit require you to submit monitoring information annually? **YES** NO N/A
If "Yes", please attach the required monitoring results to this Annual Report.
21. As required by Colorado Mined Land Reclamation Act and/or Colorado Land Reclamation Act for the Extraction of Construction Materials (C.R.S. 34-32-116 or 34-32.5-116), attach a map to this report that accurately depicts the permit boundary, current affected area boundary and location of the acreages specified in items 7- 12 and 14.
UPDATED MAP ATTACHED: **FIGURE 1**

Division records indicate the following permittee contact information. If this information is not current, please type or print **current** contact information:

Permittee Contact:		George M.L. Robinson
Permittee Company:	Wildcat Mining Corporation	
Address:		3926 North State Hwy 67 Sedalia, Colorado 80135
Phone Number:		303.832.7664
Fax Number:		303.832.7469
Email Address:		gmlrob@gmail.com

I, the undersigned, hereby state that the information provided in this report is true and accurate, and that site operations are being conducted in accordance with the Division approved mining and reclamation plans.


Signature of Permittee, Corporate Officer, Owner, or Documented Designee

10.31.2013


Date

WILDCAT MINING CORPORATION LOCATED IN SECTION 21 AND SECTION 28 T. 36 N., R. 11 W., N.M.P.M. LA PLATA COUNTY, STATE OF COLORADO



Description of Symbols

- Access Road
- Private Access Subject to Obtaining USFS Special Use Permit Approval
- USFS - Special Use Permit - Access Permit
- Proposed Utility
- Idaho Spring
- Upper Deadwood Gulch - 311 Acres (Above Chief Redemption)
- Mid a Deadwood Gulch - 77 Acres (185 acres above No. 2 Channel Redemption)
- Lower Deadwood Gulch - 12 Acres
- Mayday No. 1 - Above Bench - 2.4 Acres
- Mayday No. 1 Bench - 0.5 Acres
- Idaho Augmentation Pond Diversion - 1 Acre
- Access Road Ditch - 3.5 Acres
- Culvert #1 - 3.5 Acres (New Access Road)
- Culvert #2 - 308 Acres (Mayday No. 2 Bench)
- Culvert #3 - 1.5 Acres (Above Mayday No. 1 Peria)
- CR Channel Redirection
- CUL Culvert
- DB Debris Basin
- RR Rip Rap
- Affected Area
- Permit Boundary
- Base of Operation
- Drainage Basin Destination
- Water Storage
- Land Disposal Area
- Maintenance and Core Storage
- Snow Storage Area
- Surface Ore Stockpile
- Surface Water Diversion
- To be Reclaimed
- Construction Lay Down Area



STORMWATER MANAGEMENT STRUCTURES

WILDCAT MINING CORPORATION

8538 OLD PINEWAY

BREKENDOW VILLAGE, CO 80111

DESIGNED BY: S&B

ISSUANCE DATE: 8-13-2011

FIGURE SWMP-1

8 squared Inc.

11700 LINDSEY LANE, SUITE 100

DENVER, COLORADO 80231

TEL: (303) 755-1100

FAX: (303) 755-1101

WWW.8SQUARED.COM

M/1981-185