

COLORADO DIVISION OF RECLAMATION, MINING AND SAFETY MINERALS PROGRAM INSPECTION REPORT

PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME:	MINE/PROSPECTING ID#:	MINERAL:	COUNTY:
Spring Creek Pit	M-1994-097	Sand and gravel	Montrose
INSPECTION TYPE:	INSPECTOR(S):	INSP. DATE:	INSP. TIME:
Monitoring	Dustin M. Czapla	April 17, 2014	14:00
OPERATOR:	OPERATOR REPRESENTATIVE:	TYPE OF OPERATION: 112c - Construction Regular Operation	
Oldcastle SW Group dba United Companies	Tom Davis		
of Mesa County			S - F

REASON FOR INSPECTION:	BOND CALCULATION TYPE:	BOND AMOUNT:
Normal I&E Program	Complete Bond	\$92,230.00
DATE OF COMPLAINT:	POST INSP. CONTACTS:	JOINT INSP. AGENCY:
NA	None	None
WEATHER:	INSPECTOR'S SIGNATURE:	SIGNATURE DATE:
Clear		April 24, 2014

The following inspection topics were identified as having Problems or Possible Violations. OPERATORS SHOULD READ THE FOLLOWING PAGES CAREFULLY IN ORDER TO ASSURE COMPLIANCE WITH THE TERMS OF THE PERMIT AND APPLICABLE RULES AND REGULATIONS. If a Possible Violation is indicated, you will be notified under separate cover as to when the Mined Land Reclamation Board will consider possible enforcement action.

INSPECTION TOPIC: Financial Warranty

PROBLEM/POSSIBLE VIOLATION: Problem: The financial warranty is not adequate to reclaim the site in accordance with the approved reclamation plan. This is a failure to maintain the proper financial warranty amount to complete reclamation of the affected lands pursuant to C.R.S. 34-32.5-117(4)(b) of the Act.

CORRECTIVE ACTIONS: The operator shall submit adequate financial warranty, as determined by the Division. The Division will be sending a separate surety increase notice to the operator regarding the increase of the financial warranty. The operator will have 60 days from the date on the surety increase notice to post the additional financial warranty.

CORRECTIVE ACTION DUE DATE: 6/24/14

OBSERVATIONS

This inspection was conducted as part of the Division of Reclamation, Mining and Safety's (Division) normal monitoring program. Tom Davis, representing the Operator, was present during this inspection. Photographs are included with this report in order to illustrate some of the conditions observed.

The Spring Creek Pit is located approximately four miles northwest of Montrose and accessed from La Salle Road. The site is a 112c operation that includes a total of 200.29 permitted acres. The Division currently holds a financial warranty amount of \$92,230.00 for this site. The current financial warranty is based on a maximum disturbance of twenty acres. There are approximately fifty-five acres currently disturbed. Therefore, the Division has reviewed the reclamation costs, in order to ensure the financial warranty reflects the actual current cost of fulfilling the requirements of the Reclamation Plan, and determined that the current financial warranty amount is insufficient. The Operator will be notified under separate cover of a financial warranty increase.

Adequate mine identification signage was noted at the entrance to the site.

The affected area was marked by fencing and posts that were clearly visible and adequate to delineate the affected area boundary.


The pit has been excavated to a depth of approximately twenty feet. The pit slopes on the east and west sides were approximately 1H:1V. The south slope was graded at approximately 2H:1V and the north slope approximately 3H:1V. Topsoil is stockpiled around the perimeter of the pit. Materials stockpiles are located throughout the pit floor. Wash ponds are located in the south part of the pit. Several piles of waste asphalt were located in the north part of the pit.

The site is well maintained and no other problems or violations were noted during this inspection.

Responses to this inspection report should be directed to Dustin Czapla at the Division of Reclamation, Mining and Safety, Grand Junction Field Office, 101 South 3rd Street, Room 301, Grand Junction, Colorado 81501, phone number (970) 243-6299.

PHOTOGRAPHS

















GENERAL INSPECTION TOPICS

The following list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each

(AR) RECORDS <u>Y</u>	(FN) FINANCIAL WARRANTY PB	(RD) ROADS <u>Y</u>
(HB) HYDROLOGIC BALANCE <u>N</u>	(BG) BACKFILL & GRADING <u>Y</u>	(EX) EXPLOSIVES <u>NA</u>
(PW) PROCESSING WASTE/TAILING N	(SF) PROCESSING FACILITIES \underline{Y}	(TS) TOPSOIL <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- Y	(FW) FISH & WILDLIFE <u>N</u>	(RV) REVEGETATION N
(SM) SIGNS AND MARKERS <u>Y</u>	(SP) STORM WATER MGT PLAN NA	(SB) COMPLETE INSP NA
(ES) OVERBURDEN/DEV. WASTE NA	(SC) EROSION/SEDIMENTATION \underline{Y}	(RS) RECL PLAN/COMP N
(AT) ACID OR TOXIC MATERIALS Y	(OD) OFF-SITE DAMAGE <u>N</u>	(ST) STIPULATIONS <u>NA</u>

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

Inspection Contact Address

Jason Burkey United Companies of Mesa County P.O. Box 3609 Grand Junction, CO 81502