

COLORADO DIVISION OF RECLAMATION, MINING AND SAFETY MINERALS PROGRAM INSPECTION REPORT

PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME:	MINE/PROSPECTING ID#:	MINERAL:	COUNTY:
Wyman Pit	M-1983-037	Sand and gravel	Routt
INSPECTION TYPE:	INSPECTOR(S):	INSP. DATE:	INSP. TIME:
Monitoring	Dustin M. Czapla	May 6, 2014	10:45
OPERATOR:	OPERATOR REPRESENTATIVE:	TYPE OF OPERATION:	
Louis M. Wyman	None	110c - Construction Limited Impact	

REASON FOR INSPECTION:	BOND CALCULATION TYPE:	BOND AMOUNT:
Normal I&E Program	None	\$9,674.00
DATE OF COMPLAINT:	POST INSP. CONTACTS:	JOINT INSP. AGENCY:
NA	Nope	None
WEATHER:	ENSPECTOR'S SIGNATURE:	SIGNATURE DATE:
Clear		May 13, 2014

The following inspection topics were identified as having Problems or Possible Violations. OPERATORS SHOULD READ THE FOLLOWING PAGES CAREFULLY IN ORDER TO ASSURE COMPLIANCE WITH THE TERMS OF THE PERMIT AND APPLICABLE RULES AND REGULATIONS. If a Possible Violation is indicated, you will be notified under separate cover as to when the Mined Land Reclamation Board will consider possible enforcement action.

INSPECTION TOPIC: Availability Of Records

PROBLEM/POSSIBLE VIOLATION: Problem: Rule 1.13.5 states, if an Operator temporarily ceases production of the mining operation for one hundred eighty (180) days or more, the Operator must file a Notice of Temporary Cessation in writing to the Office.

CORRECTIVE ACTIONS: The Division recommends the Operator file for Temporary Cessation. The start date of the initial 5 year Temporary Cessation period is retroactive to the last date the pit was active. If that date is more than 5 years ago, the operator is required ask the Board for a 5 year extension to the Temporary Cessation period (per rule 1.13.5 (3) and 1.13.8 (b) or begin reclamation.

CORRECTIVE ACTION DUE DATE: 6/13/14

PERMIT #: M-1983-037 INSPECTOR'S INITIALS: DMC INSPECTION DATE: May 6, 2014

OBSERVATIONS

This inspection was conducted as part of the Division of Reclamation, Mining and Safety's (Division) normal monitoring program. A representative for the Operator was not present during this inspection. Photographs are included with this report in order to illustrate some of the conditions observed.

The Wyman Pit is located approximately twelve miles east of Hamilton and accessed from CR67. The site is a 110c operation that includes a total of 9.5 permitted acres. The Division currently holds a financial warranty amount of \$9,674.00 for this site. The Division has reviewed the reclamation costs and determined that the current financial warranty amount is adequate.

Adequate mine identification signage was noted at the entrance to the site.

The affected area was marked by t-posts that were clearly visible and adequate to delineate the affected area boundary.

Conditions at the site appeared unchanged from the Division's 2010 inspection. The Operator's annual report states that the last mining activity occurred in 2009. Per Rule 1.13.5, if an Operator temporarily ceases production of the mining operation for one hundred eighty (180) days or more, the Operator must file a Notice of Temporary Cessation in writing to the Office. The Operator has not submitted their notice of TC. This has been noted as a problem.

No other problems or violations were noted during this inspection.

Responses to this inspection report should be directed to Dustin Czapla at the Division of Reclamation, Mining and Safety, Grand Junction Field Office, 101 South 3rd Street, Room 301, Grand Junction, Colorado 81501, phone number (970) 243-6299.


PHOTOGRAPHS













PERMIT #: M-1983-037 INSPECTOR'S INITIALS: DMC INSPECTION DATE: May 6, 2014

GENERAL INSPECTION TOPICS

The following list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each

(AR) RECORDS <u>PB</u>	(FN) FINANCIAL WARRANTY <u>Y</u>	(RD) ROADS <u>NA</u>
(HB) HYDROLOGIC BALANCE <u>Y</u>	(BG) BACKFILL & GRADING <u>Y</u>	(EX) EXPLOSIVES <u>NA</u>
(PW) PROCESSING WASTE/TAILING NA	(SF) PROCESSING FACILITIES NA	(TS) TOPSOIL <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE \underline{Y}	(RV) REVEGETATION N
(SM) SIGNS AND MARKERS <u>Y</u>	(SP) STORM WATER MGT PLAN NA	(SB) COMPLETE INSP NA
(ES) OVERBURDEN/DEV. WASTE NA	(SC) EROSION/SEDIMENTATION \underline{Y}	(RS) RECL PLAN/COMP N
(AT) ACID OR TOXIC MATERIALS NA	(OD) OFF-SITE DAMAGE <u>NA</u>	(ST) STIPULATIONS <u>NA</u>

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

Inspection Contact Address

Louis M. Wyman P.O. Box 278 Craig, CO 81626

Enclosure: TC Notice Form

CC: