

ERK
RECEIVED

NOV 13 2014

Page 2 of 3

**DIVISION OF RECLAMATION,
MINING & SAFETY-MINERALS
FEE REPORT MAP FW**

110c Annual Report

Permittee Name:	Byron J. & LaLani R. Weathers	Permit Number:	M-1999-089
Operation Name:	Weathers Mine #1	County:	Yuma
Annual Fee Due:	\$323.00	Anniversary Date:	November 18, 2014
Permit Acreage:	9.90	Current Bond Amt:	\$14,260.00 \$22,000.00

According to C.R.S. 34-32.5-116 or 34-32-116, each year, on the anniversary date of the permit, an operator shall submit the Annual Fee, an Annual Report and Map showing the extent of current disturbances to affected land, required monitoring information, reclamation accomplished to date and during the preceding year, any new disturbance that is anticipated to occur during the upcoming year, any reclamation that will be performed during the upcoming year, the dates for the beginning of active operations, and the date active operations ceased for the year.

Information contained in this report will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action.

1. Is the site identification sign posted in accordance with Rule 3.1.12(1). YES ~~XX~~
2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). YES ~~XX~~
3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? ~~YES~~ NO
If "YES," please note time limits related to completion of reclamation, Rule 3.1.3.
4. What was the date of last excavation, processing or hauling activity at the mine? 10-25-2014
5. Does the mine operate more than 180 days per year? YES ~~XX~~
If "NO", please review Rule 1.13 to assure that your mine is in compliance.
6. Has this mine been granted: a) approval of TEMPORARY CESSATION Status? ~~YES~~ NO
b) approval for INTERMITTENT OPERATION? YES ~~XX~~
7. Number of acres currently affected (mining + incomplete and or unreleased reclamation). 7.07
8. Number of acres that were newly affected during the current report year. 0
9. Number of acres that were reclaimed during the current report year. 0.16
10. Estimated new acreage to be affected in the next report year. 0.50
11. Estimated acres to be reclaimed in the next report year. 0
12. Total acres in various stages of reclamation, since permitted mining activities began:

Total acres backfilled:	0	Total acres seeded w/ approved mix:	0	Total acres w/topsoil replaced:	0	Total acres mulched w/ approved mulch:	0
Total acres graded:	0.16	Total acres fertilized w/ apvd fertilizer:	NA	Topsoil replacement depth (in.):	0	Mulch application rate (tons/ac):	0
Seed application method:	NA	Fertilizer application method:	NA	Mulch application method:	NA		

13. Is weed control being conducted in accordance with an approved Weed Control Plan? ~~YES~~ ~~NO~~ N/A
If "YES", indicate the weed species, control area, control type, application rate and treatment date on the report map.
14. Is adequate topsoil reserved for reclamation, based on your approved permit? YES ~~NO~~ ~~N/A~~
If "NO", please explain:
15. Is the reserved topsoil vegetated/stabilized in accordance with Rule 3.1.9(1)? YES ~~NO~~ ~~N/A~~
If "NO" please explain:
16. If mining has exposed groundwater, is the site in compliance with the approved mining plan and Office of the State Engineer (Well Permit, S.W.S.P., and/or Permanent Augmentation Plan)? ~~YES~~ ~~NO~~ N/A
17. Are all hazardous materials stored within approved spill containment structures? ~~YES~~ ~~NO~~ N/A
18. Is your financial warranty value sufficient to cover the cost to complete reclamation? YES ~~NO~~ ~~N/A~~
19. Is your basis for legal right to enter still valid? YES ~~NO~~
20. Does your permit require you to submit monitoring information annually? ~~YES~~ NO ~~N/A~~
If "Yes", please attach the required monitoring results to this Annual Report.
21. As required by Colorado Mined Land Reclamation Act and/or Colorado Land Reclamation Act for the Extraction of Construction Materials (C.R.S. 34-32-116 or 34-32.5-116), attach a map to this report that accurately depicts the permit boundary, current affected area boundary and location of the acreages specified in items 7- 12 and 14.
UPDATED MAP ATTACHED: Yes

Division records indicate the following permittee contact information. If this information is not current, please type or print current contact information:

Permittee Contact:	Byron Weathers	
Permittee Company:	Byron J. & LaLani R. Weathers	
Address:	11955 CR 37 Yuma, CO 80759	Note: Additional information provided on attached page.
Phone Number:	(970) 848-2912	
Fax Number:		
Email Address:	CF.PR.email	byron@weathersfarms.net ✓

I, the undersigned, hereby state that the information provided in this report is true and accurate, and that site operations are being conducted in accordance with the Division approved mining and reclamation plans.


Signature of Permittee, Corporate Officer, Owner, or Documented Designee

11-9-14
Date

RECEIVED NOV 13 2014 DIVISION OF RECLAMATION MINING AND SAFETY BYRON & LALANI WEATHERS WEATHERS MINE #1 Permit # M-1999-089 ANNUAL REPORT - 2014



PART OF THE SW/4NE/4 AND SE/4NW/4 SECTION 9, TOWNSHIP 1 SOUTH, RANGE 48 WEST, 6th P.M., YUMA COUNTY, COLORADO	
PREPARED BY: <i>[Signature]</i> ENVIRONMENT, INC. ARVADA, CO 80003 PHONE: (303) 427-1271	DATE: _____ REVISION: _____ BY: _____

Notes:

No new mining took place this year. Material was removed from stockpiles this year. When more material is needed, mining will resume in the stripped and partially mined area shown on the map.

A minor Technical Revision was approved this year to allow disturbance on the entire 9.99 acres and the Division reevaluated the bond and increased to \$22,000.00. The increase was filed on 8/21/2014

We estimate there is 53,000 cu-yds of topsoil/overburden is stockpiled on the mine at this time. No new exterior slopes were mine so no sloping is required. The maximum amount of disturbance allowed at the mine is 9.99 acres.

Approximately 0.16 acres or 160 linear feet of sloping is completed on the west side of the mine. No other reclamation is required at this time.

Division of Reclamation, Mining, and Safety

Fee Receipt for M1999089

Byron J. & LaLani R. Weathers

000000000

Receipt #: 18532

Date: 11/13/2014

Permit: M1999089

Payment Method	Revenue Code	Fee Description/Notes	Amount
4951 msr	4300-MAF0	Minerals Annual Fees M1999-089	\$323.00

Receipt Total:	\$323.00
----------------	----------