


Inspection



QATESTOCR



COLORADO

Division of Reclamation,
Mining and Safety

Department of Natural Resources
1313 Sherman Street, Room 215
Denver, Colorado 80203

December 5, 2014

Kym A. Schure
12826 CR 37
Sterling, CO 80751

Re: Dollerschell Pit; Permit No. M-1986-074; Receipt of Corrective Action Documentation

Mr. Schure:

On December 5, 2014, the Division of Reclamation, Mining and Safety (Division) received corrective action documentation for one of the Compliance Problems identified in the report for the Dollerschell Pit inspection conducted on October 6, 2014. The status of the corrective actions is as follows:

Compliance Problem #2: The affected area boundary markers are missing or incorrectly placed.
This problem has been resolved as a result of coordinates and photographs submitted to the Division showing that new markers have been placed, delineating the affected area boundary.

If you need additional information or have any questions, please contact me at Division of Reclamation, Mining and Safety, 1313 Sherman Street, Room 215, Denver, CO 80203, by telephone at **303-866-3567 x8132**, or by email at elliott.russell@state.co.us.

Sincerely,

Elliott R. Russell
Environmental Protection Specialist

cc: Tom Kaldenbach; DRMS

