



COLORADO

Division of Reclamation,
Mining and Safety

Department of Natural Resources

1313 Sherman Street, Room 215
Denver, Colorado 80203

December 19, 2014

Jason McGraw
General Shale Brick, Inc.
1845 W. Dartmouth Ave.
Denver, CO 80110

Re: Navajo Clay Pit, Permit No. M-1993-004, Documentation of Corrective Action(s) Received

Mr. McGraw:

The Division of Reclamation, Mining and Safety (Division) received your response on December 19, 2014 regarding the problem identified in the inspection conducted at the Navajo Clay Pit on August 12, 2014. The status of the Corrective Action associated with this problem is as follows:

Corrective Action #1: The Operator shall conduct a survey and replace the boundary markers in the correct locations around the area proposed to be disturbed for which a Financial Warranty has been posted. The Operator shall provide photo documentation to the Division that this has been done by the Corrective Action due date.

Status: The Operator submitted several photographs showing that boundary markers have been placed in their correct locations around the affected area. Therefore, this problem is considered abated.

If you have any questions, please contact me at the Division of Reclamation, Mining and Safety, 1313 Sherman Street, Room 215, Denver, CO 80203, by telephone at 303-866-3567, extension 8129, or by email at amy.eschberger@state.co.us.

Sincerely,

Amy Eschberger
Environmental Protection Specialist

CC: Tom Kaldenbach, DRMS

