

April 24, 2015

Bob Oswald Colorado Division of Reclamation, Mining, and Safety 691 CR 233, Suite A-2 Durango, CO 81301 PROBLEM CORRECTION (3/27/15 INSP. DATE)

## M-2012-032 Revenue Mine: Repair of Reagent Room Berm at Revenue Mine

Dear Bob:

Wally Erickson performed an inspection of the Revenue Mine on March 27, 2015 and identified that a permanent repair was needed to the concrete berm that is required as containment for the Reagent Room in the Filter Building. This berm has been fully repaired with concrete, as shown in the attached pictures. The work was completed by April 10, 2015.

I certify that the concrete berm was repaired to specifications which will prevent discharge of any liquid below the level of the berm. If there are any questions, please call me at 303-346-5196.



CC: John E. Trujillo Dianna Stoopnikoff Sincerely,

neg Lewicki

Greg Lewicki, Principal Engineer Greg Lewicki and Associates







