0

	Permit Number:	M-1978-314
	Permittee Name:	King Mountain Gravel, LLC
	<b>Operation Name:</b>	King Mountain Sand & Gravel
RECEIVED		Mine
NOV 2 7 2015	County:	Routt
DIVISION OF FRACE AMATION,	Anniversary Date:	November 22, 2015
MINING & SAFETY MINERALS FEE REPORT MAP	Current Bond Amt:	\$223,300.00
	Annual Fee Due:	\$791.00
(DRMS Office Use Only)	Permit Acreage:	341.00
	DRMS Specialist	ACY

According to C.R.S. 34-32.5-116 or 34-32-116, each year, on the anniversary date of the permit, an operator shall submit the Annual Fee, an Annual Report and Map showing the extent of current disturbances to affected land, required monitoring information, reclamation accomplished to date and during the preceding year, any new disturbance that is anticipated to occur during the upcoming year, any reclamation that will be performed during the upcoming year, the dates for the beginning of active operations, and the date active operations ceased for the year.

Information contained in this report will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action.

1.	Is the site identification sign posted in accordance with Rule 3.1.12(1)?	YES	NO
2.	Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2)?	YES	NO
3.	Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? If "YES," please note time limits related to completion of reclamation, Rule 3.1.3.	YES (	NO
4.	What was the date of last excavation, processing or hauling activity at the mine?	11-23-1	5
5.	Does the mine operate more than 180 days per year? If "NO", please review Rule 1.13 to assure that your mine is in compliance.	YES	NO
6.	Has this mine been granted: a) approval of TEMPORARY CESSATION Status? b) approval for INTERMITTENT OPERATION?	YES YES	NO
7.	Number of acres currently affected (mining + incomplete and or unreleased reclamation):	8.1	
8.	Number of acres that were newly affected during the current report year:	.05	
9.	Number of acres that were reclaimed during the current report year:	0	
10.	Estimated new acreage to be affected in the next report year:	.15	
11.	Estimated acres to be reclaimed in the next report year:	.5-1	

12. Total acres in various stages of reclamation, since permitted mining activities began:

Total acres backfilled:	D	Total acres seeded w/ approved mix:	Ö	Total acres w/topsoil replaced:	0	Total a mulche approv		D
Total acres graded:	,1-,5	Total acres fertilized w/ apvd fertilizer:	D	Topsoil replacement depth (in.):	Þ		application ons/ac):	D
Seed application method:	ΑŴ		ilizer ication nod:	AN	Mule appl meth	ication	A'N	

13. Is weed control being conducted in accordance with an approved Weed Control Plan? YES NO N/A If "YES", indicate the weed species, control area, control type, application rate and treatment date on the report map.

14. Is adequate topsoil reserved for reclamation, based on your approved permit? If "NO", please explain:	YBS NO	N/A
15. Is the reserved topsoil vegetated/stabilized in accordance with Rule 3.1.9(1)? If "NO" please explain:	YES NO	N/A

16. If mining has exposed groundwater, is the site in compliance with the approved mining plan and Office of the State Engineer (Well Permit, S.W.S.P., and/or Permanent Augmentation Plan)? YES NO (N/A)

17.	Are all hazardous materials stored within approved spill containment structures?	YES	NO	N/A
18.	Is your financial warranty value sufficient to cover the cost to complete reclamation?	(YES)	NO	N/A
1 <b>9</b> .	Is your basis for legal right to enter still valid?	VES	NO	
20.	Does your permit require you to submit monitoring information annually? If "Yes", please attach the required monitoring results to this Annual Report.	YES	NO	N/A

21. As required by Colorado Mined Land Reclamation Act and/or Colorado Land Reclamation Act for the Extraction of Construction Materials (C.R.S. 34-32-116 or 34-32.5-116), attach a map to this report that accurately depicts the permit boundary, current affected area boundary and location of the acreages specified in items 7-12 and 14. UPDATED

MAP ATTACHED:

Page 5 of 5 Division records indicate the following permittee contact information. If this information is not current, please type or print <u>current</u> contact information:

Permittee Contact:	Kirk J. Eberl	
Permittee Company:	King Mountain Gravel, LLC	
Address:	7276 W. Mansfield Ave. Lakewood, CO 80235	
Phone Number:	(303) 988-6286	
Fax Number:	(303) 986-2771	
Email Address:		

I, the undersigned, hereby state that the information provided in this report is true and accurate, and that site operations are being conducted in accordance with the Division approved mining and reclamation plans.

<u>11-23-15</u> Date

Signature of Permittee, Corporate Officer, Owner, or Documented Designee


M-AF-01



## RECEIVED

NOV 27 2015

DIVISION OF RECLAMATION MINING AND SAFETY



## Division of Reclamation, Mining, and Safety

## Fee Receipt for M1978314

King Mountain Gravel, LLC	Receipt #:	20638
•	Date:	11/27/2015
	Permit:	M1978314
0000000	00	

<b>Payment Method</b>	Revenue Code	Fee Description/Notes	Amount
1037 msr	4300-MAF0	Minerals Annual Fees	\$791.00
		M1978-314 paid by Frank I. Hewes	
	-	Receipt Total:	\$791.00