



COLORADO

Division of Reclamation,
Mining and Safety

Department of Natural Resources

1313 Sherman Street, Room 215
Denver, CO 80203

January 14, 2016

Ralph Martinez
Southway Construction Company Inc.
117 White Pine Drive
Alamosa, CO 81101

RE: Butcher Pit Pit; DRMS File No. M-1995-060; Receipt of Corrective Action
Documentation

Dear Mr. Martinez,

The Division received your above referenced response in regard to the Compliance Problem cited in the report of the inspection conducted on November 17, 2015. The status of the corrective action regarding the problem are as follows:

Compliance Problem 1: The affected area boundary markers are missing or incorrectly placed.

This problem is considered abated as a result of the Operator's submittal of documentation of the boundary markers replaced.

Compliance Problem 2: if an Operator temporarily ceases production of the mining operation for one hundred eighty (180) days or more, the Operator must file a Notice of Temporary Cessation in writing to the Office.

This problem is considered abated as a result of the Operator's statement that the last time material was hauled off site was October 2015.

If you have any questions, please contact me at (970)242.5025.

Sincerely,

Stephanie Mitchell
Environmental Protection Specialist

