

112c Annual Report

<p>RECEIVED</p> <p>JAN 26 2016</p> <p>DIVISION OF RECLAMATION, MINING & SAFETY-MINERALS</p> <p>FEE REPORT MAP PW</p> <p>(DRMS Office Use Only)</p>	Permit Number:	M-1985-210
	Permittee Name:	Rocky Road Investments
	Operation Name:	Rocky Road Quarry
	County:	Larimer
	Anniversary Date:	January 27, 2016
	Current Bond Amt:	\$57,224.56
	Annual Fee Due:	\$791.00
	Permit Acreage:	106.50
	DRMS Specialist	MAC

According to C.R.S. 34-32.5-116 or 34-32-116, each year, on the anniversary date of the permit, an operator shall submit the Annual Fee, an Annual Report and Map showing the extent of current disturbances to affected land, required monitoring information, reclamation accomplished to date and during the preceding year, any new disturbance that is anticipated to occur during the upcoming year, any reclamation that will be performed during the upcoming year, the dates for the beginning of active operations, and the date active operations ceased for the year.

Information contained in this report will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action.

1. Is the site identification sign posted in accordance with Rule 3.1.12(1)? ☒ YES ☐ NO
2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2)? ☒ YES ☐ NO
3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? ☐ YES ☒ NO
If "YES," please note time limits related to completion of reclamation, Rule 3.1.3.
4. What was the date of last excavation, processing or hauling activity at the mine? Current
5. Does the mine operate more than 180 days per year? ☒ YES ☐ NO
If "NO", please review Rule 1.13 to assure that your mine is in compliance.
6. Has this mine been granted: YES ☒ NO ☒
a) approval of TEMPORARY CESSATION Status?
b) approval for INTERMITTENT OPERATION?
7. Number of acres currently affected (mining + incomplete and or unreleased reclamation): 17.87
8. Number of acres that were newly affected during the current report year: None
9. Number of acres that were reclaimed during the current report year: None
10. Estimated new acreage to be affected in the next report year: None
11. Estimated acres to be reclaimed in the next report year: None

SCANNED

12. Total acres in various stages of reclamation, since permitted mining activities began:

Total acres backfilled: <i>NONE</i>	<i>NONE</i>	Total acres seeded w/ approved mix:	<i>NONE</i>	Total acres w/topsoil replaced:	<i>NONE</i>	Total acres mulched w/ approved mulch:	<i>NONE</i>
Total acres graded: <i>NONE</i>	<i>NONE</i>	Total acres fertilized w/ apvd fertilizer:	<i>NONE</i>	Topsoil replacement depth (in.):	<i>NONE</i>	Mulch application rate (tons/ac):	<i>NONE</i>
Seed application method:	<i>NONE</i>	Fertilizer application method:	<i>NONE</i>	Mulch application method:	<i>NONE</i>		


13. Is weed control being conducted in accordance with an approved Weed Control Plan? (YES) NO N/A
If "YES", indicate the weed species, control area, control type, application rate and treatment date on the report map.
Cockaburn
14. Is adequate topsoil reserved for reclamation, based on your approved permit? (YES) NO N/A
If "NO", please explain:
15. Is the reserved topsoil vegetated/stabilized in accordance with Rule 3.1.9(1)? (YES) NO N/A
If "NO" please explain:
16. If mining has exposed groundwater, is the site in compliance with the approved mining plan and Office of the State Engineer (Well Permit, S.W.S.P., and/or Permanent Augmentation Plan)? *Groundwater not exposed* (YES) NO N/A
17. Are all hazardous materials stored within approved spill containment structures? (YES) NO N/A
18. Is your financial warranty value sufficient to cover the cost to complete reclamation? (YES) NO N/A
19. Is your basis for legal right to enter still valid? (YES) NO
20. Does your permit require you to submit monitoring information annually? *Aerial Photo* (YES) NO N/A
If "Yes", please attach the required monitoring results to this Annual Report.
21. As required by Colorado Mined Land Reclamation Act and/or Colorado Land Reclamation Act for the Extraction of Construction Materials (C.R.S. 34-32-116 or 34-32.5-116), attach a map to this report that accurately depicts the permit boundary, current affected area boundary and location of the acreages specified in items 7- 12 and 14. UPDATED

MAP ATTACHED: Yes no changes from 2014 through 2015

Division records indicate the following permittee contact information. If this information is not current, please type or print **current** contact information:

Permittee Contact:	Douglas J. Bachli	
Permittee Company:	Rocky Road Investments	
Address:	P.O. Box 63 Masonville, CO 80541	
Phone Number:	(970) 203-1072	
Fax Number:	(970) 203-0130	
Email Address:	Sale@coloradoflagstone.com	

I, the undersigned, hereby state that the information provided in this report is true and accurate, and that site operations are being conducted in accordance with the Division approved mining and reclamation plans.



Signature of Permittee, Corporate Officer, Owner, or Documented Designee

Jan 25, 2016
Date

LG

MAP

~~MAP~~

~~MAP~~

m. 1985. 210

ROCKY ROAD INVESTMENT
P.O. BOX 63
MASONVILLE, COLORADO 80541
970-203-1072

January 25, 2016

Division of Minerals and Geology
1313 Sherman St., Room 215
Denver, Colorado 80203

Subject; Annual Report – Rocky Road Investment, Inc. – DMG Permit M85-210

Division of Minerals

All quarry activity during the year 2015 occurred in the existing Affected Land-6. No area was increased in size during 2015. All extraction of material occurred within the previous affected areas.

Areas (AL-1), (AL-2), (AL-3), (AL-4), (AL-5) are primarily used for storage and processing of material.

In the spring of 2015 we seeded berms that needed more shrubs.

Any questions call 303-589-5213

Sincerely

A handwritten signature in cursive script, reading "Douglas J. Bachli". The signature is written in dark ink and is positioned above the printed name.

Douglas J. Bachli



COLORADO

Division of Reclamation,
Mining and Safety

Department of Natural Resources

1313 Sherman St. Room 215
Denver, CO 80203

November 20, 2015

Douglas J. Bachli
Rocky Road Investments
P.O. Box 63
Masonville, CO 80541

Rocky Road Quarry, Permit M-1985-210, Annual Fee Invoice and Report Request

PLEASE READ CAREFULLY – ACTION REQUIRED

Please attach your COMPLETED written Annual Report and Annual Report Map to this form

Under the terms of your Reclamation Permit and Colorado Statutes, you must submit an Annual Fee and Annual Report (including a map). You must pay the Annual Fee and submit an Annual Report each year until reclamation responsibility release is granted. The Annual Fee is not a renewal fee. The Fee and Report are for LAST YEAR'S mining and reclamation season, and MUST be paid even if your operation was inactive.

The Annual Report and Fee requirement will be considered submitted when we have received the following components:

1. **APPROPRIATE ANNUAL FEE**
2. **COMPLETED ANNUAL REPORT**
3. **ASSOCIATED MAP as required by rule**

If you have requested reclamation responsibility release from the Division of Reclamation, Mining and Safety ("Division") but your permit is not released by the anniversary date listed below, the Annual Fee MUST be paid. If the permit is released before the anniversary date, then by Statute, it is not necessary to pay an Annual Fee or submit an Annual Report for that year.

Division records indicate the \$791.00 fee is due for the following:

Permit: M-1985-210
Operation Name: Rocky Road Quarry
Anniversary Date: January 27, 2016
Total Fee Due: \$791.00 (Due on or before your Anniversary Date)

Return the enclosed Annual Report FORM, a MAP, and a CHECK or MONEY ORDER made payable to: Division of Reclamation, Mining and Safety, 1313 Sherman St., Room 215, Denver, CO 80203. If your records indicate these documents and fees have already been submitted, please notify the Division.



If you have additional comments and/or information that should be provided to the Division, please provide it below or attach it to this form along with your written report and map. Annual Report instructions are enclosed. If you have any questions, please feel free to contact Scottie Tate ((303) 866-3567 ext 8166) or Michelle Ramirez ((303) 866-3567 ext 8114). Thank you for your cooperation in this matter.

IF THE ANNUAL FEE SUBMITTALS ARE NOT RECEIVED ON OR BEFORE YOUR ANNIVERSARY DATE, THE ENFORCEMENT PROCESS WILL AUTOMATICALLY BE INITIATED. ENFORCEMENT ACTIONS MAY RESULT IN CIVIL PENALTIES AND/OR REVOCATION OF YOUR PERMIT.

Division of Reclamation, Mining, and Safety

Fee Receipt for M1985210

Rocky Road Investments

000000000

Receipt #: 20884

Date: 01/27/2016

Permit: M1985210

Payment Method	Revenue Code	Fee Description/Notes	Amount
033521 SDT	4300-MAF0	Minerals Annual Fees M1985-210	\$791.00
Receipt Total:			\$791.00