

**Environment and Social Responsibility** 

Newmont Mining Corporation Gripple Creek & Victor Gold Mining Co P.O. Box 191 Victor. CO 80860 T 719-689-2977 F 719-689-3254 www.newmont.com

## SENT CERTIFIED, RETURN RECEIPT REQUESTED 7015-1660-0000-0779-6856

9 May 2016

MAY 1 1 2016

Mr. Timothy Cazier, P.E. Environmental Protection Specialist Colorado Department of Natural Resources Division of Reclamation, Mining and Safety Office of Mined Land Reclamation 1313 Sherman Street, Room 215 Denver, Colorado 80203

DIVISION OF RECLAMATION MINING AND SAFETY

Dear Mr. Cazier:

Below are the CC&V responses to the items referenced above.

Problem 1: Fish and Wildlife

Please see the attached photo that shows there is no longer any area in the HGM Infiltration Trench that is not covered by bird balls.

**Problem 2: Processing Facilities** 

CCV stopped placing fluids in the HGM Infiltration Trench on Friday May 6, 2016.

Please contact me with any additional questions at (719) 689- 4055 or Meg.Burt@Newmont.com.

More Indgrit for meg Burt

Meg Burt Senior Environmental Manager

