



**COLORADO**

**Division of Reclamation,  
Mining and Safety**

Department of Natural Resources

1313 Sherman Street, Room 215  
Denver, CO 80203

June 2, 2016

Mr. Jack Miller  
Superior Oilfield Services Co., LTD  
1011 11<sup>th</sup> Ave  
Greeley, CO 80631

**Re: Superior Oilfield Services Co., LTD, E 8<sup>th</sup> Street Operation, File No. M-2000-082,  
March 11, 2016 Inspection Report, Unresolved Problems**

Mr. Miller,

The E 8<sup>th</sup> Street Operation has problems noted that, according to Division of Reclamation, Mining and Safety (Division/DRMS) records have not yet been resolved. According to our records, the following problems were to be resolved on or before **April 15, 2016**. Listed below are the descriptions and corrective actions for the problems. **Please resolve the corrective actions and provide evidence of such resolution on or before July 2, 2016.**

Please note if the corrective actions are not properly addressed, and evidence provided to the Division by the date provided above, the listed problems could be escalated to the level of possible violations and would then be referred to the Mined Land Reclamation Board for further action.

**PROBLEM/POSSIBLE VIOLATION #1:** Problem: The Operator has not collected the required groundwater monitoring well data since 2013 in accordance with the approved monitoring and mitigation plan and one (1) monitoring well could not be located and one (1) monitoring well was damaged during the inspection.

**CORRECTIVE ACTION #1:** The Operator must reinitiate the approved groundwater monitoring plan, provide groundwater measurements for all current wells and install a replacement monitoring well for the damaged MW-1 well and repair MW-2 well by the corrective action date.

**PROBLEM/POSSIBLE VIOLATION #2:** Problem: The dewatering activity at the E 8th Street Operation has caused disturbances to the prevailing hydrologic balance and is affecting the groundwater well located at 417 East 8th Street, Greeley, CO 80631 owned by Mr. Tyrrell.

**CORRECTIVE ACTION #2:** The Operator must implement the approved groundwater mitigation plan for the site. The report must include the specific mitigation measures taken by the Operator to alleviate the effect of the dewatering at the E 8th Street Operation on the Tyrrell well.



If the problem has already been remedied, please provide evidence of completion. If you have any questions or concerns, please contact me at (303) 866-3567 Ext 8124.

Sincerely,

A handwritten signature in blue ink, appearing to read 'P. Hays', with a long horizontal flourish extending to the right.

Peter S. Hays  
Environmental Protection Specialist

Cc: Jack Tyrell, Land and Well Owner