

July 22, 2016

Peter Babin
Calx Minerals, LLC
5501 Lakeshore Drive
Littleton, CO 80123



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

1313 Sherman Street, Room 215
Denver, CO 80203

RE: Mid-Continent LST, Permit No. M-1982-121, Inspection Problem Abated

Dear Mr. Babin:

On April 12, 2016 the Division of Reclamation, Mining and Safety (Division) conducted an inspection of the above referenced site. Sediment control was cited as a problem in the inspection report for incomplete or improperly constructed BMP features. Corrective actions required that final construction photos of stormwater features constructed/maintained in the spring of 2016 be provided to the Division to ensure adequate completion of tasks by the corrective action date.

On June 19, 2016 the Division received photo documentation via email from Justin Olin. The pictures included a brief narrative of features that were reconstructed. This satisfies the corrective action and it is considered abated.

If you require additional information, or have questions or concerns, please feel free to contact me. Amy Yeldell, at the Division of Reclamation, Mining and Safety, 1313 Sherman St., Room 215, Denver, CO 80203. Direct contact can be made by phone at 970-254-8511 or via email at amy.yeldell@state.co.us

Sincerely,

Amy Yeldell

Environmental Protection Specialist
Department of Natural Resources
Division of Reclamation, Mining and Safety
Phone: (970) 254-8511
Fax: (970) 241-1516

Ec:

Russ Means, Senior EPS / Field Office Supervisor, Grand Junction DRMS
Jessica Lopez Pearce, Colorado River Valley Field Office BLM
Justin Olin, Calx Minerals, LLC

