

MINERALS PROGRAM INSPECTION REPORT PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME:		MINE/PROSPECTING ID#:	MINERAL:	COUNTY:
White River Pit		M-2008-070	Gravel	Rio Blanco
INSPECTION TYPE:		INSPECTOR(S):	INSP. DATE:	INSP. TIME:
Surety-Related Inspection		Travis H. Marshall	August 9, 2016	12:00
OPERATOR:		OPERATOR REPRESENTATIVE:	TYPE OF OPERATION:	
OWL SWD Operating, LLC		Seth Peters	112c - Construction Regular Operation	
REASON FOR INSPECTION:		BOND CALCULATION TYPE:	BOND AMOUNT:	
Surety Related		Complete Bond	\$106,548.00	
DATE OF COMPLAINT:		POST INSP. CONTACTS:	JOINT INSP. AGENCY:	
NA		None	None	
WEATHER:	INSPECTOR'S SIGNATURE:		SIGNATURE DATE:	
Clear	2. Quel		August 25, 2016	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS <u>Y</u>	(FN) FINANCIAL WARRANTY <u>Y</u>	(RD) ROADS <u>Y</u>
(HB) HYDROLOGIC BALANCE <u>Y</u>	(BG) BACKFILL & GRADING <u>Y</u>	(EX) EXPLOSIVES <u>NA</u>
(PW) PROCESSING WASTE/TAILING NA	(SF) PROCESSING FACILITIES \underline{Y}	(TS) TOPSOIL \underline{Y}
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE \underline{Y}	(RV) REVEGETATION <u>Y</u>
(SM) SIGNS AND MARKERS <u>Y</u>	(SP) STORM WATER MGT PLAN NA	(CI) COMPLETE INSP <u>Y</u>
(ES) OVERBURDEN/DEV. WASTE NA	(SC) EROSION/SEDIMENTATION <u>Y</u>	(RS) RECL PLAN/COMP <u>Y</u>
(AT) ACID OR TOXIC MATERIALS <u>Y</u>	(OD) OFF-SITE DAMAGE <u>Y</u>	(ST) STIPULATIONS <u>NA</u>

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

PERMIT #: M-2008-070 INSPECTOR'S INITIALS: THM INSPECTION DATE: August 9, 2016

OBSERVATIONS

This inspection was conducted as part of the normal monitoring program established by the Colorado Division of Reclamation, Mining and Safety. The WRC Gravel Pit is located approximately 13 miles west of Meeker, Colorado. The WRC Gravel Pit is a 191.83 acre 112c construction materials mining operation. Seth Peters of OWL SWD Operating, LLC accompanied the inspector during the inspection.

The mine identification sign and the affected area boundary markers were present and in compliance with Rule 3.1.12.

The site was inactive during the inspection. Various stockpiles of construction material were observed.

The operator submitted an acreage reduction request (AR-02) to remove all of Phase 2, the access road to Phase 2, a portion of the office and scale area and the future bridge and access area. The remaining proposed permit area is 20.77 acres. The breakdown of the proposed permit area is as follows: Phase 1 (13.67 acres); Office, scales and Parking (1.43 acres); access road (5.67 acres).

The purpose of the inspection was to observe Phase 2 and verify that no disturbance has taken place. Upon inspection of Phase 2 it was evident that no mining related disturbance occurred. The access road to Phase 2 was improved by widening and reducing the grade, the reclamation plan states that the road will be left in the improved condition to allow for better access to the property for the landowner. The future bridge area was not disturbed.

Based on the conditions observed during the inspection the requested acreage reduction will be approved. The approval letter will be sent under separate cover.

The currently held reclamation bond in the amount of \$106,547.59 is considered to be adequate to complete the required reclamation.

No off-site damage was observed during the inspection.

Photos that show the conditions observed during the inspection are included at the end of this report.

Responses to this inspection report should be directed to Travis Marshall at the Division of Reclamation, Mining and Safety, Grand Junction Field Office, 101 South 3rd Street, Room 301, Grand Junction, Colorado 81501, phone no. 970-241-2042.

PHOTOGRAPHS




Sign located at main entrance.



Active mining area in Phase 1.





Fuel tank stored in secondary containment Phase 1.








Unmined Phase 2 to be released.







Unmined Phase 2 to be released.

PERMIT #: M-2008-070 INSPECTOR'S INITIALS: THM INSPECTION DATE: August 9, 2016

Inspection Contact Address

Seth Peters OWL SWD Operating, LLC 4775 Larimer Pkwy, Suite 200 Johnstown, CO 80534